# User's Manual



vigilantplant<sup>®</sup>



Thank you for purchasing the YOKOGAWA µR10000 Recorder.

This manual describes the functions (excluding the communication functions), installation and wiring procedures, operating procedures, and lists the handling precautions of the  $\mu$ R10000 Recorder. To ensure correct use, please read this manual thoroughly before beginning operation.

The following three manuals including this manual are available for the  $\mu R10000$  Recorder.

#### Electronic Manuals Provided on the Accompanying CD-ROM

Manual Title	Manual No.	Description
µR10000 Recorder	IM 04P01B01-01E	This manual.
User's Manual		
µR10000/µR20000	IM 04P01B01-17E	Explains the communication functions of the
Communication Interface		µR10000 Recorder using Ethernet interface
User's Manual		and the RS-422A/485 communication interface.

# Paper Manual

Manual Title	Manual No.	Description
µR10000 Recorder	IM 04P01B01-02E	Explains concisely the operations of the
Operation Guide		µR10000 Recorder.

# Notes

- The contents of this manual are subject to change without prior notice as a result of continuing improvements to the instrument's performance and functions.
- Every effort has been made in the preparation of this manual to ensure the accuracy of its contents. However, should you have any questions or find any errors, please contact your nearest YOKOGAWA dealer as listed on the back cover of this manual.
- Copying or reproducing all or any part of the contents of this manual without the permission of Yokogawa Electric Corporation is strictly prohibited.
- The TCP/IP software of this product and the document concerning the TCP/IP software have been developed/created by YOKOGAWA based on the BSD Networking Software, Release 1 that has been licensed from the University of California.

# Trademarks

- All the brands or names of Yokogawa Electric's products used in this manual are either trademarks or registered trademarks of Yokogawa Electric Corporation.
- Microsoft, MS-DOS, Windows, Windows NT, and Windows XP are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.
- Adobe, Acrobat, and PostScript are trademarks of Adobe Systems incorporated.
- For purposes of this manual, the TM and <sup>®</sup> symbols do not accompany their respective trademark names or registered trademark names.
- Company and product names that appear in this manual are trademarks or registered trademarks of their respective holders.

# Revisions

1st Edition	December 2004
2nd Edition	March 2005
3rd Edition	August 2005
4th Edition	September 2006
5th Edition	April 2011

5th Edition: April 2011 (YK) All Rights Reserved, Copyright @ 2004 Yokogawa Electric Corporation

# Recorder's Version and Functions Described in This Manual

The contents of this manual corresponds to the recorder with version 1.31.

Version Suffix Code 1.02 or earlier –		Added or M	Iodified Functions	Reference	
		-		-	
1.11	-	(Added)	The printout/display format of the date can be changed.	Section 7.19	
-		(Added)	Key operation to move the printer carriage near the center position so that the ribbon cassette can be replaced with the recorder turned ON (dot model)	Section 3.4	
		(Changed)	Selectable range of alarm values during linear scaling (including 1-5V and SQRT) to $-5\%$ to 105% of the scale span.	Section 5.2	
		(Changed)	The procedure to set the start/end date and time of Daylight Saving Time (DST) has been changed.	Section 6.16	
/C3 /C7	(Added)	Modbus/RTU slave protocol, two-wire system.	Communication manual		
	/C7	(Changed)	Users with the same user name cannot be registered.	Communication manual	
1.21	-2	(Added)	Language support (German and French).	Section 1.9	
	/CC1	(Added)	Calibration Correction.	Section 1.2	
	/H5x	(Added)	Portable type.	Sections 2.5 and 12.7	
	/P1	(Added)	24 VDC/AC power supply operation.	Section 2.5	
1.31	-	(Added)	Customized menu.	Section 1.9	
	_	(Added)	Modbus register (40301 to 40348).	Communication manual	
	/BT1	(Added)	Header printout.	Section 1.4	

# µR10000 Versions and Functions

Checking the Version Number

You can check the version number on the System display.

The System display cannot be shown at the factory default condition.

First, register the System display to the display screen.

- Procedure of registering the System display to the display screen: See section 8.2.
- Procedure of displaying the System display: The screen switches each time the DISP key is pressed. Press the DISP key repeatedly until System display is shown. The displayed contents on the System display switches every 3 seconds. Check the number shown by the "Version:" item.

# Software (Sold Separately)

The table below shows the relationship between the RXA10 Configuration Software revisions and the  $\mu$ R10000 recorder versions.

		Recorder version					
		1.02 or earlier	1.11	1.21	1.31		
RXA10 Configuration Software revision	R1.01	Yes	Limited				
	R2.01	Yes	Yes	Yes	Limited		
	R3.01	Yes	Yes	Yes	Yes		

Yes: Compatible

Limited: The new functions of the recorder cannot be configured from the RXA10.

Note -

Set the recorder version in the RXA10 Configuration Software to display the setup items that match the recorder's functions.

# **Safety Precautions**

The general safety precautions described here must be observed during all phases of operation.

# Safety Standards and EMC Standards

This recorder conforms to IEC safety class I (provided with terminal for protective grounding), Installation Category II, Measurement Category II (CAT II), and EN61326-1 (EMC standard), class A (use in a commercial, industrial, or business environment). This recorder is designed for indoor use.

# **About This Manual**

- This manual should be read by the end user.
- Read this manual thoroughly and have a clear understanding of the product before operation.
- This manual explains the functions of the product. YOKOGAWA does not guarantee that the product will suit a particular purpose of the user.
- Under absolutely no circumstances may the contents of this manual be transcribed or copied, in part or in whole, without permission.
- The contents of this manual are subject to change without prior notice.
- Every effort has been made in the preparation of this manual to ensure the accuracy of its contents. However, should you have any questions or find any errors or omissions, please contact your nearest YOKOGAWA dealer.

# Precautions Related to the Protection, Safety, and Alteration of the Product

• The following safety symbols are used on the product and in this manual.



"Handle with care." To avoid injury and damage to the instrument, the operator must refer to the explanation in the manual.



Protective ground terminal



DC



"High temperature." To avoid injury caused by hot surface, do not touch locations where this symbol appears.

- For the protection and safe use of the product and the system controlled by it, be sure to follow the instructions and precautions on safety that are stated in this manual whenever you handle the product. Take special note that if you handle the product in a manner that violate these instructions, the protection functionality of the product may be damaged or impaired. In such cases, YOKOGAWA does not guarantee the quality, performance, function, and safety of the product.
- When installing protection and/or safety circuits such as lightning protection devices and equipment for the
  product and control system or designing or installing separate protection and/or safety circuits for fool-proof
  design and fail-safe design of the processes and lines that use the product and the control system, the user
  should implement these using additional devices and equipment.
- · If you are replacing parts or consumable items of the product, make sure to use parts specified by YOKOGAWA.
- This product is not designed or manufactured to be used in critical applications that directly affect or threaten human lives. Such applications include nuclear power equipment, devices using radioactivity, railway facilities, aviation equipment, air navigation facilities, aviation facilities, and medical equipment. If so used, it is the user's responsibility to include in the system additional equipment and devices that ensure personnel safety.
- Do not modify this product.

# WARNING

# Use the Correct Power Supply

Ensure that the source voltage matches the voltage of the power supply before turning ON the power. • Connect the Protective Grounding Terminal

Make sure to connect the protective grounding to prevent electric shock before turning ON the power.

# Necessity of Protective Grounding

Never cut off the internal or external protective earth wire or disconnect the wiring of the protective earth terminal. Doing so invalidates the protective functions of the instrument and poses a potential shock hazard.

# • Defect of Protective Grounding

Do not operate the instrument if the protective earth or fuse might be defective. Make sure to check them before operation.

• Do Not Operate in an Explosive Atmosphere Do not operate the instrument in the presence of flammable liquids or vapors. Operation in such environments constitutes a safety hazard.

Do Not Remove Covers

The cover should be removed by YOKOGAWA's qualified personnel only. Opening the cover is dangerous, because some areas inside the instrument have high voltages.

- External Connection
   Connect the protective grounding before connecting to the item under measurement or to an external control unit.
- Damage to the Protective Structure

Operating the recorder in a manner not described in this manual may damage its protective structure.

# Portable Type (/H5x Option)

# Use the Correct Power Supply Ensure that the power supply is within the maximum rated voltage range of the provided power cord before connecting the power cord.

# • Use the Correct Power Cord and Plug

To prevent electric shock or fire, be sure to use the power cord supplied by YOKOGAWA. The main power plug must be plugged into an outlet with a protective earth terminal. Do not disable this protection by using an extension cord without protective earth grounding. The power cord is designed for use with this instrument. Do not use the power cord with other instruments.

# Connect the Protective Grounding Terminal

The power cord for the  $\mu$ R10000 is a three-prong type power cord. Connect the power cord to a properly grounded three-prong outlet.

# CAUTION

This instrument is a Class A product. Operation of this instrument in a residential area may cause radio interference, in which case the user is required to take appropriate measures to correct the interference.

# **Exemption from Responsibility**

- YOKOGAWA makes no warranties regarding the product except those stated in the WARRANTY that is provided separately.
- YOKOGAWA assumes no liability to any party for any loss or damage, direct or indirect, caused by the user or any unpredictable defect of the product.

# Handling Precautions of the Software


- YOKOGAWA makes no warranties regarding the software accompanying this product except those stated in the WARRANTY that is provided separately.
- Use the software on a single PC.
- You must purchase another copy of the software, if you are to use the software on another PC.
- Copying the software for any purposes other than backup is strictly prohibited.
- Please store the original media containing the software in a safe place.
- Reverse engineering, such as decompiling of the software, is strictly prohibited.
- No portion of the software supplied by YOKOGAWA may be transferred, exchanged, sublet, or leased for use by any third party without prior permission by YOKOGAWA.

# Checking the Contents of the Package

Unpack the box and check the contents before operating the recorder. If some of the contents are not correct or missing or if there is physical damage, contact the dealer from which you purchased them.

# **Checking the Model**

A name plate is affixed to the recorder. Check that the model name and suffix code given on the name plate on the rear panel match those on your order.



# **MODEL and SUFFIX Code**

Model	Suffix Code	Optional Code	Description	
436101			µR10000 1 pen recorder	
436102			µR10000 2 pen recorder	
436103			µR10000 3 pen recorder	
436104			µR10000 4 pen recorder	
436106			µR10000 6 dot recorder	
	-2		English/German/French & deg F/DST	
		/A1	Alarm output relay 2 points <sup>1</sup>	
		/A2	Alarm output relay 4 points <sup>1</sup>	
		/A3	Alarm output relay 6 points <sup>1, 2</sup>	
		/C3	RS-422A/485 interface <sup>3</sup>	
		/C7	Ethernet (10BASE-T) interface <sup>3</sup>	
		/F1	Fail/Chart end detection and output <sup>2</sup>	
		/H2	Clamped input terminal <sup>4</sup>	
		/H3	Non-glare door glass	
		/H5D	Portable type Power cord UL, CSA st'd <sup>7</sup>	
		/H5F	Portable type Power cord VDE st'd <sup>7</sup>	
		/H5R	Portable type Power cord AS st'd <sup>7</sup>	
		/H5J	Portable type Power cord BS st'd <sup>7</sup>	
		/H5H	Portable type Power cord GB st'd <sup>7</sup>	
		/M1	Mathematical function	
		/N1	Cu10, Cu25 RTD input	
		/N2	3 legs isolated RTD 4, 5	
		/N3	Expansion inputs <sup>6</sup>	
		/P1	24 VDC/AC power supply <sup>7</sup>	
		/R1	Remote control 5 points	
		/CC1	Calibration Correction	
		/BT1	Header printout	

1 /A1, /A2, and /A3 cannot be specified simultaneously.

2 /A3 and /F1 cannot be specified simultaneously.

3 /C3 and /C7 cannot be specified simultaneously.

4 /H2 and /N2 cannot be specified simultaneously.


5 Valid only on the model 436106.

6 14 types of input including Pt50 RTD, PR40-20, and Platinel TC.

7 /H5x and /P1 cannot be specified simultaneously.

# **Standard Accessories**

The standard accessories below are supplied with the recorder. Check that all contents are present and undamaged.



# One of these power cord types is supplied according to the instrument's suffix code

Part Number	Note
A1006WD	Provided when optional code /H5D is specified.
ATOUOVID	Maximum rated power voltage: 125 V
A1009WD	Provided when optional code /H5F is specified.
ATOUSVUD	Maximum rated power voltage: 250 V
A1024WD	Provided when optional code /H5R is specified.
A1024VVD	Maximum rated power voltage: 250 V
A1023WD	Provided when optional code /H5J is specified.
A1023VVD	Maximum rated power voltage: 250 V
A1064WD	Provided when optional code /H5H is specified.
A1004VD	Maximum rated power voltage: 250 V

Item			2-Pen	3-Pen	4-Pen	Dot Printing
Z-fold chart paper		1	1	1	1	1
Ribbon cassette		-	-	-	-	1
	Red	1	1	1	1	-
Dianaaahla falt nan	Green	-	1	1	1	-
Disposable felt pen	Blue	-	-	1	1	-
	Violet	-	-	-	1	-
Plotter pen Purple		1	1	1	1	-
Mounting bracket		2	2	2	2	2
(included with models without /H5x)		2	2	2	2	2
Power cord (included with /H5x)		1	1	1	1	1
Manuals for the µR10000/µR20000 (CD-ROM)		1	1	1	1	1
µR10000 Recorder Operation Guide		1	1	1	1	1
IM 04P01B01-02E						I

# **Optional Accessories (Sold Separately)**

The optional accessories below are available for purchase separately. If you make an order, make sure that all contents are present and undamaged.

For information about ordering accessories, contact the dealer from which you purchased the recorder.

Item		Model (Part Number)	Quantity	Note
Z-fold chart paper		B9565AW	1	10 pcs.
Ribbon cassette		B9901AX	1	
	Red	B9902AM	1	3 pcs.
Dianaachla falt nan	Green	B9902AN	1	3 pcs.
Disposable felt pen	Blue	B9902AP	1	3 pcs.
	Violet	B9902AQ	1	3 pcs.
Plotter pen Purple		B9902AR	1	3 pcs.
Mounting bracket		B9900BX	2	
Chunt register for the		415920	1	250 Ω ±0.1%
Shunt resistor for the		415921	1	100 Ω ±0.1%
screw terminal (standard)		415922	1	10 Ω ±0.1%
Churt register for the		438920	1	250 Ω ±0.1%
Shunt resistor for the		438921	1	100 Ω ±0.1%
clamped input terminal (/H2)		438922	1	10 Ω ±0.1%


# Software (Sold Separately)

Item	Model	Note
uB10000 Configuration coffware	RXA10-01	
µR10000 Configuration software	RXA10-02	With interface unit*

\* You can use the Configuration Software if you install the interface unit to a recorder does not include the communication function.

# **Removing the Packing Materials**

Open the door, put your finger on the tab at the lower left of the display, and open the display.



# How to Use This Manual

This user's manual consists of the following sections.

For details on communication functions, see the  $\mu R10000/\mu R20000$  Communication Interface User's Manual (IM 04P01B01-17E) on the CD-ROM.

Chapter	Title and Description
1	Functional Explanation and Setup Guide
	Describes the functions of the $\mu$ R10000 Recorder and provides a function setup guide
	Refer to this chapter when you are unsure of the details of the function that you are
	operating.
2	Before Using the Recorder
	Describes the installation and wiring procedures.
3	Names of Parts and Run Operations
	Describes the names of each part of the recorder and the daily operations.
4	Common Operations for Setting Functions and Setup Menu
	Explains the recorder operation modes and the basic setup operations using keys. It
	also provides menu configuration diagrams and lists of setup items.
5	Frequently Used Setup Operations (Setting Mode)
	Describes how to change the input range, alarms, chart speed, etc.
6	Setup Operations for Convenient Functions (Setting Mode)
	Describes the setup operations for convenient functions such as how to assign tags to
	channels and how to set message strings that are to be printed.
7	Setup Operations for Changing/Adding Functions (Basic Setting Mode)
	Describes the setup operations for changing or adding functions such as setting the
	recorder to detect sensor burnouts and changing the contents that are printed on the
	chart paper.
8	Setup Operations for Changing the Displayed Contents
	Describes how to select the display type suitable for the application.
9	Operations Related to the Computation Function (/M1 Option)
	Describes all operations related to the computation function.
10	Troubleshooting
	Describes error message and troubleshooting measures of the µR10000 Recorder.
11	Maintenance
	Describes periodic inspection, calibration, pen adjustment/printer carriage adjustment,
	and recommended replacement period for worn parts.
12	Specifications
	Gives the specifications of the µR10000 Recorder.
Appendix	Describes the printout contents.
Index	

# Note \_

• This user's manual covers information regarding the recorders with English as the display/ printout language (suffix code "2").

• For the procedure of setting the display/printout language, see section 7.14, "Changing the Display/Printout Language."

# **Conventions Used in This Manual**

#### Unit

K ...... Denotes 1024. Example: 768 KB (file size)

k ..... Denotes 1000.

### **Safety Markings**

The following markings are used in this manual.



Improper handling or use can lead to injury to the user or damage to the instrument. This symbol appears on the instrument to indicate that the user must refer to the user's manual for special instructions. The same symbol appears in the corresponding place in the user's manual to identify those instructions. In the manual, the symbol is used in conjunction with the word "WARNING" or "CAUTION."

# WARNING

Calls attention to actions or conditions that could cause serious or fatal injury to the user, and precautions that can be taken to prevent such occurrences.



Calls attentions to actions or conditions that could cause light injury to the user or damage to the instrument or user's data, and precautions that can be taken to prevent such occurrences.

Calls attention to information that is important for proper operation of the instrument.

#### Subheadings

Note

On pages that describe the operating procedures in Chapter 3 through 9, the following symbols are used to distinguish the procedures from their explanations. Bold characters denote keys or character strings that are displayed on the screen.

Example: Range, Unit



Follow the numbered steps. All procedures are written with inexperienced users in mind; depending on the operation, not all steps need to be taken.

**Explanation** This subsection describes the setting parameters and the limitations on the procedures. It does not give a detailed explanation of the function. For details on the function, see chapter 1.

# Contents

Recorder's Version and Functions Described in This Manual	ii
Safety Precautions	. iii
Checking the Contents of the Package	. vi
How to Use This Manual	х

# Chapter 1 Functional Explanation and Setup Guide

1.1	Overview of the Recorder	1-1
1.2	Measuring Input Section	1-2
1.3	Alarms	1-7
1.4	Recording	1-13
1.5	Display	1-24
1.6	Computation Function (/M1 Option)	1-26
1.7	FAIL/Chart End Detection and Output Function (/F1 Option)	1-29
1.8	Remote Control Function (/R1 Option)	1-30
1.9	Other Functions	1-32
1.10	Function Setup Guide	

# Chapter 2 Before Using the Recorder

	2.1	Handling Precautions	2-1
	2.2	Installation	2-2
⚠	2.3	Input Signal Wiring	2-4
⚠	2.4	Optional Terminal Wiring	2-8
⚠	2.5	Power Supply Wiring	2-11
	2.6	Turning ON/OFF the Power Switch	2-13

# Chapter 3 Names of Parts and Run Operations

3.1	Names of Parts	3-1
3.2	Installing or Replacing the Chart Paper	3-4
3.3	Installing/Replacing Felt Pens or Plotter Pen (Pen Model)	3-7
3.4	Installing/Replacing the Ribbon Cassette (Dot Model)	3-9
3.5	Starting/Stopping the Recording	.3-11
3.6	Switching the Display Screen	3-12
3.7	Printing Measured Values (Manual Printout)	3-13
3.8	Printing the Recorder Settings	3-14
3.9	Clearing the Alarm Printout Buffer	3-15
3.10	Printing Messages	3-16
3.11	Resetting the Report Data of the Periodic Printout	3-17
3.12	Releasing the Alarm Output (Alarm ACK Operation)	3-18
3.13	Activating/Releasing the Key Lock	3-19

# Chapter 4 Common Operations for Setting Functions and Setup Menu

4.1	Run Modes	4-	1
4.2	Key Operations	4-2	2
4.3	Menu Structure, Settings, and List of Default Values	4-	5

Chapter 5	Free	quently Used Setup Operations (Setting Mode)		1
	5.1	Setting the Input Range	5-1	
	5.2	Setting the Alarm	5-9	
	5.3	Setting the Unit on Scaled Channels	5-12	2
	5.4	Changing the Chart Speed	5-13	~
	5.5	Setting the Date/Time	5-14	
Chapter 6	Setu	up Operations for Convenient Functions (Setting Mode)		3
-	6.1	Setting the Trend Recording Interval (Dot Model)	6-1	
	6.2	Setting the Filter (Pen Model)	6-2	
	6.3	Setting the Moving Average (Dot Model)	6-3	
	6.4	Setting Recording Zones for Each Channel (Zone Recording)	6-4	4
	6.5	Setting the Partial Expanded Recording	6-5	
	6.6	Turning Trend Recording (Dot Model) and Periodic Printout ON/OFF for Each Chann	iel 6-6	
	6.7	Setting Tags on Channels	6-7	5
	6.8	Setting the Message String	6-8	Ð
	6.9	Setting the Secondary Chart Speed (Remote Control Function, /R1)	6-9	
	6.10	Setting the Alarm Delay Duration	6-10	
	6.11	Setting the Brightness of the Display and Internal Light	6-11	6
	6.12	Applying a Bias on the Measuring Input Signal	6-12	Ŭ
	6.13	Performing Calibration Correction (/CC1 Option)	6-13	
	6.14	Setting Up Start Printout and End printout (/BT1 Option)	6-15	
		Setting the Message Format (/BT1 Option)		7
	6.16	Setting the Date/Time When Switching between Standard Time and DST	6-21	
Chapter 7	Setu	up Operations for Changing/Adding Functions (Basic Settin	Ig	0
	Мос	e)		8
		Changing the Auxiliary Alarm Function		
		Changing the Integration Time of the A/D Converter		
		Setting the Burnout Detection Function of Thermocouples		9
		Setting the RJC Function on Channels Set to TC Input		
		Changing the Channel Recording Color (Dot Model)		
		Recording by Compensating for the Pen Offset along the Time Axis (Pen Model)		
		Turning Printouts ON/OFF		10
		(Selecting the Channel/Tag Printout and Turning ON/OFF the Channel No., Alarm, Re	ecordina	
		Start, New Chart Speed, Scale, and Pen Color Printouts)	-	
	7.8	Setting the Periodic Printout Interval and the Type of Data to Be Printed		44
		Setting the Bar Graph Display Mode		11
		Setting the Key Lock Function		
		Enabling the Moving Average Function (Dot Model)		
		Enabling the Filter Function (Pen Model)		12
		Enabling the Partial Expanded Recording Function		
		Changing the Display/Printout Language		
		Enabling the Bias, Low-Cut, Alarm Delay, Calibration Correction (/CC1 Option)		
		Functions	7-23	Арр
	7,16	Changing the Time Printout Format		
		Initializing the Settings		
		Assigning Functions to the Remote Control Input Terminals (/R1 Option)		
		Changing the Printout/Display Format of the Date		Index
		Selecting to Show/Hide the FUNC Key Menus		
		Selecting to Show/Hide Setting Mode Menus		
		Enabling/Disabling the Customized Menu		

xiii

	7 23	Setting the Calibration Correction Function (/CC1 Option)	7-38
		Enabling Start Printout, End printout, and Message Format (/BT1 Option)	
		Changing the Temperature Unit	
Chapter 8	Set	up Operations for Changing the Displayed Contents	
	8.1	Key Operations for Changing the Displayed Information	8-1
	8.2	Changing the Displayed Information	8-3
Chapter 0	0	arctions Balated to the Computation Function (/M4 Ontion)	
Chapter 9	9.1	erations Related to the Computation Function (/M1 Option) Starting/Stopping/Resetting the Computation	0.1
	9.1 9.2	Starting/Stopping/Resetting the Computation	
	9.2 9.3	Setting the Unit	
	9.3 9.4	Setting the Constants Used in Equations	
	9. <del>4</del>	Setting the Alarm	
	9.6	Specifying the Timer Used in Statistical Calculations (TLOG)	
	9.0 9.7	Setting Recording Zones for Each Channel (Zone Recording)	
	9.8	Setting the Partial Expanded Recording	
	9.9	Turning Trend Recording (Dot Model) and Periodic Printout (Including the Printout U	
	9.9	TLOG Timer) ON/OFF for Each Channel	•
	Q 10	Setting Tags on Channels	
		Setting the Alarm Delay Duration	
		Setting the Timer Used in TLOG Computation and Periodic Printout	
		Changing the Channel Recording Color (Dot Model)	
		Changing the Channel Assignments of Recording Pens (Pen Model)	
		Changing the Type of Report Data Printed in Periodic Printout	
		Setting the Bar Graph Display Mode	
		Setting the Procedure Taken When the Computed Result Is in Error	
	_		
Chapter 10		ubleshooting	
		A List of Error Messages	
	10.2	Troubleshooting Flow Charts	10-4
Chapter 11	Mai	intenance	
		Periodic Inspection	11-1
		Cleaning the Recorder	
		Replacing the Internal Light LED	
		Calibrating the Recorder	
		Adjusting the Pen Position (Pen Model)	
		Adjusting the Dot Printing Position (Dot Model)	
		Recommended Replacement Periods for Worn Parts	
Chapter 12	Sne	acifications	
Shapter 12	-	Input Specifications	10 1
		Alarm Function Specifications	
		Recording Function Specifications	
	12.0		······ 12- <del>1</del>

12.4 Display Function Specifications12-712.5 Specifications of Optional Functions12-1312.6 General Specifications12-1812.7 Dimensional Drawings12-23


# Contents

Appendix		
	Appendix 1	Periodic Printout and Printout Using the TLOG Timer (/M1 Option) App-1
	Appendix 2	Periodic Printout Interval App-6

# Index

# 1.1 Overview of the Recorder

The  $\mu$ R10000 Recorder (hereafter referred to as the recorder) can be used to assign DC voltage, 1-5V, thermocouple, RTD, and contact or voltage ON/OFF signal to channels for measurement. The measured results are recorded with pens or dots on a chart paper that is fed at a constant speed. The pen model can record up to 4 channels; the dot model can record up to 6 channels.



#### Alarms

For each channel, various alarms such as high limit alarm and low limit alarm can be assigned to monitor the measured values. Alarm output relays can be used to output contact signals when alarms occur (/A1, /A2, and /A3 options).

#### Recording

The measured results are recorded with pens or dots on a chart paper (trend recording). The chart speed can be selected from 5 to 12000 mm/h on the pen model and 1 to 1500 mm/h on the dot model.

In addition to trend recording, various types of information can be printed or recorded on the chart paper such as numeric measured values, alarm occurrence/release, and predefined messages. Also, the recorder settings can be printed.

#### Internal Light

A light is provided for easier viewing of the recording area of the chart paper.

#### Display

Measured values can be displayed numerically or using bar graphs on the large display. Also, alarm status and chart speed can be displayed.

#### **Communication Function**

Using the Ethernet communication interface (/C7 option) or the RS-422A/485 communication interface (/C3 option), the measured values on the recorder can be output to a PC or a PC can be used to control the recorder.

This manual does not cover the communication functions. For details on communication functions, see the  $\mu R10000/\mu R20000$  Communication Interface User's Manual (IM 04P01B01-17E) on the CD-ROM.

# Other Main Functions

The computation function (/M1 option) can be used to perform various computations from four arithmetic operations to statistical calculations on 8 and 12 computation channels on the pen model and dot model, respectively. The computed results can be recorded. The remote control function (/R1 option) can be used to control the start/stop and other operations of the recorder by applying contact signals to the dedicated terminals. The FAIL/chart end detection and output function (/F1 option) can be used to output contact signals when errors are detected on the recorder or when the chart paper runs out.

# 1.2 Measuring Input Section

# Input Section

# Number of Measurement Channels and Scan Interval

The recorder samples the input signals on the measurement channels at the scan interval to obtain the measured values.

Model	Number of Channels	Scan Interval
1-pen model	1	125 ms
2-pen model	2	125 ms
3-pen model	3	125 ms
4-pen model	4	125 ms
Dot model	6	1 s (However, the scan interval is $2.5$ s when the integration time of the A/D converter is 100 ms.)

# Input Type, Measurable Range, and Computation

The recorder can measure the following types of inputs.

Input Type	Measurable Range
DC voltage	DC voltage in the range of ±20 mV to ±50 V
1-5V	See "1-5V" below.
Thermocouple	Temperature range corresponding to each type: R, S, B, K, E, J, T, N, W, L, U, and WRe
RTD	Temperature range corresponding to each type: Pt100 $\Omega$ and JPt100 $\Omega$
ON/OFF input	Contact input: Open contact is OFF (0). Closed contact is ON (1).
	Voltage input: Less than 2.4 V is OFF (0). Greater than or equal to 2.4 V is ON (1).
	Within ±6 V.

#### • 1-5V

1-5V is scaled to values in the appropriate unit to be used as measured values. Also, the low-cut function (input less than 0% is fixed to 0% (scale left value)) can be used.

#### Current Input

A shunt resistor is attached to the input terminal. The current signal is converted to a voltage signal and measured. The measurable range is the range equivalent to the "DC voltage" range indicated above after converting the current to the voltage signal.


#### Note

Three types of shunt resistors (250  $\Omega$ , 100  $\Omega$ , and 10  $\Omega$ ) are available for current input (see "Optional Accessories (Sold Separately)" on page vii). For example, a 250- $\Omega$  shunt resistor is used to convert the signal to the range of 1 to 5 V for 4 to 20 mA input.

#### Range Type, Measurable Range, and Recording Span

Various "range type" are available for the different types of inputs (for example thermocouple type R). Each range type has a preset measurable range (0.0 to 1760.0°C for thermocouple type R). Measurement can be made by specifying an arbitrary range within the measurable range as the *input range*. The measured values in the input range are recorded on the chart paper. The range of measured values that are recorded is called the *recording span*.

# Measurable range (Thermocouple type R example)



<Related Topics> Setting the input range: Section 5.1

# Delta Computation

The value obtained by subtracting the measured value of another channel (called the *reference channel*) from the input value of the channel set to delta computation is used as the measured value of that channel. The reference channel must be assigned to a channel whose channel number is less than that of the channel on which delta computation is specified. The channel on which delta computation is specified is automatically set to the same range type as the reference channel.






Measured value on the reference channel



A channel whose input type is set to DC voltage, TC, or RTD can be designated as a reference channel. However, channels set to scaling or square root computation cannot be designated.


### Scaling

The input values are scaled to values in the appropriate unit to be used as measured values.



# Square Root Computation

When the input type is DC voltage, the square root of the input value is calculated, the result is scaled to a value in the appropriate unit, and used as the measured value of the channel. Also, the low-cut function (input less than a given measured value is fixed to 0% (scale left value)) can be used.



# Note

The square root computation on the recorder uses the following formula.

$$F_{x} = (F_{max} - F_{min}) / \frac{V_{x} - V_{min}}{V_{max} - V_{min}} + F_{min}$$

where V*min* (leftmost value of span) < V*max* (rightmost value of span)


F*min* (leftmost value of scale after scaling) < F*max* (rightmost value of scale after scaling)

Vx is the input voltage and Fx is the scaled value

<Related Topics> Setting the input range: Section 5.1

Bias


A given value (bias value) is added to the input value and used as the measured value of that channel.



<Related Topics> Setting the bias: Sections 7.15 and 6.12

### Calibration Correction (/CC1 Option)

Corrects the measured value of each channel using segment linearizer approximation and makes the resultant value the measured value of the channel. You can set arbitrary correction values for 2 to 16 points of arbitrary measured values. Linear approximation is used between two segment points. Correction values can be assigned using revise values or absolute values.



<Related Topics> Setting the calibration correction function: Sections 7.15, 7.23, and 6.13

# **Burnout Detection of Thermocouples**

This function makes the recording go off the scale to the right or left when the thermocouple burns out while measuring temperature with a thermocouple. This function can also be used on 1-5V. The burnout detection function can be set for each channel. By default, this function is disabled.

Νυίε -	N	0	te	ò	_
--------	---	---	----	---	---

For 1-5V, a burnout occurs when the input value is less than or equal to 0.2 V.

<Related Topics> Setting the burnout detection function: Section 7.3

# **Reference Junction Compensation of Thermocouple Input**


When measuring the temperature using a thermocouple, the reference junction compensation on the recorder can be used. When using external reference junction compensation, you can set the reference voltage. The reference junction compensation can be set for each channel.

By default, the recorder is configured to use the internal reference junction compensation function.

### Note \_

When using external reference junction compensation, set an appropriate reference junction compensation voltage. For example, if the reference junction temperature of the external reference compensation is T<sub>0</sub> °C, set the reference compensation junction voltage to the thermoelectromotive force of the 0°C reference of T<sub>0</sub> °C.

Example when using external reference junction compensation



<Related Topics> Setting the reference junction compensation function: Section 7.4


# Noise Elimination from Input Signals

# Filter and Moving Average

This function used to suppress the effects of noise that is riding on the signal. The pen model and dot model are equipped with a filter function and a moving average function, respectively. The function can be set for each measurement channel. However, it does not operate on channels set to ON/OFF input.


• Filter (Pen Model)

The filter is a low-pass filter. The time constant can be set to  $2 ext{ s}$ ,  $5 ext{ s}$ , or  $10 ext{ s}$ . Filter result (output for a step input)



# Moving Average (Dot Model)

The average value of the m most recent values acquired at the scan interval is used as the measured value of the channel. The number of moving-averaged data points (m) can be set in the range 2 to 16. The figure below shows an example indicating the operation of the buffer for the moving average computation when the number of moving averaged data points is set to 5.



<Related Topics> Setting the filter: Sections 7.12 and 6.2 Setting the moving average: Sections 7.11 and 6.3

# Integration Time of the A/D Converter

The recorder uses an A/D converter to convert the sampled analog signal to a digital signal. By setting the integration time of the A/D converter to match the time period corresponding to one cycle of the power supply or an integer multiple of one cycle, the power supply frequency noise can be effectively suppressed.

The integration time of the A/D converter is selected according to the model from the table below.

Model Integration Time of the A/D Converter	
Pen model	Select 16.7 ms (60 Hz), 20 ms (50 Hz), or Auto
Dot model	Select 16.7 ms (60 Hz), 20 ms (50 Hz), 100 ms or Auto

- If Auto is selected, the recorder detects the power supply frequency and automatically selects 16.7 ms or 20 ms.
- If Auto is specified when using the 24-VDC power supply on a recorder with the 24-VDC/AC power supply (/P1 option), the integration time is fixed to 20 ms (50 Hz).
- Because 100 ms is an integer multiple of 16.7 ms and 20 ms, this setting can be used to suppress the power frequency noise for either frequency, 50 Hz or 60 Hz.
- The scan interval on the dot model is 1 s when the integration time is set to 16.7 ms or 20 ms and 2.5 s when the integration time is set to 100 ms.

<Related Topics> Setting the A/D integration time: Section 7.2

### Alarms 1.3

This function generates an alarm when the measured data meets a certain condition. The alarm occurrence/release can be recorded on the chart paper. The alarm status can be displayed on the screen. Also, alarm output relays can be used to output contact signals when alarms occur (/A1, /A2, and /A3 options).

# Alarm Types

# Number of Alarm Point Marks

Up to four alarms can be set for each channel. The 4 alarm settings are called Level 1, Level 2, Level 3, and Level 4. The numbers do not indicate a difference in importance.

# **Alarm Conditions**


The eight conditions below are available. The character inside the parentheses is the symbol used to denote each alarm on the recorder.

- High Limit Alarm (H)
  - An alarm occurs when the input value exceeds the alarm value.

### Low Limit Alarm (L)

An alarm occurs when the input value falls below the alarm value.

#### High limit alarm



### Difference High Limit Alarm (h)\*

An alarm occurs when the difference in the input values of two channels is greater than or equal to the specified value.

Difference Low Limit Alarm (I)\*

An alarm occurs when the difference in the input values of two channels is less than or equal to the specified value.

\* Can be specified on channels set to delta computation.

# • High Limit on Rate-of-Change Alarm (R)


The rate-of-change of the measured values is checked over a certain time (interval). An alarm occurs if the rate-of-change of the measured value in the rising direction is greater than or equal to the specified value.

Low Limit on Rate-of-Change Alarm (r)

The rate-of-change of the measured values is checked over a certain time (interval). An alarm occurs if the rate-of-change of the measured value in the falling direction is greater than or equal to the specified value.

High limit on rate-of-change alarm

Low limit on rate-of-change alarm




The alarm value of the rate-of-change alarm is set using an absolute value. The interval is derived using the following equation and set using the number of samples. Interval = the scan interval × the number of samples

#### • Delay High Limit Alarm (T)

An alarm occurs when the measured value remains above the alarm value for a specified time period (alarm delay period).

# Delay Low Limit Alarm (t) An alarm occurs when the measured value remains below the alarm value for a specified time period (alarm delay period).

#### Delay High Limit Alarm Example (T denotes the specified delay)



- Alarm does not occur at T1, because the time period is shorter than the specified alarm delay period (T).
- The measured value exceeds the alarm value at time X2, and the alarm occurs at time X3 at which the specified alarm delay period elapses (the time when the alarm occurs is the time at X3).
- The measured value falls below the alarm value at time X4, and the alarm is released.

#### Note.


- The alarm detection operation is reset when a power failure occurs. The operation restarts after the power recovers.
- If the alarm value is changed while a delay alarm is occurring, the alarm is released if the new alarm value does not meet the alarm condition.

#### Alarm Hysteresis

Hysteresis can be specified to the values for activating and releasing the alarm. The hysteresis applies only to high limit alarm (H) and low limit alarm (L). The hysteresis width can be set in the range of 0.0% (Off) to 1.0% of the recording span in 0.1 steps. The setting applies to all high limit alarms and low limit alarms. By default, the hysteresis width is set to 0.5%.

#### High limit alarm

Low limit alarm



<Related Topics> Setting alarms: Section 5.2

Setting the alarm delay function: Sections 7.15 and 6.10 Setting the alarm hysteresis: Section 7.1

# Alarm Indication


The alarm status can be displayed on the screen. For details on the display, see section 1.5.

### Non-Hold/Hold Operation of the Alarm Indication

The alarm indication can be set to operate in the following fashion when the alarm condition is no longer met.

- Clear the alarm indication (non-hold).
- Hold the alarm indication until the alarm ACK operation is executed (hold).

The default setting is non-hold.



<Related Topics> Setting the non-hold/hold operation of the alarm indicator: Section 7.1

# Alarm Recording

The alarm occurrence/release can be recorded on the chart paper. See section 1.4.

# Alarm Output Relay (/A1, /A2, and /A3 Options)


Contact signals can be generated from alarm output relays when alarms occur. The number of output relays is 2 (/A1), 4 (/A2), or 6 (/A3). The alarm output relays are denoted as 101 to 106 on the recorder.

The following functions can be assigned to the alarm output relay.

# **Diagnosis Output**

The diagnosis output can be assigned to alarm output relay I01.

The relay is activated when there is an error in the plotter operation on the pen model, when a burnout is detected, or when there is an error in the A/D converter. Output relay I01 is normally energized and de-energizes when an error is detected (de-energized operation and non-hold operation).



Note\_

If diagnosis output is enabled, I01 becomes a relay dedicated to diagnosis output.

For the procedure to set the functions, see section 1.10, "Function Setup Guide."

<Related Topics> Setting the diagnosis output: Section 7.1


1

#### **Reflash Alarm**

When multiple alarms are assigned to one alarm output relay, this function notifies the occurrence of subsequent alarms after the relay is activated by the first alarm. When subsequent alarms occur, the output relay is released temporarily (approximately 500 ms).

The reflash alarm function is set to three output relays (I01, I02, and I03 (I01 and I02 for the /A1 option)).

By default, the reflash alarm is disabled.




- If the reflash alarm is enabled, I01 to I03 are set to reflash alarm operation. In this case, I01 to I03 are set to OR operation and non-hold operation regardless of the settings specified in "AND/OR Operation of Alarm Output Relays" and "Non-Hold/Hold Operation of Alarm Output Relays" described below.
- If diagnosis output is enabled, I01 is set to diagnosis output.

<Related Topics> Setting the reflash alarm: Section 7.1

# AND/OR Operation of Alarm Output Relays

When multiple alarms are assigned to one alarm output relay, the condition for activating the alarm output relay can be selected from the following:

- AND: Activated when all assigned alarms are occurring simultaneously.
- OR: Activated when any of the specified alarms is occurring.



The alarm output relays assigned to AND operation are specified as follows: "I01 (first relay) to Ixx (where xx is the relay number)."

The default setting is "no AND relay."


#### Note \_\_\_

- If the reflash alarm is enabled, I01 to I03 are fixed to OR operation. Specifying AND produces no effect.
- If diagnosis output is enabled, I01 is set to diagnosis output. Specifying AND produces no effect.

<Related Topics> Setting the AND operation: Section 7.1

# Energized/De-energized Operation of Alarm Output Relays

You can select whether the alarm output relay is energized or de-energized when an alarm occurs. If de-energized is selected, the status of the alarm output relay when an alarm occurs is the same as the status that results when the recorder is turned OFF (including power failures). The setting applies to all alarm output relays. The default setting is energized.



If diagnosis output is enabled, I01 is fixed to de-energized operation.


**Related Topics>** Setting the energized/de-energized operation of alarm output relays: Section 7.1 1

# Non-Hold/Hold Operation of Alarm Output Relays

The alarm output relay can be set to operate in the following fashion when the alarm condition is no longer met.

- Turn off the relay output (non-hold).
- Hold the relay output until the alarm ACK operation is executed (hold).
- The setting applies to all alarm output relays.

The default setting is non-hold.



### Note\_

- If the reflash alarm is enabled, I01 to I03 are fixed to non-hold operation. Specifying Hold produces no effect.
- If diagnosis output is enabled, I01 is fixed to non-hold operation. Specifying Hold produces no effect.

<Related Topics> Setting the non-hold/hold operation of alarm output relays: Section 7.1

# **Alarm ACK Operation**

The alarm acknowledge (alarm ACK) operation releases all alarm indications and relay outputs (/A1, /A2, and /A3 options) that are activated when the alarm indication or alarm output relay is set to hold operation. This operation can be executed from the front panel key.

<Related Topics> Alarm ACK operation: Section 3.12


# 1.4 Recording

The recorder is capable of recording the measured values with pens or dots (trend recording) as well as various other types of information.



**Recording Example on the Pen Model** 





The recording examples may appear differently from the actual recording as a result of functional improvements made on the recorder after this manual was written.

<Related Topics> Starting/Stopping recording: Section 3.5

# Trend Recording

The measured values are printed within a width of 100 mm.

### **Recording Method (Pen Model)**

- The measured value is updated every scan interval and continuously recorded.
- The recording colors in order from channel 01 are red, green, blue, and violet.

#### **Recording Method (Dot Model)**

- The most recent measured value is recorded with a dot every dot printing interval. The
  dot printing interval is in the range of 10 s to 90 s. There are two recording methods
  from which you can select. One method automatically adjusts the dot printing interval
  according to the chart speed so that the dots do not overlap. The other method
  records at the fastest dot printing interval at all times.
- The recording colors in order from channel 01 are purple, red, green, blue, brown, and black. The recording color of each channel can be changed among these six colors.
- For each channel, trend recording can be enabled or disabled.

<Related Topics> Setting the trend recording interval: Section 6.1 Changing the recording color: Section 7.5 Enabling/Disabling trend recording for each channel: Section 6.6

# **Chart Speed**

On the pen model, the chart speed can be selected from 82 settings in the range of 5 to 12000 mm/h.


On the dot model, the chart speed can be set in the range of 1 to 1500 mm/h in 1-mm steps.


The default setting is 20 mm/h.

<Related Topics> Setting the chart speed: Section 5.4

#### **Zone Recording**


A recording zone is assigned to each channel. This function is useful such when the recording results overlap making them difficult to be viewed.





# Partial Expanded Recording


This function expands a section of the recording range. By default, partial expanded recording is disabled.



<Related Topics> Setting the partial expanded recording: Sections 7.13 and 6.5


# Pen Offset Compensation (Pen Model)

This function compensates for the pen offset (phase difference) along the time axis. On 2-pen, 3-pen, and 4-pen recorders, there are offsets along the time axis (phase difference) between the pens. This offset is corrected when pen offset compensation is used.



Below is an explanation for the 2-pen model.

The recording of these two pens are offset by an amount of phase P. If pen offset compensation is enabled, the measured values of pen 1 are stored in the memory, and recorded when the chart paper is fed by an amount corresponding to P.




By default, this function is disabled.

<Related Topics> Setting the pen offset compensation: Section 7.6

# Printout

The figure below is used to explain the printout contents. The actual printout and font are different from those illustrated in the figure. The printout positions are also slightly different.

Printout Example on the Pen Model



#### **Time tick**

A time tick is a mark that indicate the position of the date/time on the chart paper. **Time tick cancel mark** 

An exclamation point (!) is printed when the periodic printout time tick was not printed at the correct position.

Channel number or tag printout

Channel numbers or tags can be printed.

#### <Related Topics>

Switching between channel number printout and tag printout: Section 7.7

Setting the periodic printout (interval, reference time, types of measured values, and periodic printout ON/OFF): Section 7.8


Turning printout ON/OFF (alarm printout, recording start printout, new chart speed printout, scale printout for periodic printout, and recording color printout for periodic printout): Section 7.7

Setting the time format (alarm printout, message printout, recording start printout, and new chart speed printout): Section 7.16

Turning periodic printout ON/OFF for each channel: Section 6.6 Executing manual print: Section 3.7

Setting the message string and printing messages: Sections 6.8 and 3.10 Clearing the alarm printout buffer: Section 3.9 Printing settings: Section 3.8

### 1.4 Recording



# Channel Printout (Dot Model Only)

Prints the channel number or tag by the trend recording. The channel number or tag is printed every approximately 25 mm on the chart paper. The channel printout can be enabled or disabled. By default, the channel printout is enabled.

### <Related Topics>

Switching between channel number printout and tag printout: Section 7.7 Setting the periodic printout (interval, reference time, types of measured values, and periodic printout ON/OFF): Section 7.8

Turning printout ON/OFF (channel printout, alarm printout, recording start printout, new chart speed printout, and scale printout for periodic printout): Section 7.7

- Setting the time format (alarm printout, message printout, recording start printout, and new chart speed printout): Section 7.16
- Turning recording and printout ON/OFF for each channel (trend recording and periodic printout): Section 6.6
- Executing manual print: Section 3.7

Setting the message string and printing messages: Sections 6.8 and 3.10

Clearing the alarm printout buffer: Section 3.9

Printing settings: Section 3.8


1

### Alarm Printout

Alarm information is printed when an alarm occurs or releases.

Printout is not performed when the chart speed is as follows:

Pen model: 1600 mm/h or higher, dot model: 101 mm/h or higher



- The print condition can be set to (1) print when alarms occur and release, (2) print only when alarms occur, or (3) do not print.
- Alarms that occur while an alarm printout is in progress are temporarily saved to the buffer memory in a printout-wait condition. Alarms are cleared from the buffer memory when they are printed.
- The number alarms that can be stored in the buffer is 8 and 12 on the pen model and dot model, respectively. Alarms that occur while the buffer is full are not printed. A buffer overflow mark is printed when there are alarms that cannot be printed because the buffer is full.
  - Type Printout format Printout format Туре Hour:Minute:Second Hour:Minute 10:00 10:00:00 Month:Day: Nov. 09 Month:Day: Nov. 09 00:00:00 Hour:Minute 10:00 Hour:Minute:Second Year:Month:Day: Nov. 09. 2004 Hour:Minute:Second 10:00:00
- The time printout format can be selected.

\* The format of year, month, and day varies depending on the setting (see the next page).

# **Periodic Printout**

Measured values and other items are printed at the preset interval.

Printout is not performed when the chart speed is as follows:

Pen model: Less than or equal to 9 mm/h or greater than or equal to 1600 mm/h Dot model: 9 mm/h or less, 101 mm/h or greater

- Printout Contents (for details, see appendix 1)
  - Date/time, time ticks (marks that indicate the positions of the date/time on the chart paper); measured values, alarm status, scale (leftmost and rightmost values of span) and recording color (pen model) for each channel; and chart speed can be printed. When pen offset is being executed on the pen model, the pen offset marks are printed. On the pen model, if a time tick is not printed at the correct position, a time tick cancel mark (!) is printed.
  - Printout of measured values and alarm status can be enabled or disabled for each channel.
  - Printout of the scale and recording colors (pen model) can be enabled or disabled.
     The scale can be printed when the recording zone is greater than or equal to 40 mm.
  - The measured values for each channel can be selected from the following data types. Instantaneous value (measured value at the time of periodic printout) AVE (average of the measured values over an interval) MIN (minimum value of the measured values over an interval) MAX (maximum value of the measured values over an interval) MIX (minimum , maximum , and average value of the measured values over an interval) SUM (summed value of the measured values over an interval)
- Interval (for details, see appendix 2)

The printout interval can be set by specifying the value or set automatically in sync with the chart speed.

# • Turning ON/OFF the Periodic Printout

Periodic printout can be turn ON/OFF. By default, periodic printout is enabled with the interval synchronized to the chart speed. Also, the measured values that are printed are the instantaneous values.

# Manual Printout

Measured values and alarm status can be printed manually using the keys. When manual printout is executed, trend recording stops and restarts when manual printout is complete.

### **Message Printout**

Printout is not performed when the chart speed is as follows:

Pen model: 1600 mm/h or higher, dot model: 101 mm/h or higher

Preset messages can be printed on the chart paper using the keys. Five messages, each within 16 characters, can be registered in advance.

- If message printout is executed while another message is being printed, the most recent message is temporarily stored to the buffer memory in a printout-wait condition. Messages are cleared from the buffer memory when they are printed.
- The number of messages that can be stored in the buffer is 5. If message printout is executed when the buffer is full, the message is not printed. A buffer overflow mark is printed when there are messages that cannot be printed because the buffer is full.
- The time printout format can be selected.

# **New Chart Speed Printout**

Printout is not performed when the chart speed is as follows:

Pen model: 1600 mm/h or higher, dot model: 101 mm/h or higher

- When the chart speed is changed, the time tick (dot model), the date/time of change, and the new chart speed are printed. An asterisk (\*) shows there are messages that cannot be printed.
- · The time printout format can be selected.

# **Recording Start Printout**

Printout is not performed when the chart speed is as follows:

Pen model: 1600 mm/h or higher, dot model: 101 mm/h or higher

When recording is started, the time tick (dot model), the time, and the chart speed can be printed. An asterisk (\*) shows there are messages that cannot be printed.

- The recording start printout can be enabled or disabled. By default, the recording start printout is disabled.
- The time printout format can be selected.

# Printout/Display Format of the Date (Version 1.11 or Later)

The printout/display format of the date can be selected from the list below. The setting applies to all dates printed and shown on the display. However, this does not apply to the format of the date printout of the message printout that include the measured values (/BT1 option).

Туре	Printout/Display Format	
Y/M/D	2005/08/31	
M/D/Y	08/31/2005	
D/M/Y	31/08/2005	
D.M.Y	31.08.2005	
M.D.Y	Aug.31.2005	

<Related Topics> Setting the printout/display format of the date: Section 7.19


# Setting Printout

List or Setup List can be printed. When setting printout is executed, trend recording stops and restarts when the printout is complete.


List printout contains Setting Mode settings such as the input range and alarm for each channel.

Setup List contains Basic Setting Mode settings such as the alarm output relay operation and printout method.

# • Printout Example of List on the Pen Model




The printout examples may appear differently from the actual printout as a result of functional improvements made on the recorder after this manual was written.



The printout examples may appear differently from the actual printout as a result of functional improvements made on the recorder after this manual was written.

### Header Printout (/BT1 Option)

When recording is started, the Start printout is performed, and recording starts. During trend recording, you can print out messages (up to 5) that include measured values.\* When recording is stopped, End printout is performed.



\* Computed values can also be included on models with the /M1 option.

The printout examples may appear differently from the actual printout as a result of functional improvements.

### Start Printout and End printout

When recording starts, "Start printout" or "Start printout 2" prints. Also, when recording stops, "End printout" or "End printout 2" prints.

Printout/Operation	Description	Notes
Comment	Prints 32 characters x 5 lines or less.	
Batch name		Can be displayed in the main display.
Batch number	Prints up to 26 characters.	
Lot number	Prints a number from 4-digits or 6-digits.	You can automatically increment by 1 when recording stops.
Date/time	The date format prints out according to the date printout/display format.	Date and time cannot be turned On/Off independently.
Chart speed	Prints the current chart paper feed speed.	
Chart paper food	Feeds the chart paper 50 mm or less before Start printout.	Steps of 1 mm
Chart paper feed	Feeds the chart paper 50 mm or less after End printout.	Steps of 1 mm
Ejection of pen offset compensating data	You can record the portion of the data that remains after recording stops. Also, when recording the remaining portion of the data, you can change the chart speed to 450 mm/h (fixed).	When pen offset compensating is On (pen model).
	You can select whether to print out the batch name, date	/time, and chart speed. By default, the

You can select whether to print out the batch name, date/time, and chart speed. By default printout is enabled.

For the procedure to set the functions, see section 1.10, "Function Setup Guide."

# • Switching between Start Printout and Start printout 2, and between End printout and End printout 2


With the remote control function (/R1 option), you can change the items that are printed out.

For example, when a process ends successfully, End printout is performed and the lot number is updated. If the process fails, you can have End printout 2 be carried out and the lot number remain not updated.

Depending on the status of the "batch comment switching signal," the following switches occur when the "record start/stop signal" switches:

	Batch Comment Switching Signal Status				
Record Start/Stop Signal Status	Level: 0 (Open)	Level: 1 (Closed)			
Upon start Edge (rising)	Start printout	Start printout 2			
Upon stop Edge (falling)	End printout	End printout 2			


**Remote Control Signal** 



### Message Printout Including Measured Values\*

Following the specified message format, the date/time, message strings of the standard function (5 strings of up to 16 characters), and measured instantaneous values\* are printed out together.

- · Up to 5 messages of 35 characters can be entered.
- · Messages are printed out in the order in which they are set.
- Message strings set with the standard function are specified as the first n number of characters from the start of the string. If a number of characters is specified more than once, the first instance is n number of characters from the start of the string, the second instance is n number of characters immediately after the first instance, and so on. And, for example, the character string set for message 1 can only be used once for message format 1.



\* Computed values can also be included on models with the /M1 option.

<Related Topics> Setting the header printout: Sections 7.24 and 6.14 Assigning functions to the remote control input terminals: Section 7.18 Setting the message string: Section 6.8 Enabling the message format: Section 7.24 Setting the message format: section 6.15

# 1.5 Display

# **Displayed Information**

### Main Display

The recorder is capable of displaying measured values, alarm information, and so on the VFD (Vacuum Fluorescent Display). Using normal fonts, 17 characters × 2 lines can be displayed. Using large fonts, 11 characters can be displayed.

Status display

		Main d	lispla	у							
1		•									
	RECORD	KEY LOCK	MATH	CHART END	ALARM	1	2	3	4	5	6

Various display types are available. Also, different displays can be assigned to the top and bottom sections of the main display. These display types can be registered to screens 1 to 15 and switched during operation using the keys.

### **Status Display**

A status display is available at the bottom of the main display. The indicators below turn ON/OFF.

RECORD

This indicator turns ON when recording is started and turns OFF when stopped.

• ALARM 1 2 3 4 5 6

The numbers correspond to measurement channel numbers. The indicator turns ON when an alarm occurs and turns OFF when the alarm is released.

If the alarm indication is set to hold operation, the indicator blinks when an alarm occurs. When alarm ACK operation is performed, the indicator turns ON or OFF.

• MATH

This indicator turns ON when computation on the computation function (/M1 option) is started and turns OFF when stopped.

- KEYLOCK
  - This indicator turns ON when key lock is enabled and turns OFF when disabled.
- CHART END

This indicator turns ON when the remaining amount of chart paper falls to approximately 2 cm on models with the FAIL/chart end function and output function (/F1 option).

## **Display Types**

The following display types are available.

- Displays that show measured values
- Measured values can be displayed numerically or using bar graphs. The channels that are displayed can be switched automatically at constant intervals.

The bar graph displays 0 to 100% using 101 points.

0%	101 dots	100%
0 /0		100/0


- · Displays that show alarms
- Displays that show the date/time and chart speed
- Displays that show the remote control input and alarm output relay statuses (/R1 and /Ax options)
- · Displays that show the status
- System display
- Batch name (/BT1 option)

Different display types can be assigned to the top and bottom sections of the main display.

For the procedure to set the functions, see section 1.10, "Function Setup Guide."


Several display examples are shown below. For details on the display types, see "Display Function Specifications" in section 12.4.

### 1 Channel Digital + 1 Bar Graph Display




### **Flag Display**






#### **Alarm Status Display**



#### **Date/Time and Chart Speed**

The date format can be specified (see page 1-19).





Time

Chart speed

#### **Status Display**

Alarm status Remaining amount of chart paper is less than approx. 2 cm (/F1 option)

<b>•</b>	•	
۳Ŵ		

<Related Topics> Assigning display types to screens: Chapter 8 Switching displays: Section 3.6 Setting the bar graph display mode: Section 7.9 Changing the date format: Section 7.19 Setting the display brightness: Section 6.11 Displaying measured values: Section 12.4.

For the procedure to set the functions, see section 1.10, "Function Setup Guide."

# **1.6 Computation Function (/M1 Option)**

## **Computation Function**

Computing equations can be set up using measured values and other computed values as variables in computation-dedicated channels, and the computation can be executed. The computed result can be recorded. Computation is performed every scan interval.

## **Channels Dedicated to Computations**

The computation-dedicated channels below can be used.

Model	Number of Channels	Channel Names
Pen model	8	0A, 0B, 0C, 0D, 0E, 0F, 0G, and 0J
Dot model	12	0A, 0B, 0C, 0D, 0E, 0F, 0G, 0J, 0K, 0M, 0N, and 0P

## **Types of Computations**

In the table below, y represents the computed result. X and n represent the measured value, a constant, etc.

Туре	Syntax in the Equation	Description
Four arithmetic operation	+, -, *, /	Determines addition, subtraction, multiplication, and division.
Power	**	Determines the power. $y = X^n$
Square root	SQR()	Determines the square root.
Absolute value	ABS()	Determines the absolute value.
Common logarithm	LOG()	Determines the common logarithm. y=log <sub>10</sub> x
Exponent	EXP()	Determines the exponent. $y = e^{x}$
Relational computation	.LT., .LE., .GT., .GE., .EQ., .NE.	Determines <, <, >, or $\geq$ of two elements and outputs "0" or "1."
Logical computation	AND, OR, XOR, NOT	Determines the AND (logical product), OR (logical sum),XOR (exclusive logical sum) of two elements, NOT (negation) of an element and outputs "0" or "1."
TLOG computation	TLOG.SUM(), TLOG.MAX(), TLOG.MIN(), TLOG.AVE(), TLOG.P-P()	Determines the sum (SUM), the maximum (MAX), the minimum (MIN), the average (AVE), and the maximum – minimum (P-P) at specified time intervals. There are three timers for setting the interval.

## Data That Can Be Used in Equations

In TLOG computation, the measured values of measurement channels or computed values of computation channels can only be used. For all other computations, all of the data types below can be used.

- **Measured Values on Measurement Channels** Specified by the channel number. For channels that have scaling enabled, the scaled values are used in the computation.
- Computed Values on Computation Channels Specified by the channel number.
- Constants (K01 to K30) The values assigned to K01 to K30 can be used as constants. Range of values (maximum significant digits is 5): -9.9999E+29 to -1.0000E-30, 0, 1.0000E-30 to 9.9999E+29

Communication Input Data (Pen model: C01 to C08, dot model: C01 to C12)

This data type is set using the communication interface (/C7 or /C3 option). Range of values (maximum significant digits is 5):

-9.9999E+29 to -1.0000E-30, 0, 1.0000E-30 to 9.9999E+29

For the procedure of setting the communication input data, see the  $\mu R10000/\mu R20000$ Communication Interface User's Manual (IM04P01B01-17E).

- Status of the Remote Control Input Terminal (D01 to D05, /R1 option) The status of the remote control input signal (1 or 0) can be used in the computation. Use D01 to D05 (the number following the letter D is the remote control input terminal number) to specify the status in the equations.
- <Related Topics> Setting the computing equation, constant, and unit: Sections 9.2 to 9.4 Setting the TLOG timer: Sections 9.6 and 9.12

### Handing of the Unit in Computations

In computations, measured/computed values are handled as values without units. For example, if the measured value of channel 01 is 20 mV and the measured value of channel 02 is 20 V, the computed result of 01 + 02 is 40.

### **Recording Computation Channels**

### **Trend Recording**

Trend recording is possible by setting the recording span for each computation channel. The recording span of computation channels can be set in the range of –9999999 to 99999999 excluding the decimal.

Zone recording and partial expanded recording are also possible.

### Assignment of Computation Channels to the Pens (Pen Model)

Trend recording is possible by assigning computation channels to arbitrary pens. Only display or printout is possible for measurement channels or computation channels that are not assigned to a pen. Assignment of pens is possible only on models with the computation function.

Channel (01) (02) 03 (04) 0A 0B (0C) 0D 0E 0F 0G 0J

Measurement channels Computation channels

<Related Topics> Changing the channel assignment of recording pens: Section 9.14

### Changing the Channel Recording Color (Dot Model)

The recording colors of computation channels can be changed. The default recording colors of channels are indicated below.

Recording color	Purple	Red	Green	Blue	Brown	Black
Computation channels	0A	0B	0C	0D	0E	0F
	0G	0J	0K	0M	0N	0P

### The Number of Channels Being Trend Recorded and the Fastest Recording Interval

The fastest recording interval varies depending on the number of channels being trend recorded. Only display or printout is possible on measurement channels or computation channels that are not trend recorded.

Number of Channels Being Trend Recorded	Fastest Recording Interval
6 channels or less	10 s
7 to 12 channels	15 s
13 to 18 channels	20 s

<Related Topics> Changing the channel recording color: Section 9.13 Enabling/Disabling trend recording for each channel: Section 9.9

### Printout

Various printouts can be executed in the same fashion as measurement channels. The computed values of computation channels can be printed at constant intervals by using the periodic printout timer or the two TLOG timers. The TLOG timers can be used only on the computation channels. For the printout contents when printing using the TLOG timer, see appendix 1.

<Related Topics> Setting the periodic printout: Sections 7.8, 9.6, and 9.15 Setting the printout using the TLOG timer: Sections 9.6 and 9.12

### Alarms

Up to 4 alarms can be assigned to each computation channel.

- The alarm types are high limit alarm (H), low limit alarm (L), delay high limit alarm (T), and delay low limit alarm (t).
- Hysteresis can be specified to the values for activating and releasing the alarm. The hysteresis applies only to high limit alarm (H) and low limit alarm (L). The hysteresis width can be set in the range of 0.0% (Off) to 1.0% of the recording span in 0.1 steps. The setting applies to all high limit alarms and low limit alarms. By default, the hysteresis width is set to 0% (Off).

<Related Topics> Setting alarms: Section 9.5 Setting the alarm delay function: Sections 7.15 and 9.11 Setting the alarm hysteresis: Section 7.1

### Display

Computation channels can be displayed on the VFD as with the measurement channels.

<Related Topics> Setting the bar graph display mode: Section 9.16

### **Starting/Stopping Computation**

Computation can be started or stopped using keys.

<Related Topics> Starting/Stopping computation: Section 9.1

# 1.7 FAIL/Chart End Detection and Output Function (/F1 Option)

# FAIL Output


When a failure occurs in the CPU of the recorder, a relay contact signal (1 signal) is output. The relay is energized when the CPU is normal and de-energizes when a CPU failure occurs. Therefore, relay output is carried out also when the power is turned OFF (including a power failure). This relay behavior cannot be changed.

• FAIL Relay Output



# **Chart End Output**

When the remaining amount of chart paper falls to approximately 2 cm, recording is stopped, and the relay contact signal (1 relay) is output. The relay is energized in this case. This relay behavior cannot be changed.




# 1.8 Remote Control Function (/R1 Option)

Specified operations can be carried out by applying remote signals (contact or open collector signals) to the remote control input terminals.

There are five remote control input terminals. An action can be assigned to each terminal.

### µR10000 Recorder



### **Assignable Functions**

### Recording start/stop

- · Remote input signal: Rising edge signifies start; falling edge signifies stop
- Starts/stops recording.
- Applying a rising edge signal when recording is already in progress produces no effect. Applying a falling edge signal when recording is stopped produces no effect.

### Chart Speed Switch

- Remote input signal: Level
- The chart paper is fed at the secondary chart speed while a level signal is applied to the terminal. The secondary chart speed is set in advance.

### Message 1 Printout to Message 5 Printout

- Remote input signal: Trigger
- Prints message 1 to 5 on the chart paper.
- Manual Printout
  - Remote input signal: Trigger
  - Executes a manual printout.

### Alarm ACK

- Remote input signal: Trigger
- Alarm ACK is executed on all alarms that are occurring. This is valid only when the alarm indication or output relay operation is set to hold.

### Internal Clock Adjustment

- Remote input signal: Trigger
- The internal clock of the recorder is adjusted to the nearest hour depending on the time when the remote signal is applied.

Time When Signal Is Input	Adjustment
00 min 00 s to 01 min 59 s	Truncates the minutes and seconds.
	Example: 10 hours 01 min 50 s becomes 10 hours 00 min 00 s.
02 min 00 s to 57 min 59 s	The time is not changed.
58 min 00 s to 59 min 59 s	Rounds up the minutes and seconds.
	Example: 10 hours 59 min 50 s becomes 11 hours 00 min 00 s.

### 1.8 Remote Control Function (/R1 Option)

### Computation Start/Stop (/M1 Option)

- · Remote input signal: Rising edge signifies start; falling edge signifies stop
- Starts/stops the computation.
- If the computation is started, applying a rising edge signal produces no effect. If the computation is stopped, applying a falling edge signal produces no effect.

### Computation Reset (/M1 Option)

- · Remote input signal: Trigger
- The computed results of computation channels are reset. This is valid only while the computation is stopped. For all other cases, applying the remote signal produces no effect.

### • Priority to Remote Recording (/BT1 Option)


- Remote input signal: Edge (rising/start or falling/stop)
- Starts/stops recording.
- When started with a remote signal (on a remote signal rise), stop per key operation or communication is disabled.

### Switching Batch Comment (/BT1 Option)

- Remote input signal: Level
- Switches between Start printout and Start printout 2, and between End printout and End printout 2 depending on the status of the batch comment switching signal when recording is started/stopped remotely.
- · When starting/stopping by key operation, performs Start printout and End printout.

### Remote Signal (Edge, Trigger, and Level)

The above actions are carried out on the rising or falling edge of the remote signal (edge), the ON signal lasting at least 250 ms (trigger), or the ON/OFF signal (level).



For contact inputs, the remote signal rises when the contact switches from open to closed and falls when the contact switches from closed to open. For open collector signals, the remote signal rises when the collector signal (voltage level of the remote control terminal) goes from high to low and falls when the collector signal goes low to high.

<Related Topics> Assigning functions to the remote control input terminals: Section 7.18 Setting the secondary chart speed: Section 6.9

# 1.9 Other Functions

## Key Lock

Key lock is a function that prohibits key operations. When key lock is enabled, pressing keys produces no effect. To release the key lock, a password is entered.

### **Key Lock Items**

Each of the following keys can be included or excluded from the key lock function.



#### Keys that can be locked

In the case of the FUNC key, each function of the FUNC key can be included or excluded from the key lock function.


FUNC key functions: Alarm ACK execution, computation start/stop, manual printout and setting printout, message printout, printout buffer clear, resetting of the periodic printout report data (the average, etc.), and pen replacement (pen model), ribbon cassette replacement (dot model)

<Related Topics> Setting the key lock function: Section 7.10 Using the key lock function: Section 3.13

## Customize Menu

The menu can be customized to display only the menus that you use (version 1.31 or later).

- Display only the items that you use on the FUNC key menu.
- Display only the items that you use on the Setting mode menu.
- Lock Basic Setting mode (use a password to enter the mode).
   The pen position adjustment (pen model) and dot printing position adjustment (dot model) can be set so that they can be used without the password.



<Related Topics> Selecting the FUNC key menu: Section 7.20 Selecting the Setting mode menu: Section 7.21 Enabling/Disabling the customized menu: Section 7.22

### Language

The display and recording language can be set to English, Japanese, German, or French.

- English: Alphabet, numbers, and symbols
  - Japanese: Alphabet, numbers, katakana, and symbols
- German: German alphabet, numbers, and symbols
- French: French alphabet, numbers, and symbols
   \* German and French are supported on version 1.21 or later.

<Related Topics> Changing the language: Section 7.14

For the procedure to set the functions, see section 1.10, "Function Setup Guide."

## DST

If the recorder is used in a region that has DST, time can be switched automatically between DST and standard time by setting the date/time when switching from the standard time to DST and the date/time when switching back from DST to standard time. When switching from standard time to DST, the clock is set ahead by 1 hour. When switching back from DST to standard time, the clock is set back by 1 hour.

<Related Topics> Using the DST: Section 6.16

### Temperature Unit

The temperature unit can be set to Celsius or Fahrenheit. The setting applies to all channels.

<Related Topics> Changing the temperature unit: Section 7.25

# 1.10 Function Setup Guide

This section explains the settings necessary to use various functions of the recorder. Read the section corresponding to the function you wish to use.

### Note -

This section contains all the settings related to each item. If the desired setting is the same as the default value, you do not have to set it.

Item	Description	Reference Section
Date/Time setting	Use Clock in Setting mode.	5.5
DST	Sets the date/time for switching between DST and standard time using <b>Aux &gt; DST</b> in Setting mode.	6.16
Setting initialization	Use <b>Initialize</b> in Basic Setting mode to initialize the settings of Setting mode and Basic Setting mode to their default values.	7.17

# **Measuring input functions**

Item	Description	Reference Section
Range and span of the TC,	, RTD, or DC voltage	
	Use Range in Setting mode.	5.1
1-5V	Range, span, and scale	5.1
	Use Range in Setting mode.	
	• Unit	5.3
	Use <b>Unit</b> in setting mode to set the unit after scaling.	
	• Low-cut	7.15
	Use <b>Personalize &gt; Add function &gt; 1-5V low-cut</b> in Basic Setting mode and select Use or Not.	5.1
	If Use is selected, turn On/Off Low-cut using Range in Setting mode.	
	If Not is selected, the Low-cut item does not appear in the Range setting.	
Scaling	Range, span, and scale	5.1
	Use Range in Setting mode.	
	• Unit	5.3
	Use <b>Unit</b> in setting mode to set the unit after scaling.	
Square Root Computation	Range, span, and scale	5.1
	Use Range in Setting mode.	
	• Unit	5.3
	Use <b>Unit</b> in setting mode to set the unit after scaling.	
	• Low-cut	7.15
	Use <b>Personalize &gt; Add function &gt; SQRT low-cut</b> in Basic Setting mode and select Use or Not.	
	If Use is selected, set the Low-cut point using Range in Setting mode.	5.1
	If Not is selected, the Low-cut item does not appear in the Range setting.	
Unused channels	Use <b>Range &gt; Skip</b> in Setting mode to disable the trend recording (dot model) and periodic printout of the target channel.	5.1
Bias	Use Personalize > Add function > Bias in Basic Setting mode and select Use or Not.	7.15
	If Use is selected, set the bias value that is added to the input using <b>Bias</b> in Setting mode. If Not is selected, the <b>Bias</b> item does not appear.	6.12
Burnout detection function	(TC input and 1-5V input)	7.3
	Use <b>Burnout</b> in Basic Setting mode to set the burnout detection function for each channel.	
RJC of TC input	Use <b>RJC</b> in Basic Setting mode to select whether to use the internal RJC function or an external RJC function.	7.4
Filter (pen model)	Use Filter in Basic Setting mode and select Use or Not.	7.12
	If Use is selected, set the filter time constant using <b>Aux &gt; Filter</b> in Setting mode. If Not is selected, the <b>Aux &gt; Filter</b> item does not appear.	6.2

Item	Description	Reference
		Section
Moving average (de	ot model)	
	Use Moving_AVE in Basic Setting mode and select Use or Not.	7.11
	If Use is selected, set the number of samples of moving average using Aux >	6.3
	Moving_AVE in Setting mode.	
	If Not is selected, the Aux > Moving_AVE item does not appear.	
Integration time of the A/D converter		7.2
	Use A/D in Basic Setting mode to set the integration time of the A/D converter.	
Temperature Unit	Select the temperature unit using <b>Temperature</b> in Basic Setting mode.	7.25

# Alarm functions

Item	Description	Reference Section
Alarms for each channel	Use Alarm in Setting mode.	5.2
Delay high limit alarm/del	ay low limit alarm	
	Alarm type	7.15
	Use <b>Personalize &gt; Add function &gt; Alarm delay</b> in Basic Mode and select Use or Not.	
	If Use is selected, delay high limit alarm (T) and delay low limit alarm (t) become selectable under <b>Alarm &gt; Type</b> in Setting mode.	5.2
	If Not is selected, alarm delay cannot be selected.	
	Alarm delay time	6.10
	Use Aux > Alm delay T in Setting mode to set the alarm delay time.	
High limit on rate-of-chan	ge alarm/low limit on rate-of-change alarm	
•	Use <b>Alarm</b> in Setting mode and set the channel to rate-of-change alarm.	5.2
	Use Alarm > Increase in Basic Setting mode to set the interval of the high limit on	7.1
	rate-of-change alarm; use Alarm > Decrease in Basic Setting mode to set the interval	
	of the low limit on rate-of-change alarm.	
Use the alarm ACK opera	tion	
	<ul> <li>Relay operation and display operation</li> </ul>	7.1
	Set <b>Alarm &gt; Behavior</b> in Basic Setting mode to Hold and set <b>Alarm &gt; Indicator</b> to Hold.	
	<ul> <li>Executing the alarm ACK operation</li> </ul>	3.12
	Use Func > Alarm ACK in Operation mode to execute the release of the alarm output.	
Set a hysteresis on the al	arm occurrence/release value of high limit alarm and low limit alarm	
	Use <b>Alarm &gt; Hysteresis</b> in Basic Setting mode to set the hysteresis to be applied to the high limit alarm and low limit alarm of measurement channels.	7.1
	Likewise, use <b>Alarm &gt; M_Hysteresis</b> to set the hysteresis to be applied to the high limit alarm and low limit alarm of computation channels (/M1 option).	
Change the alarm output		
enange the diam output	If Alarm > Act in Basic Setting mode set to De energize, alarm output relay is	7.1
	energized during normal operation and de-energized when an alarm occurs.	
Diagnosis output	Use Alarm > Diagnosis in Basic Setting mode to set the function.	7.1

# **Recording functions**

Item	Description	Reference Section
Chart speed	Use Chart in Setting mode to set the chart speed.	5.4
Turn trend recording	ON/OFF (dot model)	
	Use <b>Aux &gt; Print</b> out in Setting mode to set whether to trend record on each measurement channel.	6.6
Change the recording	g color of measurement channels (dot model).	
	Use <b>Color</b> in Basic Setting mode to set the recording color of measurement channels.	7.5
Record by compens	ating for the pen offset along the time axis (pen model)	
	Use Aux > POC in Setting mode to turn On/Off offset compensation.	7.6
Record by setting re	cording zone	
	Use Aux > Zone in Setting mode to set the recording zone for each channel.	6.4
Partial expanded red	cording Use Partial in Basic Setting mode and select Use or Not.	7.13
	If Use is selected, set the display mode using Aux > Partial in Setting mode.	6.5
	If Not is selected, the Aux > Partial item does not appear.	

1

Functional Explanation and Setup Guide

### 1.10 Function Setup Guide

Item	Description	Referenc Section
Periodic printout	Mar.31.2004!         Channel number or tag           15:50*         1.000V           2         1.000V	
	0.000 2.000 Scale	
		. <b>r</b>
	RED  Recording colo 50mm/h_	7
	<ul> <li>Type of measured values to be printed/disable periodic printout</li> <li>Use Print1 in Basic Setting mode to set the type of measured values to be printed.</li> <li>You can select Inst, Report (statistical calculation value), or Off.</li> </ul>	7.8
	• If Report is selected, use <b>Print2</b> in Basic Setting mode to select the report data type.	7.8
	Printout interval	7.8
	<ul> <li>Use Print 1 in Basic Setting mode to set the periodic printout interval.</li> <li>Turn On/Off periodic printout for each channel</li> <li>Use Aux &gt; Print out in Setting mode to enable/disable the periodic printout on each</li> </ul>	6.6
	measurement channel.	
	<ul> <li>Scale printout and recording color printout (pen model)</li> <li>Use Print &gt; Scale in Basic Setting mode to turn scale printout On/Off.</li> </ul>	7.7
	Use <b>Print &gt; Scale</b> in Basic Setting mode to turn scale printout On/Off. Use <b>Print &gt; Pen color</b> in Basic Setting mode to turn pen color printout On/Off (pen model).	
Tag printout	<ul> <li>Select channel printout or tag printout</li> <li>Use Print &gt; CH/Tag in Basic Setting mode to select whether to use channel numbers or tags in printouts.</li> </ul>	7.7
	Set the tag	6.7
Tag display	Use <b>Aux &gt; Tag</b> in Setting mode to set the tag name. In data display setup mode, select <b>Screen No.</b> > (the screen number) > Tag_1CH digital display, Tag_2CH digital display, Tag_1CH digital + 1CH bargraph, or Tag_1CH digital + 4CH bargraph.	8.2
Alarm occurrence/release		
	Turn printout On/Off	7.7
	Use <b>Print &gt; Alarm</b> in Basic Setting mode to select whether to print the alarm occurrence and release, print only the alarm occurrence, or not print.	
	<ul> <li>Time printout format Use Personalize &gt; Time print &gt; Alarm in Basic Setting mode to set the time printout format when printing alarm occurrence/release.</li> </ul>	7.16
Recording Start Printout	Turn printout On/Off	7.7
	Use <b>Print &gt; Record On</b> in Basic Setting mode to enable/disable the recording start printout.	
	• Time printout format	7.16
	Use <b>Personalize &gt; Time print &gt; RCD On</b> in Basic Setting mode to set the time	
New chart speed printout	printout format.     Turn printout On/Off	7.7
New chart speed printout	Use <b>Print &gt; Chart speed</b> in Basic Setting mode to set whether to print the new chart speed when the chart speed is changed.	1.1
	<ul> <li>Time printout format</li> <li>Use Personalize &gt; Time print &gt; C. Speed in Basic Setting mode to set the time printout format.</li> </ul>	7.16
Message printout	Set the message string	6.8
	Use Aux > Message to set the message string to be printed.	0.0
	<ul> <li>Time printout format</li> <li>Use Personalize &gt; Time print &gt; Message in Basic Setting mode to set the time</li> </ul>	7.16
	<ul><li>printout format.</li><li>Execute the message printout</li></ul>	3.10
	Use Func > Message in Operation mode to execute the message printout.	
Date format	Use <b>Date format &gt; Type</b> in Basic Setting mode to set the printout/display format of the date.	7.19

# **Display functions**

Item	Description	Reference
		Section
Display brightness	Use Aux > Brightness > Display in Setting mode to set the display brightness.	6.11
Bar graph display mode	Use Bar graph in Basic Setting mode to set the bar graph display mode.	7.9
Display type	Assigns the display type on the data display setup Screen No.	Chapter 8
Date format	Same as the Date format in "Recording functions."	7.19

## Other functions

Item	Description	Reference Section
Key lock	Target keys and password	7.10
	Use <b>Keylock</b> in Basic Setting mode to set the keys to be key-locked and the password.	
	Enable the key lock	3.13
	Use Func > Keylock in Operation mode and select Use or Not.	
Customized menu	Selecting the FUNC key display menu	7.20
	Use <b>Select menu &gt; Function</b> in Basic Setting mode to select the menus to be displayed.	
	<ul> <li>Selecting the displayed menu of Setting mode</li> </ul>	7.21
	Use <b>Select menu &gt; Set mode</b> in Basic Setting mode to select the menus to be displayed.	
	Executing the customize menu	7.22
	Use <b>Cust. menu</b> in Basic Setting mode to set whether to use the customized menu. If Use is selected, only the menus set to ON in the menu selection are displayed, and Basic Setting mode is locked.	
	If Not is selected, all menus are displayed, and the Basic Setting mode lock is released.	
Language	Use Language in Basic Setting mode to set the display and printout language.	7.14
Internal light brightness	Use Aux > Brightness > Light in Setting mode to set the internal light brightness.	6.11

# Computation function (/M1 option)

Item	Description	Reference Section
Computing equation and r	ecording span	
	Use <b>Math &gt; Formula</b> in Setting mode to set the computing equation and recording span for each channel.	9.2
TLOG computation	If TLOG computation is selected, use <b>Math &gt; Timer</b> in Basic Setting mode to set the timer operation	9.12
	Use <b>Math &gt; TLOG &gt; Timer No.</b> in Setting mode to set the timer used on each computation channel.	9.6
Unit	Use Math > Unit in Setting mode to set the unit for each channel.	9.3
Constants	Use <b>Math &gt; Constant</b> in Setting mode to define constants to be used in the computing equations.	9.4
Alarms	Use <b>Math &gt; Alarm</b> in Setting mode to set the alarm for each channel. • Delay high limit alarm/delay low limit alarm	9.5
	<ul> <li>Alarm type         Use Personalize &gt; Add function &gt; Alarm delay in Basic Mode and select Use or         Not (common with measurement channels).         If Use is selected, delay high limit alarm and delay low limit alarm become selectable         under Math &gt; Alarm &gt; Type in Setting mode. If Not is selected, alarm delay cannot         be selected.</li> </ul>	7.15
	<ul> <li>Alarm delay time</li> <li>Use Math &gt; Aux &gt; Alm delay T in Setting mode to set the alarm delay time.</li> </ul>	9.11
Record by setting recordir		
Record by Setting recordin	Use Math > Aux > Zone in Setting mode to set the recording zone for each channel.	9.7
Partial expanded recording	g Use <b>Partial</b> in Basic Setting mode and select Use or Not.	7.13
	If Use is selected, set the display mode using <b>Math &gt; Aux &gt; Partial</b> in Setting mode. If Not is selected, the <b>Math &gt; Aux &gt; Partial</b> item does not appear.	9.8
Change the recording cold	or (dot model)	
	Use <b>Color</b> in Basic Setting mode to set the recording color of each computation channel.	9.13

### 1.10 Function Setup Guide

ltem	Description	Referen Section
Recording pen ass	ignment (pen model)	
	Assigns measurement/computation channels to the recording pens.	9.14
Turn trend recordin	g ON/OFF (dot model)	
	Use Math > Aux > Print out > Trend in Setting mode to set whether to trend record	9.9
	each computation channel.	
Periodic printout	Mar.31.2004! Channel num	abor
	15:50^	iber
	1 / 1.000	alua
	$(A) \leftarrow (-100.00 \text{UNIT}) \leftarrow Computed v.$	aiue
	RED	olor
	50mm/h_	
	<ul> <li>Type of computed values to be printed/disable periodic printout Common with measurement channels.</li> </ul>	7.8
	<ul> <li>If Report is selected, use Math &gt; Print2 in Basic Setting mode to select the report data type.</li> </ul>	9.15
	Printout interval	7.8
	Set Math > TLOG > Timer No. in Setting mode to Periodic.	
	The interval is common with measurement channels.	
	<ul> <li>Turn On/Off periodic printout for each channel</li> </ul>	9.9
	Use Math > Aux > Print out > Periodic in Setting mode to enable/disable the	
	periodic printout for each computation channel.	
	<ul> <li>Scale printout and recording color printout (pen model)</li> </ul>	7.7
	Common with measurement channels.	
Periodic printout us	sing TLOG timer (dedicated to computation channels)	
	Mar.31.2004! Channel nun	abor
	$\begin{bmatrix} TAG-00A \\ B \end{bmatrix} \leftarrow \begin{bmatrix} 100.00UNITA \\ 1.0 \end{bmatrix} \leftarrow \begin{bmatrix} 0 \text{ tag} \\ Computed v \end{bmatrix}$	alue
	-200,00 -200,00	
	TAG-00A ZOU.UN Scale	
	RED	
	TLOG1  Timer number	ər
	<ul> <li>Use Math &gt; Timer (TLOG) in Basic Setting mode to set the printout interval.</li> </ul>	9.12
	• Use Math > Timer (TLOG) > Print in Basic Setting mode to turn the printout On.	9.12
	<ul> <li>Use Math &gt; Aux &gt; Print out &gt; Periodic in Setting mode to enable/disable the</li> </ul>	9.9
	periodic printout for each computation channel.	
	<ul> <li>Set Math &gt; TLOG &gt; Timer No. in Setting mode to set the timer used on each</li> </ul>	9.6
	computation channel.	
	<ul> <li>Scale printout and recording color (pen model)</li> </ul>	7.7
	Common with periodic printout.	
larm occurrence/r	•	
	Common with measurement channels.	7.7
āg	Channel/tag selection	7.7
	Common with measurement channels.	
	• Tag name	9.10
	Use Math > Aux > Tag in Setting mode to set the tag name.	0.10
3ar graph display r	node Use <b>Math &gt; Bar graph</b> in Basic Setting mode to set the bar graph display mode.	9.16
	omputed results are in error	

# Remote control function (/R1 option)

ltem	Description	Reference Section
Remote co	ontrol function (/R1 option)	
	<ul> <li>Assign functions to the remote control input terminals</li> </ul>	7.18
	Use <b>Remote</b> in Basic Setting mode to set the function to be assigned to the remote control input terminal.	
	Secondary chart speed	6.9
	If "chart speed switching" is assigned, use <b>Aux &gt; Chart 2</b> in Setting mode to set the secondary chart speed.	
	<ul> <li>Switching between start printout and start printout 2 and between end printout and end printout 2 (/BT1 option)</li> </ul>	
	If BatchCMT switch is assigned	
	Use <b>Batch &gt; Dual comment</b> in Basic Setting mode to enable or disable start printout 2 and end printout 2.	7.24
	If Use is selected, set Batch > Detail > Start2 and End2 in Setting mode.	6.14
	If Not is selected, the <b>Batch &gt; Detail &gt; Start2</b> and <b>End2</b> items in Setting mode do not appear.	

# Calibration Correction (/CC1 Option)

Item	Description	Reference
		Section
Calibration	correction function	
	Use Personalize > Add function > Calibration in Basic Setting mode and select Use or Not.	7.15
	If Use is selected,	
	<ul> <li>Use Calibration in Basic Setting mode to set the correction mode and the number of calibration points.</li> </ul>	7.23
	<ul> <li>Use Calibration in Setting mode to set the measured value and correction value for each channel.</li> </ul>	6.13
	If Not is selected, the Calibration item does not appear.	

# Header Printout (/BT1 Option)

Item	Description	Reference Section
Setting sta	t printout and end printout	
	Use <b>Batch</b> in Basic Setting mode to set whether to use the start printout and end printout. If Use is selected, select a Lot No. from 4 digits, 6 digits, or OFF. If Use is selected.	7.24
	Use Batch > Batch No. in Setting mode to set the batch number. Use Batch > Lot No. in Setting mode to set the lot number. Use Batch > Detail > Start, End in Setting mode.	6.14
	If Not is selected, the <b>Batch &gt; Lot No.</b> item in Basic Setting mode and the Batch item in Setting mode do not appear.	
Switch betw	<ul> <li>veen start printout and start printout 2 and between end printout and end printout 2 (/R1 option)</li> <li>Switch settings</li> </ul>	
	Assign "BatchCMT switch" to the remote control input terminal.	7.18
	Use <b>Batch &gt; Dual comment</b> in Basic Setting mode to set whether to use start printout 2 and end printout 2.	7.24
	If Use is selected, set <b>Batch &gt; Detail &gt; Start2</b> and <b>End2</b> in Setting mode. If Not is selected, the <b>Batch &gt; Detail &gt; Start2</b> and <b>End2</b> items in Setting mode do not appear.	6.14
	<ul> <li>Executing the switch The switch occurs according to the status of the "BatchCMT switch" signal when "Record On/Off" or "Priority R_RCD" signal assigned to the remote control input terminal rises or falls.</li> </ul>	1.4
Printout of	messages including measured/computed values	
	<ul> <li>Setting message strings</li> <li>Use Aux &gt; Message in Setting mode to enter the message to print out.</li> <li>Setting the message format</li> </ul>	6.8
	Use <b>Batch &gt; MSG format</b> in Basic Setting mode and select whether to use the message format.	7 24
	If Use is selected, use <b>Batch &gt; MSG format &gt; Message No.</b> in Setting mode to set the message format.	
	If Not is selected, the <b>Batch &gt; MSG format</b> item does not appear.	
	<ul> <li>Executing message printout</li> <li>Use Func &gt; Message in Operation mode to execute the message printout.</li> </ul>	3.10

# 2.1 Handling Precautions

This section describes the precautions to be taken when using the recorder. Read this section before use.

## **Handling Precautions**

- Use care when cleaning the recorder, especially any plastic parts. When cleaning, wipe using a dry soft cloth. Do not use chemicals such as benzene or thinner, since these may cause discoloring and deformation.
- Keep electrically charged objects away from the recorder as this may cause malfunction.
- Do not apply volatile chemicals to the door glass, display, panel keys, etc. Do not allow rubber and vinyl products to remain in contact with the recorder for long periods of time. This may damage the recorder.
- When not in use, make sure to turn OFF the power switch.
- If there are any symptoms of trouble such as strange odors or smoke coming from the recorder, immediately turn OFF the power switch and the power supply source. Then, contact your nearest YOKOGAWA dealer.

# 2.2 Installation

## Installation Location

Install the recorder indoors in a location that meets the following conditions. See also the normal operating conditions described in section 12.6, "General Specifications."

### Instrument Panel

The recorder is designed for panel mounting. The portable type (/H5x option) is designed to be used on the desktop.

### Well-Ventilated Location

To prevent overheating, install the recorder in a well-ventilated location. For the panel cut dimensions when arranging multiple recorders, see section 12.7. Follow the panel cut dimensions providing adequate space between instruments when other instruments are arranged on the panel. We recommend that you secure at least 50 mm of space from the left, right, top, and rear panels on the portable type (/H5x option).

### Minimum Mechanical Vibrations

Choose an installation location with the minimum mechanical vibration. Installing the recorder in a location with large mechanical vibration not only causes adverse effects on the mechanism but also may hinder normal recording.

### Horizontal

Install the recorder horizontally (However, the recorder can be inclined up to 30 degrees backwards for panel mounting).

### Note .

- Condensation may occur if the recorder is moved to another place where both the ambient temperature and humidity are higher, or if the temperature changes rapidly. In addition, measurement errors will result when using thermocouples. In this case, let the recorder adjust to the new environment for at least one hour before using it.
- The chart paper may be adversely affected by a rapid change in the ambient temperature and humidity.

Do not install the instrument in the following places.

- Outdoors
- In direct sunlight or near heat sources

Install the recorder in a place with small temperature fluctuations near room temperature (23°C). Placing the recorder in direct sunlight or near heat appliances can cause adverse effects on the internal circuitry.

• Where an excessive amount of soot, steam, moisture, dust, or corrosive gases are present

Soot, steam, moisture, dust, and corrosive gases will adversely affect the recorder. Avoid such locations.


### Near Strong Magnetic Field Sources

Do not bring magnets or instruments that produce electromagnetic fields close to the recorder. Operating the recorder in strong magnetic fields can cause errors in the measurements.

### Installation Procedure

The recorder should be mounted on a steel panel of thickness 2 mm to 26 mm.

- **1.** Insert the recorder from the front side of the panel.
- **2.** As shown in the figure below, mount the recorder to the panel using the mounting brackets that come with the package.
  - Use two brackets to support the top and bottom or the left and right sides of the case. (Remove the seal that is covering the holes for the mounting brackets beforehand.)
  - The proper torque for tightening the mounting screws is 0.7 to 0.9 N•m.
  - Mount the recorder to the panel according to the procedure below.
    - First, attach the two mounting brackets and temporarily fasten the attachment screws.
    - Next, fix the recorder in place by tightening the attachment screws with the appropriate torque. When the recorder is approximately perpendicular to the panel as you fasten the screws, press the mounting bracket against the case so that they are in contact with each other.



# CAUTION

Tightening the screws too much can deform the case or damage the bracket.

For the dimensional drawings and panel cut dimensions, see section 12.7.

# 2.3 Input Signal Wiring

# General Precautions to Be Taken While Wiring



# WARNING

To prevent the possibility of electric shock when wiring, make sure that the power supply source is turned OFF.



# CAUTION

- The input terminals of this instrument are specific to this instrument. Do not connect the input terminals of the  $\mu$ R1000,  $\mu$ R1800 or other models, as malfunction may result.
- If a strong tension is applied to the cable wired to the recorder, the terminals of the recorder and/or the cable can be damaged. In order to prevent tension from being applied directly on the terminals, fasten all wiring cables to the rear of the mounting panel.
- Do not apply a voltage exceeding the following value to the input terminals as this may damage the recorder.
  - Maximum input voltage
    - Voltage range less than or equal to 200 mVDC, TC, RTD, and DI:  $\pm$ 10 VDC Ranges other than those listed above:  $\pm$ 60 VDC
  - Maximum common-mode voltage
    - ±60 VDC (under measurement category II conditions)
- The recorder is an INSTALLATION CATEGORY II product.

## Precautions to Be Taken While Wiring

Take the following precautions when wring the input signal cables. It is recommended that crimp-on lug with insulation sleeves (designed for 4-mm screws) be used when connecting the input/output signal wires to the terminals. However, this does not apply clamped terminals (/H2).

Crimp-on lug with insulation sleeves (for 4-mm screws)

### For clamped terminals (/H2), the following wire is recommended.

- Conductive cross-sectional area for single wire: 0.14 mm<sup>2</sup> to 1.5 mm<sup>2</sup>, stranded wire:
   0.14 mm<sup>2</sup> to 1.0 mm<sup>2</sup>
- Length of the stripped section of the wire: Approx. 5 mm

### Take measures to prevent noise from entering the measurement circuit.

- Move the measurement circuit away from the power cable (power circuit) and ground circuit.
- It is desirable that the object being measured does not generate noise. However, if this is unavoidable, isolate the measurement circuit from the object. Also, ground the object being measured.
- Shielded wires should be used to minimize noise caused by electrostatic induction. Connect the shield to the ground terminal of the recorder as necessary (make sure you are not grounding at two points).

- To minimize noise caused by electromagnetic induction, twist the measurement circuit wires at short, equal intervals.
- Make sure to earth ground the protective ground terminal through minimum resistance (less than 100 Ω).

When using internal reference junction compensation on the thermocouple input, take measures to stabilize the temperature at the input terminal.

- Always use the terminal cover.
- Do not use thick wires which may cause large heat dissipation (cross sectional area of 0.5 mm<sup>2</sup> or less recommended).
- Make sure that the ambient temperature remains reasonably stable. Large temperature fluctuations can occur if a nearby fan turns ON or OFF.


# Connecting the input wires in parallel with other devices can cause signal degradation, affecting all connected devices.


If you need to make a parallel connection, then

- Turn the burnout detection function OFF.
- Ground the instruments to the same point.
- Do not turn ON or OFF another instrument during operation. This can have adverse effects on the other instruments.
- RTDs cannot be wired in parallel.


### Arrangement of the Measuring Input Terminals

A terminal cover is screwed in place on the measuring input terminal block on the rear panel. A label indicating the terminal arrangement is affixed to the cover.





- 1. Turn OFF the recorder and remove the terminal cover.
- 2. Connect the signal wires to the terminals.




#### Note

Input signal wires of diameter less than or equal to 0.3 mm may not be secured firmly for clamped terminals (/H2). Fold over the conducting section of the wire, for example, to make sure that the wire is securely connected to the clamped terminal.

**3.** Replace the terminal cover and fasten it with screws. The proper torque for tightening the screws is 0.6 N•m.

## **Measuring Input Wiring**



RTD input terminals A and B on the dot model are isolated on each channel. Terminal b is shorted internally across all channels. However, for 3 legs isolated RTDs (/N2 option), input b is also isolated for each channel.

# 2.4 Optional Terminal Wiring

# General Precautions to be Taken While Wiring the Input/Output Signal Wires



# WARNING

- To prevent electric shock while wiring, ensure that the power supply source is turned OFF.
- If a voltage of more than 30 VAC or 60 VDC is to be applied to the output terminals, use ring-tongue crimp-on lugs with insulation sleeves on all terminals to prevent the wires from slipping out when the screws become loose.
   Furthermore, use double-insulated wires (dielectric strength of 2300 VAC or more) for the signal wires on which a voltage of more than 30 VAC or 60 VDC is to be applied. For all other wires, use basic insulated wires (dielectric strength of 1390 VAC). To prevent electric shock, attach the terminal cover after wiring and make sure not to touch the terminals.

Crimp-on lug with insulation sleeves (for 4-mm screws)




# CAUTION

- The option terminals of this instrument are specific to this instrument. Do not connect the option terminals of the µR1000, µR1800 or other models, as malfunction may result.
- To prevent fire, use signal wires having a temperature rating of 70°C or more.
- If a strong tension is applied to the cable wired to the recorder, the terminals of the recorder and/or the cable can be damaged. In order to prevent tension from being applied directly on the terminals, fasten all wiring cables to the rear of the mounting panel.


# Arrangement of the Optional Terminals

As shown in the figure below, the optional terminal block is located on the rear panel. The optional terminal block is provided on the recorder when an option that requires input/output is installed such as the alarm output relay (/A1, /A2, or /A3 option), FAIL/ chart end output (/F1 option), remote control function (/R1 option), RS-422A/485 interface (/C3 option)<sup>\*</sup>, and Ethernet (10BASE-T) interface (/C7 option)<sup>\*</sup>. A terminal cover is screwed in place on the measuring input terminal block. A label indicating the terminal arrangement is affixed to the terminal block.

\* For details on terminal and connector arrangement and wiring, see the μR10000 /μR20000 Communication Interface User's Manual (IM 04P01B01-17E).



### 2.4 Optional Terminal Wiring



Alarm Output Relay Terminals and FAIL/Chart End Output Relay Terminals NC (Normally Closed), C (Common), NO (Normally Opened)


### **Remote Control Input Terminals**

1 to 5 (remote control input terminals), C (Common)

Alarm output terminals correspond to 101 to 106 in the alarm output relay settings. Remote control input terminals 1 to 5 correspond to numbers 1 to 5 in the remote control input settings. 2

### **Wiring Procedure**

- **1.** Turn OFF the recorder and remove the terminal cover.
- 2. Connect the input/output signal wires to the terminals.



 Replace the terminal cover and fasten it with screws. The proper torque for tightening the screws is 0.6 N•m.

### Alarm Output Relay Terminals and FAIL/Chart End Output Relay Terminals




#### NO (Normally Opened), C (Common), NC (Normally Closed)

### Relay Contact Output Specifications

Output type:	Relay
Contact rating:	250 VAC (50/60 Hz)/3 A, 250 VDC/0.1 A (resistive load)
Dielectric strength:	1500 VAC at 50/60 Hz for one minute (between output
	terminals and the ground terminal)

#### Remote Control Input Terminals



### Relay Contact Input/Transistor Input Specifications

 Voltage-free contact: Contact closed at 200 Ω or less and contact open at 100 kΩ or greater

 Open collector: 0.5 V or less (30 mADC) when turned ON, leakage current of 0.25 mA or less when turned OFF
 Dielectric strength: 500 VDC for one minute between input terminals and the ground terminal

#### Note -

Input signal:

To reduce noise, use a shielded cable for the wiring of the remote control input terminals. Connect the shield to the ground terminal of the recorder.

# 2.5 Power Supply Wiring

### Precautions to Be Taken While Wiring the Power Supply

Make sure to follow the warnings below when wiring the power supply. To prevent electric shock and damage to the recorder, observe the following warnings.





- Panel Mount Type
  To prevent electric shock when wiring, ens
  - To prevent electric shock when wiring, ensure the main power supply is turned OFF.
- To prevent the possibility of fire, use 600 V PVC insulated wire (AWG 20 to 16) or an equivalent wire for power wiring.
- Make sure to earth ground the protective earth terminal through a grounding resistance less than 100  $\Omega$  before turning ON the power.
- Use crimp-on lugs (designed for 4 mm screws) for power and ground wiring termination.
- To prevent electric shock, make sure to close the transparent cover for the power supply wires.
- Make sure to provide a power switch (double-pole type) on the power supply line in order to separate the recorder from the main power supply. Put an indication on this switch as the breaker on the power supply line for the recorder and indications of ON and OFF.

Switch specifications

Rated power current: 1 A or more (other than /P1), 3 A or more (/P1 option) Rated rush current: 60 A or more (other than /P1), 70 A or more (/P1 option) Complies with IEC 60947-1, 3.

• Connect a fuse in the power supply line. Use a fuse approved by CSA (for the use in North America) or VDE (for the use in Europe).

2 A to 15 A (other than /P1), 4 A to 15 A (/P1 option)

• Do not add a switch or fuse to the ground line.

#### Portable Type (/H5x Option)

- Ensure that the source voltage matches the rated power supply voltage of the instrument before connecting the power cord.
- Connect the power cord after checking that the power switch of the portable type is turned OFF.
- To prevent electric shock or fire, be sure to use the power cord for the portable type supplied by YOKOGAWA.
- Make sure to connect protective earth grounding to prevent electric shock. Connect the power cord of the portable type to a three-prong power outlet equipped with a protective earth terminal.
- Do not use an extension cord that does not have a protective grounding wire. The protective features of the instrument will be rendered ineffective.

Use a power supply that meets the following conditions:

Item	Power Supply Specifications	
	(Options Other Than /P1)	(/P1 Option)
Rated supply voltage	100 to 240 VAC	24V DC/AC
Allowable power supply voltage range	90 to 132/180 to 264 VAC	21.6 V to 26.4 VDC/AC
Rated power supply frequency	50/60 Hz	50/60 Hz (for AC)
Allowable power supply frequency range	50/60 Hz ± 2%	50/60 Hz ± 2% (for AC)
Maximum power consumption	40 VA	25 VA (for DC) or 35 VA (for AC)

### Note\_


Do not use a supply voltage in the range 132 to 180 VAC, as this may have adverse effects on the measurement accuracy.

### Wiring Procedure


#### Panel Mount Type

The power supply terminals and protective ground terminals are located on the rear panel.

1. Turn OFF the power switch on the recorder and open the power terminal cover.




**2.** Wire the power cord and the protective ground cord to the power supply terminals. Use ring-tongue crimp-on lugs (designed for 4 mm screws).



**3.** Close the power supply terminal cover and secure it with the screw. The proper torque for tightening the screws is 0.6 N•m.

### Portable Type (/H5x Option)

- 1. Check that the power switch to the recorder is turned OFF.
- **2.** Connect the plug on the accessory power cord to the power supply connector on the rear panel.



**3.** Ensure that the power outlet to be used meets the conditions on the previous page and that the voltage of the power supply is within the maximum voltage rating of the power cord, then connect the other end of the power cord to the power supply outlet.

The AC outlet must be of a three-prong type with a protective earth ground terminal.

# 2.6 Turning ON/OFF the Power Switch




# CAUTION

Check the following points before turning ON the power switch.

- · The power cord/wires are connected correctly to the recorder.
- The recorder is connected to the correct power supply (see section 2.5).

The power switch is located inside the door at the lower right.

The power switch is a push button. Press once to turn it ON and press again to turn it OFF.



When the power switch is turned ON, a self-diagnosis program runs for a few seconds, and the recorder is ready for operation.

### Note.

- If the input wires are connected in parallel with other devices, do not turn ON/OFF the power switch of the recorder or another device during operation. This can have adverse effects on the measured values.
- If nothing is displayed when the power switch is turned ON, turn OFF the power switch and check the points listed above one more time. After checking the points, turn ON the power switch again. If the unit still does not work, it is probably malfunctioning. Contact your nearest YOKOGAWA dealer for repairs.
- If an error message is displayed on the screen, take measures according to the description in chapter 10, "Troubleshooting."
- Turn ON the power switch, let the recorder warm up for at least 30 minutes, and then start the measurements.


### Checking the Date/Time

The date/time is shown on the display when the **DISP** key is pressed several times. To correct the date/time, see the reference indicated below.

<Related Topics> Setting the date/time: See section 5.5

# 3.1 Names of Parts

Front




Display and key panel (see the next page) There is an internal light on the bottom section of the display and key panel. It lights up the recording area of the chart paper.

#### Display and Key Panel Status display Displays the following information. RECORD Illuminates while recording measured values. **KEY LOCK** Illuminates when key lock is enabled. MATH Illuminates when computation on the computation function (/M1 option) is in progress. CHART END Illuminates when the chart paper is out (/F1 option). ALARM 1 to 6 Illuminates when an alarm is occurring on channels 1 to 6. Main display Displays the measured values. Also, displays the setup screen when setting functions. ALARM RECORD KEY LOCK MATH CHART END 1 2 3 4 5 6 SHIFT CHARACTER $\nabla \Delta$ $\triangleleft \triangleright$ ESC/? Ŷ RCD MENU DISP →FUNC UMENU FEED CH UP Seven keys are available. For all keys except RCD, functions marked above the keys are enabled when setting functions or when the FUNC key or the DISP MENU key is pressed. <While setting functions, when the FUNC key/DISP MENU key is pressed> CHARACTER Key: Changes the character type when entering a character. Press this key while holding down the SHIFT key to switch the character type in reverse order. UP/DOWN Key: Switches the setup item or the value. Press this key while holding down the SHIFT key to switch the setup item or the value in reverse order. LEFT/RIGHT Key: Moves the cursor to the right when entering a value or character. Press this key while holding down the SHIFT key to move the cursor to the left ... ESC Key: Cancels the operation. When pressed with the SHIFT key, the display of the comment on the setting turns ON/OFF. SHIFT Key: Used with the $\nabla \triangle$ key, $\triangleleft \triangleright$ key, or the CHARACTER key. ENTER Key: Confirms the setup item or value. CHARACTER ESC/? SHIFT ÷ MENU DISP OFUNC MENU FEED RCD CHUP <During normal operation> CH UP key Switches the displayed channel. (when manual switching is specified) **FEED key** Feeds the chart paper. **DISP MENU key** Hold this key down for 3 seconds to switch to the data display setup screen. Hold this key down for 3 seconds also to exit from the data display setup screen. FUNC kev Used when executing manual printout, message printout, etc. **DISP** key Switches the screen in the main display. MENU kev Hold this key down for 3 seconds to enter Setting mode. Hold this key down for 3 seconds also to exit from Setting mode. **RCD** key Starts/stops recording.


#### Note.

This manual denotes the operation of pressing a key while holding down the **SHIFT** key as **SHIFT** + the other key (for example: **SHIFT** +  $\triangleleft \triangleright$  key).

## **Rear Panel**



## Portable Type (/H5x Option)



# 3.2 Installing or Replacing the Chart Paper


# CAUTION

- Do not install or remove the chart cassette with the chart paper guide open. This may damage the stopper.
- Continuing to record or print without the chart paper on the dot model can cause damage to the chart cassette platen (the cylindrical section that holds the paper during the recording operation). Be sure to replace the chart paper ahead of time.
- When attaching the chart cassette, push it in until you hear the left and right stoppers click into place. Recordings will be inaccurate if the chart cassette is not fixed in place with stoppers.

### Loading the Chart Paper


1. Open the door.

If recording is in progress, press the  $\widehat{\mathbf{RCD}}$  key to stop the recording.




2. Remove the chart cassette.

Gently pressing the left and right stoppers inward. The bottom section of the chart cassette comes out. Gently lift the chart cassette and pull it out from the recorder case.




**3.** Open the chart holder and the chart paper guide.




4. Load the chart paper.

Riffle the chart thoroughly before loading.

Make sure that the sprocket teeth of the chart drives are properly engaged in the chart paper perforations. Make sure not to load the chart paper backwards.




5. Close the chart holder and close the chart paper guide.



#### 3.2 Installing or Replacing the Chart Paper

- 6. Replace the chart cassette back into the recorder case.
  - Align the left and right projections of the sprocket section with the guide grooves of the recorder and press the entire chart cassette into the recorder case. Push in the chart cassette until it is fixed in place with stoppers.



# Feeding the Chart Paper

7. Press the FEED key to assure that the chart moves two or more folds smoothly into the chart receiver.

If it moves unsteadily, do the installing procedure again.


# 3.3 Installing/Replacing Felt Pens or Plotter Pen (Pen Model)

# CAUTION

- Do not press or pinch the felt tip to prevent deformation.
- Do not move the penholder left or right by force to protect the driving mechanism.
- Make sure to remove the pen cap before installation.
- Use pen caps of the same ink color. If a pen cap of a different ink color is used on the pen, the remaining ink in the cap may be absorbed through the pen tip, and the ink may change its color.

# Replacing Felt Pens

- Open the door.
   If recording is in progress, press the RCD key to stop the recording.
- Open the display and key panel section. You can open the display and key panel section by holding the tab at the lower left and pulling it toward you.
- 3. Hold the felt pen cartridge and pull it out from the pen holder. If the pen (pen holder) is at a position that is not easily accessible, see "When the Pen (Pen Holder) Is at a Position That Is Not Easily Accessible" on the next page.
- **4.** Remove the cap from the new felt pen and insert the pen firmly into the pen holder.



When the Pen (Pen Holder) Is at a Position That Is Not Easily Accessible If the pen (pen holder) is at a position that is not easily accessible, carry out the procedure below to move it near the center position.

- 1. Turn ON the power switch and press the OFUNC key.
- 2. Press the  $\triangleleft \triangleright (\overline{\text{pisp}})$  key several times to display the **Pen exchange** screen.



Press the <≓ (EHUP) key.</li>
 The pen (pen holder) moves near the center position, and the Pen exchange = End appears.


#### Note \_

When the pen moves, a line is drawn on the chart paper.

- 4. Replace the pen.
- Press the <⊢ (CHUP) key. The screen returns to the data display screen.

# **Replacing the Plotter Pen**

- **1.** Open the door.
  - If recording is in progress, press the **(RCD)** key to stop the recording.
- **2.** Open the display and key panel section.
- 3. Hold the plotter pen cartridge and pull it out from the pen holder.
- **4.** Remove the cap from the new plotter pen and insert the pen firmly into the pen holder.



# 3.4 Installing/Replacing the Ribbon Cassette (Dot Model)

# CAUTION

- Improper cassette insertion may cause the color to change or damage the ribbon.
- Do not apply upward force to the printer carriage. If you do, the carriage position may be offset, and the recorder may not print correctly.
- 1. Open the door.

If recording is in progress, press the RCD key to stop the recording.


- 2. Press the OFUNC key.
- **3.** Press the  $\nabla \Delta$  (DISP) key several times to display **R. exchange**.



- Press the <⊢ (CHUP) key. The printer carriage moves near the center position, and R. exchange = End is displayed.
- Open the display and key panel section. You can open the display and key panel section by holding the tab at the lower left and pulling it toward you.


#### Note .

- Moving of the printer carriage using keys is a function available on version 1.11 or later.
- If the recorder is OFF, pinch the printer carriage and move it near the center position.




6. Remove the ribbon cassette.

Pull the left-hand part of the ribbon cassette so that the cassette holder tab disengages, and pull the ribbon cassette out from the recorder case.



7. Install a new ribbon cassette.

First, insert the right-hand part and then the left-hand part into the cassette holder. Check that the cassette is properly engaged with the cassette holder tab. If inserting the ribbon cassette is difficult, turn the ribbon feeding knob in the direction of the arrow to align the ribbon feeding shaft of the cassette with the ribbon feeding shaft hole of the holder.



- **8.** Turn the ribbon feeding knob in the direction of the arrow a half turn or more to check that the ribbon is feeding properly. If the ribbon is loose, turn the knob in the direction of the arrow to tighten it.
- 9. Return the display and key panel section to its original position, and press the <⊨ ((CH UP)) key.

The screen returns to the data display screen.

# 3.5 Starting/Stopping the Recording

This section describes the procedures for starting/stopping the chart feed and checking the recorded result.

# Procedure

## Starting the Recording

Press the **RCD** key to start the chart feed. The status display shows the word "RECORD."

#### Note .

For models with the FAIL/chart end detection and output function (/F1 option), the chart feed will not start even when pressing the RCD key if the chart paper is empty or almost out. Insert new chart paper before pressing the RCD key.

#### Stopping the Recording


While recording is in progress, press the **RCD** key to stop the chart feed. The word "RECORD" on the status display clears.

#### Feeding the Chart Paper

The chart paper is fed while the FEED key is held down.

#### Viewing the Recorded Results

Pull the front cover tab of the chart cassette to open the front cover. The recorded chart paper can be pulled out for viewing.



. . . . . . .

<Related Topics> Changing the chart speed: Section 5.4

# 3.6 Switching the Display Screen

This section describes the procedure for switching the display screen. To change the displayed content, see chapter 8.

### Procedure

#### Switching the Display Screen

The display screen switches each time the **DISP** key is pressed. Screen 01 through 15 are switched in order. Screens that are set to "Skip" are skipped.

#### **Channel Auto Switching**

On screens that show the measured values and computed values, the displayed channel is automatically switched in ascending order. The switching interval can be set to 1 s, 2 s, 3 s, 4 s, or 5 s.

Measurement channels set to Skip and computation channels set to OFF are not displayed.

# Switching the Displayed Channel Using Keys

If Manual switching is specified, the channel switches each time the *CHUP* key is pressed in ascending order. All channels are displayed in order.

#### Note .

The operation is different between auto channel switching and manual switching using keys on the 2-channel digital display.

03 04

02 03

During auto switching	01 02	
0 0	01 02	
When switching using keys	02	

05 06

03 04

#### **Printing Measured Values (Manual Printout)** 3.7

The measured values of all channels are printed.

#### Procedure

#### **Starting the Manual Printout**

- 1. Press the wFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Print out** and then press the  $\triangleleft$  key.

Func=Print out

3. Press the <-> key with ManualStart shown on the screen. Manual printout starts. The screen returns to the data display screen.

Print=<mark>ManualStart</mark>

#### Note \_

- When manual printout is executed, trend recording is suspended. However, the recorder continues the measurement and alarm detection (in the background).
- · When manual printout is complete, trend recording resumes.
- If an alarm occurs during the manual printout, the alarm is printed after the trend recording resumes.

#### **Aborting the Manual Printout**

The following procedure is for aborting the manual printout that is in progress.

- 1. Press the wFUNC key.
- **2.** Press the  $\nabla \Delta$  key to select **Print out** and then press the  $\triangleleft$  key.
- 3. Press the <- key with Manual Stop shown on the screen. Manual printout stops. The screen returns to the data display screen.

When the  $\triangleleft \triangleright$  key or  $\bigtriangledown \triangle$  key is pressed while holding down the **SHIFT** key, the operation is reversed as when the respective key is pressed by itself.

Print=Manual Stop

# 3.8 Printing the Recorder Settings

This section explains the procedure for printing the recorder settings. There are two sets of settings that can be printed: List and Setup.

List: Prints the settings of Setting mode (input range for each channel, etc.) Setup: Prints the settings of Basic Setting mode

#### Note\_

- · The printout takes several minutes to tens of minutes to complete.
- When this printout is executed, trend recording is suspended. However, the recorder continues the measurement and alarm detection (in the background).
- When the printout is complete, trend recording resumes.
- · If an alarm occurs during the printout, the alarm is printed after the trend recording resumes.

#### Procedure

#### **Starting the List Printout**

- 1. Press the OFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Print out** and then press the  $\triangleleft$  key.
- Press the \sigma A key to display List Start and then press the <- key. The List printout starts. The screen returns to the data display screen.

Print=<mark>List Start</mark>

#### Aborting the List Printout

- 1. Press the OFUNC key.
- **2.** Press the  $\nabla \Delta$  key to select **Print out** and then press the  $\triangleleft$  key.
- Press the \u2275 A key to display List Stop and then press the <
   <p>Press the \u2275 A key.

   The List printout stops. The screen returns to the data display screen.

Print=<mark>List Stop</mark>

#### **Starting the Setup Printout**

- 1. Press the OFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Print out** and then press the  $\triangleleft$  key.
- Press the \u2272\u0211 key to display Setup Start and then press the <
   <p>key.
   The Setup printout starts. The screen returns to the data display screen.

Print=<mark>Setup Start</mark>

#### **Aborting the Setup Printout**

- 1. Press the OFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Print out** and then press the  $\triangleleft$  key.

Print=<mark>Setup Stop</mark>

# 3.9 Clearing the Alarm Printout Buffer


Alarm information waiting to be printed is temporarily stored in the buffer memory. This operation clears all of the alarm information in the buffer. This function can be used to prevent unneeded alarm printouts from being executed.

# Procedure

- 1. Press the **JUNC** key.
- 2. Press the  $\nabla \Delta$  key to select **Buffer clear** and then press the  $\prec \exists$  key.

Func=<mark>Buffer clear</mark>

 Press the \\rightarrow \Lefta key to select Alarm and then press the \\Press key. The data in the alarm printout buffer is cleared. The screen returns to the data display screen.



# 3.10 Printing Messages

This section explains the procedure for printing the preset character strings. For the procedure of setting the character strings, see section 6.8.

- Note\_
  - Messages can be printed only during trend recording. However, regardless of whether trend recording is ON or OFF, messages waiting to be printed are temporarily stored in the buffer memory.
- Message printouts are not performed when the chart speed is greater than or equal to 1600 mm/h and 101 mm/h on the pen model and dot model, respectively.

#### Procedure

#### **Printing a Message**

- 1. Press the OFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Message** and then press the  $\triangleleft$  key.



 Press the \scale A key to select message number and then press the <⊨ key. The message printout starts. The screen returns to the data display screen.

#### **Clearing the Message Printout Buffer**

Messages waiting to be printed are temporarily stored in the buffer memory. This operation clears the messages in the buffer.

- 1. Press the wFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Buffer clear** and then press the  $\triangleleft$  key.
- Press the \\IDCA key to select Message and then press the \(\IDCA key.
   The messages in the printout buffer are cleared. The screen returns to the data display screen.

Buf.clear=<mark>Message</mark>

# 3.11 Resetting the Report Data of the Periodic Printout

This operation resets the past report data when the recorder is configured to print the report data (the average, the minimum, the maximum, or the sum) of the measured values in periodic printout.

# Procedure

# **Resetting the Report Data**

- 1. Press the OFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Periodic** and then press the  $\triangleleft$  key.

Func=<mark>Periodic</mark>

 Press the \u2275 A key to select Reset and then press the <⊢ key. The report data is reset, and the calculation of the report data starts again from that point. The screen returns to the data display screen.

Log data=<mark>Reset</mark>

**3** Names of Parts and Run Operations

# 3.12 Releasing the Alarm Output (Alarm ACK Operation)

This operation releases the alarm indication or relay output (/A1, /A2, or /A3 option) when the alarm indication or output relay is set to hold operation.

# Procedure

# **Releasing the Alarm Output**

- 1. Press the OFUNC key.
- Press the <> key with Alarm ACK shown on the screen. The alarm indication or relay output is released. The screen returns to the data display screen.

Func=Alarm ACK

# Explanation

# **Alarm Output Relay Operation**

- · When the alarm is released
  - The alarm output is released when the alarm ACK operation is carried out.
- · When an alarm is occurring

The alarm output is held even after the alarm ACK operation. If the alarm ACK operation is carried out again after the alarm is released, the alarm output is released.

# Indication (Status Display)


Blinks when an alarm occurs.

• When the alarm is released

The alarm indication turns OFF when the alarm ACK operation is carried out.

When an alarm is occurring

The alarm indication turns ON after the alarm ACK operation. The alarm indication turns OFF when the alarm is released.



# 3.13 Activating/Releasing the Key Lock

When the recorder is configured to use the key lock function, this operation activates or releases the key lock.

Note \_

Key lock does not apply to the **DISP** and **CHUP** keys.

#### Procedure

#### Activating the Key Lock

- 1. Press the OFUNC key.
- Press the \\\\Delta \Lefta key to select Keylock and then press the \\\=' key. The key lock is activated. The screen returns to the data display screen.

Func=<mark>Keylock</mark>

#### **Releasing the Key Lock**

# Note -

A password is required to release the key lock.

- 1. Press the wFUNC key.
- 2. Press the  $\nabla \Delta$  key to select **Keylock** and then press the  $\triangleleft$  key.
- **3.** Enter the password for releasing the key lock. The password values are shown with asterisks.

Press the  $\nabla \Delta$  key to increment the value.

Press the **SHIFT** +  $\nabla \Delta$  key to decrement the value.

Press the  $\triangleleft \triangleright$  key to move the cursor to the right.

Press **SHIFT** +  $\triangleleft$   $\triangleright$  key to move the cursor to the left.

Password=	
_	

 Press the <⊨ key. The key lock is released. The screen returns to the data display screen.

<Related Topics> Changing the password: Section 7.10

When the  $\triangleleft \triangleright$  key or  $\nabla \triangle$  key is pressed while holding down the **SHIFT** key, the operation is reversed as when the respective key is pressed by itself.

# 4.1 Run Modes

The recorder has three run modes.

#### **Operation Mode**


This mode is used for normal recording operation. The recorder enters this mode when the power is turned ON. The operations that can be carried out in this mode are described in chapter 3. The details on the data display setup screen are explained in chapter 8.

# **Setting Mode**

This mode is used to set the input range, alarms, chart speed, and other parameters. These settings can be changed while recording is in progress. However, the input range of measurement channels and the computing equation, unit, constant, and TLOG setting of computation channels cannot be changed while computation (/M1 option) is in progress. The operations that can be carried out in this mode are described in chapter 5 and 6.

#### **Basic Setting Mode**

This mode is used to set the basic specifications of the recorder such as the thermocouple burnout detection function and the alarm output relay operation. This mode cannot be entered while the recorder is recording or while computation is in progress on the computation function (/M1 option). Measurement, recording, and alarm detection cannot be carried out in this mode. The operations that can be carried out in this mode are described in chapter 7.



4

# 4.2 Key Operations

This section describes basic operations on the panel keys to change various settings. Functions are set in Setting mode or Basic Setting mode.

# **Entering Setting Mode**

Hold down the MENU key for 3 seconds.

The Setting mode display appears. The top and bottom lines are the setup item and comment, respectively.

The section that is blinking in the setup item that you change. In this manual, the section that you change appears shaded.

Setup item> Set=Range	The item to be controlled blinks.
<b>Comment</b> $\rightarrow$ Input range and	

The panel keys are set to the functions marked above the keys.

(	CHARACTER	$\nabla \Delta$	$\triangleleft \triangleright$	ESC/?	SHIFT	Ą
RCD	MENU	DISP	<b>⊸</b> FUNC	<b>U</b> MENU	FEED	CHUP

#### Exiting from Setting Mode (Returning to Operation Mode)

Hold down the **MENU** key for 3 seconds. The screen returns to operation mode.

# **Entering Basic Setting Mode**

Basic Setting mode is entered from Setting mode.

Hold down the **MENU** key for 3 seconds to enter Setting mode. Next, hold down both the  $\nabla \Delta$  (**DISP**) key and the  $\triangleleft \triangleright$  (**FINC**) key for 3 seconds.

The Basic Setting mode display appears. The top and bottom lines are the setup item and comment, respectively.

The section that is blinking in the setup item that you change. In this manual, the section that you change appears shaded.



#### Exiting from Basic Setting Mode (Returning to Operation Mode)

This operation is used to return to Operation mode after changing the settings in Basic Setting mode.

Press the ESC key several times to return to the Basic= screen.

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. The setup save screen appears.

Basic	c= <mark>End</mark>	
Save	Settings	

Press the  $\nabla\Delta$  key to select **Store** and then press the  $\prec \exists$  key. The setting is applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the setting is discarded, and the screen returns to Operation mode.




# Changing the Settings

Note \_\_\_\_

The comment line shows useful information such as a description of the setup item and the range of selectable values. Read the comment and change the items as necessary.

The selected item change each time you press the  $\nabla \Delta$  key. The selected item changes in reverse order if you press the  $\nabla \Delta$  key while holding down the **SHIFT** key.



This manual denotes the operation of pressing a key while holding down the **SHIFT** key as **SHIFT** + the other key (for example: **SHIFT** +  $\nabla \Delta$  key).

After you make a selection, press the <- key. The next screen appears. When the **Setting complete** screen appears, the changed item is applied.

01-01 0	Channel
Settin	g complete


# Using the ESC Key

If you press the **ESC** (MENU) key, the operation is cancelled, and the display returns to a higher level menu. In other words, if you do not show the Setting Complete screen, the changes you made up to that point are discarded.

Press the **ESC** (MENU) key while holding down the **SHIFT** (FEED) key to show or hide the comment that is displayed at the bottom half of the screen.

# Entering Values


Use the  $\triangleleft \triangleright$  key or **SHIFT** +  $\triangleleft \triangleright$  key to move the cursor. Use the  $\neg \triangle$  key or **SHIFT** +  $\neg \triangle$  key to change a digit value. You repeat these steps to enter the value.




When you press the <>> key, the change is applied and the next screen is displayed.

#### **Entering Characters**

Use the  $\triangleleft \triangleright$  key or **SHIFT** +  $\triangleleft \triangleright$  key to move the cursor.




Use the **CHARACTER** key or **SHIFT** + **CHARACTER** key to select the character type. Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select a character. You repeat these steps to set the character string.



The character types change in the following order: uppercase alphabet (**A-Z**), lowercase alphabet (**a-z**), numbers (**0-9**), and symbols (%-.).

A-	Z A to Z, and space
	a to z, and space
0-9	0 to 9, and space
%	. $\%, \#, \circ, @, +, -, *, /, (, ), \mu, \Omega, ^2, ^3, ., and space$




When you press the <- key, the change is applied and the next screen is displayed.

#### **Inserting Characters**

Press the  $\triangleleft \triangleright$  key or **SHIFT** +  $\triangleleft \triangleright$  key to move the cursor to the position where the character is to be inserted.

Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Ins DISP** and then press the  $\nabla \Delta$  key. A space for one character is inserted. Enter the character.



#### **Deleting a Character**

Use the  $\triangleleft \triangleright$  key or **SHIFT** +  $\triangleleft \triangleright$  key to move the cursor to the character to be deleted. Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Del DISP** and then press the  $\neg \Delta$  key. The character is deleted.

#### **Deleting an Entire Character String**

Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Clear DISP** and then press the  $\nabla \Delta$  key. The entire character string is deleted.

# **Copying & Pasting a Character String**

Show the copy source character string.


Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Copy DISP** and then press the  $\nabla \Delta$  key. The character string is saved to the memory.

Show the copy destination.

Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Paste DISP** and then press the  $\nabla \Delta$  key. The character string is pasted.

# **Operation Menus Using the FUNC Key (Operation Mode)**

Below are the items that are operated using the **DFUNC** key. Information indicated inside the parentheses is references.



# Alarm ACK

Alarm output release operation. This operation is valid only when the alarm indication or relay output is set to hold operation.

# Math (Models with the Computation Function (/M1 Option))

Starts/stops the computation.

### Print out

Starts/Stops the manual printout or setting printout (List or Setup).

# Message

Prints messages.

# **Buffer clear**

Clears the data waiting to be printed in the alarm printout buffer or the message printout buffer.

# Keylock

Activates or releases the key lock. This operation is possible only when the use of the key lock function is enabled.

# Periodic

Resets the computed value when printing of the report data (average, etc.) is specified in periodic printout.

4

Recorder version: 1.31

### Pen exchange (Pen Model)


Moves the recording pen to a position that is easily accessible for replacement on the pen model.

#### R. exchange (Dot Model)

Moves the printer carriage near the center position when replacing the ribbon cassette on the dot model.

# Menu Structure of Setting Mode


Below are the setup items in Setting mode. Information indicated inside the parentheses is references.



4

#### Menu Structure of Basic Setting Mode

Below are the setup items in Basic Setting mode. Information indicated inside the parentheses is references.



# Setup Items in Setting Mode and Their Default Values (Recorder version: 1.31)

Items with an asterisk on the left are not displayed in the default condition. To display

these items, settings must be changed in Basic Setting mode.

Setup Item	Pen/Dot	Selectable Range or Selections	Default Value
Range > CH	-	01 to 06	01
Range > Mode	-	Volt/TC/RTD/1-5V/Scale/Delta/DI/SQRT/Skip	Volt
Range > Mode > Range	-	20mV/60mV/200mV/2V/6V/20V/50V/1-5V/	2V
		R/S/B/K/E/J/T/N/W/L/U/WRe/Pt/JPt/Level/Cont/	
		(Slections for /N1 and /N3 options)	
*Bias > CH	-	01 to 06	01
*Bias > Bias	-	On/Off	Off
*Bias > Bias	-	±10% of the span of the measurable range or the	-
		scaling span	
Calibration (/CC1 option)		04 1- 00	04
Calibration > CH	-	01 to 06	01
Calibration > Calibration	-	On/Off	Off
Calibration > datums	-	Within the range	-
Calibration > revise	-	Within the range (correction point + correction value for revise value)	-
Calibration > Decision		Yes/No	Yes
Alarm > CH	-	01 to 06	01
Alarm > Level	_	1/2/3/4	1
Alarm > Alarm	_	On/Off	Off
Alarm > Type	_	H/L/h///R/r (*/T/t)	H
Alarm > Value	_	Depends on the alarm type.	-
Alarm > Relay	_	On/Off	Off
Alarm > Relay No.	_	101 to 106	101
Unit > CH	_	01 to 06	01
Unit > Unit	_	6 characters or less	Blank
	Pen Model	82 types (pen model)	20 mm/h
		1 to 1500 mm/h (dot model)	20 mm/h
Clock	-	Date/Time	-
Aux > Trend	Dot Model		Auto
Aux > Zone > CH	-	01 to 06	01
Aux > Zone > Left, Right	-	Within the recording span range (mm)	Left: 0, Right: 100
*Aux > Partial > CH	-	01 to 06	01
*Aux > Partial > Partial	-	On/Off	Off
*Aux > Partial > Expand	-	1 to 99%	50
*Aux > Partial > Boundary	-	Within the recording span range	-
Aux > Print out > CH	-	01 to 06	01
Aux > Print out > Trend	Dot Model	On/Off	On
Aux > Print out > Periodic	-	On/Off	On
Aux > Tag > CH	-	01 to 06	01
Aux > Tag > Tag	-	7 characters or less	1 to 6
Aux > Message > Message No.	-	1 to 5	1
Aux > Message > (Message)	-	16 characters or less	Blank
Aux > Chart2	Pen Model	82 types (pen model)	20 mm/h
	Dot Model	1 to 1500 mm/h (dot model)	20 mm/h
*Aux > Moving_AVE > CH	Dot Model	01 to 06	01
*Aux > Moving_AVE > No. of samples	Dot Model	Off, 2 to 16	Off
*Aux > Filter > CH	Pen Model	01 to 06	01
*Aux > Filter > Resp. Time	Pen Model	2s/5s/10s	Off
*Aux > Alm delay T > CH	-	01 to 06	01
*Aux > Alm delay T > Duration	-	0 to 3600s	10s
Aux > Brightness > Display	-	1/2/3/4/5/6/7/8	4
Aux > Brightness > Light	-	1/2/3/4	2
Aux > DST	-	Not/Use	Not
Aux > DST > Start month	-	Apr/May/Jun/Jul/Aug/Sep/Oct/Nov/Dec/Jan/Feb/Mar	Apr
Aux > DST > Strt day	-	1st-Sun//Last-Mon	1st-Sun
Aux > DST > Start time	-	0:00 to 23:00	0:00
Aux > DST > End month	-	Apr/May/Jun/Jul/Aug/Sep/Oct/Nov/Dec/Jan/Feb/Mar	Apr
Aux > DST > End day	-	1st-Sun//Last-Mon	Last-Mon
Aux > DST > End time		0:00 to 23:00	0:00

Setup Item	Pen/Dot	Selectable Range or Selections	Default Value
Math (/M1 option)		-	
Math > Formula > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Formula > Mode	-	On/Off	Off
Math > Formula > f	-	120 characters or less	01
Math > Unit > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Unit > Unit	-	6 characters or less	Blank
Math > Constant > No.	-	K01 to K30	K01
Math > Alarm > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Alarm > Level	-	1/2/3/4	1
Math > Alarm > Alarm	-	On/Off	Off
Math > Alarm > Type	-	H/L (*/T/t)	Н
Math > Alarm > Value	-	-99999999 to 99999999 excluding the decimal	-
Math > Alarm > Relay	-	On/Off	Off
Math > Alarm > Relay No.	-	101 to 106	101
Math > TLOG > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > TLOG > Timer No.	-	Periodic/1/2	Periodic
Math > TLOG > SUM scale	-	Off, /s, /min, /h, /day	Off
Math > Aux > Zone > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Aux > Zone > Left, Right	-	Within the recording span range (mm)	Left: 0, Right: 100
Math > Aux > Partial > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Aux > Partial > Partial	-	On/Off	Off
Math > Aux > Partial > Expand	-	1 to 99%	50
Math > Aux > Partial > Bound	-	Within the recording span range	-
Math > Aux > Print out > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Vath > Aux > Print out > Trend	Dot Model		On
Math > Aux > Print out > Periodic	-	On/Off	On
Math > Aux > Tag > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Aux > Tag > Tag	-	7 characters or less	A to P
Math > Aux > Alm delay T > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
*Math > Aux > Alm delay T > Duration	_	0 to 3600s	10s
Batch (/BT1 option)			100
Batch > Batch No.	_	26 characters or less	Blank
Batch > Lot No.	_	0000-9999 or 000000-999999	0000 or 000000
Batch > Detail > Start > Comment > Line No.	_	1/2/3/4/5	1
Batch > Detail > Start > Comment > (Comment)	-	32 characters or less	Blank
Batch > Detail > Start > Print > Batch name	_	On/Off	On
Batch > Detail > Start > Print > Chart speed	_	On/Off	On
Batch > Detail > Start > Print > Clock	_	On/Off	On
Batch > Detail > Start > Action > Feed	_	0 to 50 mm	0 mm
Batch > Detail > End > Comment > Line No.		1/2/3/4/5	1
Batch > Detail > End > Comment > (Comment)	-	32 characters or less	Blank
Batch > Detail > End > Print > Batch name	_	On/Off	On
Batch > Detail > End > Print > Chart speed		On/Off	On
Batch > Detail > End > Print > Clock	-	On/Off	On
	-		
Batch > Detail > End > Action > Feed Batch > Detail > End > Action > Auto inc.	-	0 to 50 mm On/Off	0 mm On
	- Pen Model		Off
Batch > Detail > End > Action > POC output			
*Batch > Detail > End > Action > POC speed	Fen wouel	C.Speed/450 mm h	C.Speed
Batch > Detail > Start2 Same as Start			
*Batch > Detail > End2 Same as End		1/2/2/4/5	1
Batch > MSG format > Message No.	-	1/2/3/4/5 25 sharastara ar laga	1
*Batch > MSG format > Message No. > (MSG format)	-	35 characters or less	H:M L16

Setup Items in Basic Setting Mode and Their Default Values (Recorder version: 1.31)

Setup Item	Pen/Dot	Selectable Range or Selections	Default Value
Alarm > Diagnosis	-	On/Off	Off
Alarm > Reflash	-	On/Off	Off
Alarm > AND	-	None/I01/I01-I02/I01-I03/I01-I04/I01-I05/I01-I06	None
Alarm > Act	-	Energize/De_energize	Energize
Alarm > Behavior	-	Nonhold/Hold	Nonhold
Alarm > Indicator	-	Nonhold/Hold	Nonhold
Alarm > Increase	-	01 to 15	01
Alarm > Decrease	-	01 to 15	01
Alarm > Hysteresis	-	Off/0.1% to 1.0%	0.5%
Alarm > M_Hysteresis	-	Off/0.1% to 1.0%	Off
A/D > Integrate	Dot Model	Auto/50Hz/60Hz/100ms	Auto
	Pen Model	Auto/50Hz/60Hz	Auto
Burnout > CH	-	01 to 06	01
Burnout > Burnout	-	Off/Up/Down	Off
RJC > CH	-	01 to 06	01
RJC > RJC	-	Internal/External	Internal
RJC > RJC > Volt	-	–20000 to 20000 μV	0 μV
Color > Channel	Dot Model		01
Color > Color	Dot Model	Purple/Red/Green/Blue/Brown/Black	01: Purple, 02: Red,
			03: Green, 04: Blue,
			05: Brown, 06: Black
POC > POC	Pen Model		Off
Print > CH/Tag	-	CH/Tag	СН
Print > Channel	Dot Model	On/Off	On
Print > Alarm	-	On1/On2/Off	On1
Print > Record On	-	On/Off	Off
Print > Chart speed	-	On/Off	On
Print > Scale	-	On/Off	On
Print > Pen color	Pen Model	On/Off	On
Print1 > Periodic	-	Auto/Manual	Auto
Print1 > Ref. Time	-	Hour 0 to 23 (1 hour steps)	00:00
Print1 > Interval	-	10min/15min/20min/30min/1h/2h/3h/4h/6h/8h/12h/ 24h	1h
Print1 > Mode	-	Inst/Report/Off	Inst
Print2 > CH	-	01 to 06	01
Print2 > Mode	-	AVE/MIX/SUM/MIN/MAX/INST	AVE
Print2 > SUM scale	-	Off, /s, /min, /h, /day	Off
Bar graph > CH	-	01 to 06	01
Bar graph > Graph	-	Normal/Center	Normal
Keylock > Keylock	-	Not/Use	Not
Keylock > Password	-	Numbers and spaces within 4 digits	Blank
Keylock > RCD	-	Free/Lock	Free
Keylock > Feed	-	Free/Lock	Free
Keylock > Menu	-	Free/Lock	Free
Keylock > Disp Menu	-	Free/Lock	Free
Keylock > Alarm ACK	-	Free/Lock	Free
Keylock > Math	-	Free/Lock	Free
Keylock > Print out	-	Free/Lock	Free
Keylock > Message	-	Free/Lock	Free
Keylock > Buffer clear	-	Free/Lock	Free
Keylock > Periodic	-	Free/Lock	Free
Keylock > Pen exchange	Pen Model	Free/Lock	Free
Keylock > R. exchange	Dot Model	Free/Lock	Free
Moving_AVE > Moving_AVE	Dot Model	Not/Use	Not
Filter > Filter	Pen Model		Not
		Not/Use	Not
	-	100.000	
Partial > Partial	-	English/Japanese/German/French	English
Partial > Partial Language > Lang Date format > Type			

Setup Item	Pen/Dot	Selectable Range or Selections	Default Value
Personalize > Add function > Bias	-	Not/Use	Not
Personalize > Add function > SQRT low-cut	-	Not/Use	Use
Personalize > Add function > 1-5V low-cut	-	Not/Use	Not
Personalize > Add function > Alarm delay	-	Not/Use	Not
Personalize > Add function > Calibration	-	Not/Use	Use
Personalize > Time print > Alarm	-	HH:MM, HH:MM:SS, M/D H:M, M/D H:M:S, YMD H:M:S	HH:MM
Personalize > Time print > Message	-	HH:MM, HH:MM:SS, M/D H:M, M/D H:M:S, YMD H:M:S, None	HH:MM
Personalize > Time print > RCD On	-	HH:MM, HH:MM:SS, M/D H:M, M/D H:M:S, YMD H:M:S	HH:MM
Personalize > Time print > C.Speed	-	HH:MM, HH:MM:SS, M/D H:M, M/D H:M:S, YMD H:M:S	HH:MM
Setting initialization			
Initialize > Mode	-	Setup+Set/Set	Setup+Set
Initialize > Mode > Are you sure?	-	No/Yes	No
Remote (/R1 option)			
Remote > Remote No.	-	1/2/3/4/5	1
Remote > Remote No. > No.	-	Record On Off /Chart speed/Time adjust/ Math start stop (/M1)/Math reset (/M1)/ Manual print/Alarm ACK/Message1/Message2/ Message3/Message4/Message5/	Record On/Off
		Priority R_RCD (/BT1)/BatchCMT switch (/BT1)/ None (/M1, /BT1: option)	
Math (/M1 option)			
Math > Timer (TLOG) > Timer No.	-	1/2	1
Math > Timer (TLOG) > Mode	-	Off/Relative/Absolute	Absolute
Math > Timer (TLOG) > Interval (Relative)		10 min to 24 h (1 min steps)	01:00
Math > Timer (TLOG) > Interval (Absolute)	-	10min/12min/15min/20min/30min/1h/2h/3h/4h/6h/ 8h/12h/24h	1h
Math > Timer (TLOG) > Ref. Time	-	Hour 0 to 23 (1 hour steps)	00:00
Math > Timer (TLOG) > Reset	-	On/Off	On
Math > Timer (TLOG) > Print	-	On/Off	On
Math > Color > Channel	Dot Model	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Color > Color	Dot Model	Purple/Red/Green/Blue/Brown/Black	Purple: 0A/0G Red: 0B/0J Green: 0C/0K Blue: 0D/0M Brown: 0E/0N Black: 0F/0P
Math > Output pen > Pen $\leftarrow$ CH	Pen Model	Pen: 1 to 4, Channel: 01 to 04/0A to 0J	1pen: 01, 2pen: 02 3pen: 03, 4pen: 04
Math > Print2 > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Print2 > Mode	-	AVE/MIX/SUM/MIN/MAX/INST	AVE
Math > Print2 > SUM scale	-	Off, /s, /min, /h, /day	Off
Math > Bar graph > CH	-	0A/0B/0C/0D/0E/0F/0G/0J/0K/0M/0N/0P	0A
Math > Bar graph > Graph	-	Normal/Center	Normal
Math > Error data > Error	-	+Over/–Over	+Over
Math > Error data > Over	-	Skip/Limit	Skip
RS-422/485 (/C3 option)			
RS-422/485 > Address	-	1 to 32	1
RS-422/485 > Baud rate	-	1200/2400/4800/9600/19200/38400	9600
RS-422/485 > Data length	-	7/8	8
RS-422/485 > parity	-	Odd/Even/None	Even

Setup Item	Pen/Dot	Selectable Range or Selections	Default Value
Ethernet (/C7 option)			
Ethernet > Host > Host	-	64 characters or less	Blank
Ethernet > Host > Domain	-	64 characters or less	Blank
Ethernet > Local IP > A	-	IP address	0.0.00
Ethernet > Local IP > M	-	IP address (Subnet mask)	0.0.0.0
Ethernet > Local IP > G	-	IP address (Default gateway)	0.0.00
Ethernet > DNS > DNS	-	On/Off	Off
Ethernet > DNS > P	-	IP address (Primary DNS sever)	0.0.0.0
Ethernet > DNS > S	-	IP address (Secondary DNS sever)	0.0.00
Ethernet > DNS > Suffix_P	-	Primary domain suffix	Blank
Ethernet > DNS > Suffix_S	-	Secondary domain suffix	Blank
Ethernet > Login > Login	-	Use/Not	Not
Ethernet > LoginSet > Level	-	Admin/User1 to User6	Admin
Ethernet > LoginSet > Register	-	On/Off	Admin and User1 are On
Ethernet > LoginSet > User	-	16 characters or less	Admin: admin User1 to 6: user1 to user6
Ethernet > LoginSet > Password	-	4 characters or less	Administrator: 0 User1 to 6: 1 to 6
Ethernet > Timeout > Timeout	-	On/Off	Off
Ethernet > Timeout > Duration	-	1 to 120 min	1 min
Ethernet > K. Alive > Keep alive	-	On/Off	On
Calibration (/CC1 option)			
Calibration > CH	-	01 to 06	01
Calibration > Mode	-	Revise Value, Abs. Value	Revise Value
Calibration > Point	-	2 to 16	2
Cust. menu > Cust. menu	-	Not/Use	Not
Cust. menu > Password	-	Numbers and spaces within 4 digits	Blank
Cust. menu > P_Adj	-	On/Off	Off
Select menu > Set mode > Range	-	On/Off	On
Select menu > Set mode > Bias	-	On/Off	On
Select menu > Set mode > Alarm	-	On/Off	On
Select menu > Set mode > Unit	-	On/Off	On
Select menu > Set mode > Chart speed	-	On/Off	On
Select menu > Set mode > Aux	-	On/Off	On
Select menu > Set mode > Calibration	-	On/Off	On
Select menu > Set mode > Math	-	On/Off	On
Select menu > Set mode > Batch name	-	On/Off	On
Select menu > Set mode > Batch detail	-	On/Off	On
Select menu > Function > Manual print	-	On/Off	On
Select menu > Function > Setup list	-	On/Off	On
Select menu > Function > Message	-	On/Off	On
Select menu > Function > Buffer clear	-	On/Off	On
Select menu > Function > Periodic	-	On/Off	On
Batch (/BT1)			~!!
Batch > Batch	-	Not/Use	Not
Batch > Lot No.	-	4/6/Not	4
Batch > Dual comment	-	Not/Use	Not
Batch > MSG format	-	Not/Use	Not
Adjustment		101000	1101
$P_Adj > P_Adj$	Dot Model	Hysteresis/Zero/Full	Hysteresis
	Pen Model	-	Zero
P_Adj > Pen No.	Pen Model		1
P_Adj > Peri No. Store	F ETT WOULEI	1121014	I
End > End		Store/Abort	Store
	-		51016

# 5.1 Setting the Input Range


Input range is set for each measurement channel. Set unused channels to Skip.

- The input range cannot be changed on models with the computation function (/M1 option) when computation is in progress.
- If you change the input range, set the bias, alarm, partial expanded recording, and calibration correction again.

#### Procedure

# TC, RTD, and DC Voltage

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the <- key with Range shown on the screen.
- **3.** Set each item and press the  $\triangleleft$  key.
  - Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>
   If you are done, press the ESC key.
- 5. Hold down the MENU key for 3 seconds to return to Operation mode.



5

# • Selectable Range of Input Range, Span Left, and Span Right

The input range, span left, and span right can be set in the range shown below. Span left and span right cannot be set to the same value.

#### DC voltage (Volt)

-20.00 to 20.00 mV
–60.00 to 60.00 mV
–200.0 to 200.0 mV
-2.000 to 2.000 V
-6.000 to 6.000 V
-20.00 to 20.00 V
–50.00 to 50.00 V

#### Thermocouple (TC)

Range Type	Selectable Span Range (°C)	Selectable Span Range (°F)
R	0.0 to 1760.0°C	32 to 3200°F
S	0.0 to 1760.0°C	32 to 3200°F
В	0.0 to 1820.0°C	32 to 3308°F
К	-200.0 to 1370.0°C	–328 to 2498°F
E	–200.0 to 800.0°C	–328.0 to 1472.0°F
J	–200.0 to 1100.0°C	-328.0 to 2012.0°F
Т	–200.0 to 400.0°C	-328.0 to 752.0°F
Ν	0.0 to 1300.0°C	32 to 2372°F
W	0.0 to 2315.0°C	32 to 4199°F
L	–200.0 to 900.0°C	–328.0 to 1652.0°F
U	–200.0 to 400.0°C	–328.0 to 752.0°F
WRe	0.0 to 2400.0°C	32 to 4352°F

#### RTD

Range Type	Selectable Span Range (°C)	Selectable Span Range (°F)
PT (Pt100)	–200.0 to 600.0°C	–328.0 to 1112.0°F
JPT (JPt100)	–200.0 to 550.0°C	–328.0 to 1022.0°F


#### RTD

Range Type	Selectable Span Range (°C)	Selectable Span Range (°F)
PT (Pt100)	–200.0 to 600.0°C	-328.0 to 1112.0°F
JPT (JPt100)	–200.0 to 550.0°C	-328.0 to 1022.0°F

#### /N1 Option


Selections	Input Type	
Cu1	Cu10 (GE)	
Cu2	Cu10 (L&N)	
Cu3	Cu10 (WEED)	
Cu4	Cu10 (BAILEY)	
Cu5	Cu10: a = 0.00392 at 20°C	
Cu6	Cu10: a = 0.00393 at 20°C	
Cu25	Cu25*: a = 0.00425 at 0°C	

/N3 Option		
Selections	Input Type	Note
PR	PR40-20	Thermo
PLATI	PLATINEL	couple
NiMo	NiNiMo	
W/WRe	W/WRe26	
N2	Type N (AWG14)	
Кр	Kp vs Au7Fe	
Pt4	Pt25	RTD
Pt3	Pt50	
Ni1	Ni100 (SAMA)	
Ni2	Ni100 (DIN)	
Ni3	Ni120	
J263	J263*B	
Cu8	Cu53	
Cu9	Cu100: a = 0.00425 at 0°C	



<Related Topics> Setting the unit: Section 5.3

5



#### Reference Channel

The reference channel must be a channel that is smaller in channel number than the channel being set.

#### • Span Left and Span Right

The range type is set to the same type as the reference channel. The span left and span right can be set in the range shown below. Span left and span right cannot be set to the same value.


Input Type	Range Type	Selectable Span Range	
DC voltage	20 mV	-20.00 to 20.00 mV	
(Volt)	60 mV	-60.00 to 60.00 mV	
	200 mV	–200.0 to 200.0 mV	
	2 V	-2.000 to 2.000 V	
	6 V	–6.000 to 6.000 V	
	20 V	-20.00 to 20.00 V	
	50 V	–50.00 to 50.00 V	
Thermocouple	R	-1760.0 to 1760.0°C	–3168 to 3168°F
(TC)	S	-1760.0 to 1760.0°C	–3168 to 3168°F
	В	-1820.0 to 1820.0°C	–3276 to 3276°F
	K	–1570.0 to 1570.0°C	–2826 to 2826°F
	E	-1000.0 to 1000.0°C	–1800 to 1800°F
	J	-1300.0 to 1300.0°C	-1999.9 to 2340.0°F
	Т	–600.0 to 600.0°C	-1080.0 to 1080.0°F
	Ν	-1300.0 to 1300.0°C	–2340 to 2340°F
	W	–1999.9 to 2315.0°C	-4167 to 4167°F
	L	–1100.0 to 1100.0°C	–1980 to 1980°F
	U	–600.0 to 600.0°C	-1080.0 to 1080.0°F
	WRe	–1999.9 to 2400.0°C	–4320 to 4320°F
RTD	PT (Pt100)	–800.0 to 800.0°C	-1440.0 to 1440.0°F
	JPT (JPt100)	–750.0 to 750.0°C	–1350.0 to 1350.0°F

<b>ON/OFF</b> Input	t		
Set	=Range		
	CH=01-01	]	Set the channel range.
	First channel Last channel		-
	Mode=DI		Select DI.
			Select Cont or Level.
	Range= <mark>Level</mark>		Select Cont of Level.
	Span_L= <mark>0</mark>		Set the left span value.
			<b>•</b> /
	Span_R= <mark>1</mark>	]	Set the right span value.
	01-01 Channel		The new setting takes effect.
ESC/?	-Setting comple	ete	······································

# • Selectable Range Type, Span Left, and Span Right

The range type, span left, and span right can be set in the range shown below. Span left and span right cannot be set to the same value.

Range Type	Selectable Span Values
Level	0: Less than 2.4 V, 1: 2.4 V or higher, within ±6 V
Contact	0: Open, 1: Closed



• Span Left and Span Right Selectable span left range: 0.8 to 1.2 V Selectable span right range: 4.8 to 5.2 V

#### Scale Left, Scale Right, and Decimal Position

Selectable range (mantissa): -20000 to 30000

Example: The value in the range of –100.00 to 350.00 cannot be specified. The mantissa of Scale\_R is 35000, which exceeds the upper limit of 30000. Set in the range of –100.0 to 350.0.

Decimal position: XXXXX, XXXXX, XXXXX, XXXXX, X.XXXX

The decimal position is set using Scale\_L. It cannot be set using Scale\_R. Example: Change 0.00 to 0.0.

Press the  $\triangleleft \triangleright$  key to move the cursor to the last digit of 0.00.

Press the  $\nabla \Delta$  key to change the value to 0.0.

Space —

Make sure that scale left is less than scale right.

• Low-cut


On: Cuts values below 0% of the recording span (set to 0% (scale left value)). Off: Does not apply the low-cut function.

<Related Topics> Setting the unit: Section 5.3 Enabling the low-cut function: Section 7.15

#### Note \_

- The displayable/printable range of scale values is -19999 to 30000 excluding the decimal.
- If the leftmost value of the scale is set to -20000 (excluding the decimal), the value when the low-cut function is applied is displayed as "-Over."

# **Square Root Computation**



#### Description

- Input Type in Which Square Root Computation Can Be Performed Square root computation can be performed when set to DC voltage input.
- Span Left and Span Right Same as the selectable span range of the DC voltage input. Make sure that span left is less than span right.

5

#### 5.1 Setting the Input Range

#### Scale Left, Scale Right, and Decimal Position

Selectable range (mantissa): -20000 to 30000

Example: The value in the range of –100.00 to 350.00 cannot be specified. The mantissa of Scale\_R is 35000, which exceeds the upper limit of 30000. Set in the range of –100.0 to 350.0.

Decimal position: XXXXX, XXXXX, XXXXX, XXXXX, X.XXXX, X.XXXX

The decimal position is set using Scale\_L. It cannot be set using Scale\_R. Example: Change 0.00 to 0.0.

Press the  $\triangleleft \triangleright$  key to move the cursor to the last digit of 0.00.

Press the  $\nabla \Delta$  key to change the value to 0.0 .

Space —

#### Low-cut and Low-cut Point

If low-cut is set to On, set the low-cut point.


Selectable range of the low-cut point: 0.0 to 5.0% of the recording span Values below the low-cut point is set to 0% (scale left value) of the recording span.

#### Note -

- The displayable/printable range of scale values is -19999 to 30000 excluding the decimal.
- If the leftmost value of the scale is set to -20000 (excluding the decimal) and the low-cut value is set to -20000, the value when the low-cut function is applied is displayed as "Over."

<Related Topics> Setting the unit: Section 5.3 Enabling the low-cut function: Section 7.15

# Skip (Unused Channels)



#### Note .

Do not use channels set to skip as a reference channel of delta computations or in computing equations of the computation function (/M1 option).

#### IM 04P01B01-01E

.2	Setting	the Alarm
----	---------	-----------

The alarm is set for each channel. If you change the input range, set the alarm again.

# Procedure

5

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Press the \(\nbox\) A key or SHIFT + \(\nbox\) A key to select Alarm and then press the <\(\mu\) key.</li>
- Set each item and press the <⊨ key.</li>
  Use the \\$\sigma \\$ key or SHIFT + \\$\sigma \\$ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>
   If you are done, press the ESC key.
- 5. Hold down the **MENU** key for 3 seconds to return to Operation mode.

Set= <mark>Alarm</mark>		
CH= <mark>01</mark> -01		Set the channel range.
First channel Last channel		
Level= <mark>1</mark>		Select the level number between 1 and 4.
Alarm= <mark>Off</mark>		Select On to set the alarm. When set to On, the settings below can
		be entered.
Type= <mark>H</mark>		Select the alarm type.
Value= 1.000		Select the value used to turn On the alarm.
Relay= <mark>Off</mark>		Turn relay On when outputting alarms on the relay. This setting is valid only on
		models with the /A1, /A2, or /A3 option.
Relay_No.=I01		Specify the alarm relay No.
		The new patting takes affect
ESC?? Setting complet	1 :e	The new setting takes effect.

5

## Explanation

#### **Channel Range**

The only case when an alarm can be set on multiple channels simultaneously is when the channels are set to the same range type (for example channel 01 and 02 are set to 2 V range). For channels on which scaling is set, the channels must be set to the same range type, same span values, and same scaling values.


# Alarm Type

Symbol	Name	Note
Н	High limit alarm	
L	Low limit alarm	
h	Difference high limit alarm	Can be specified on channels set to delta computation.
l	Difference low limit alarm	Can be specified on channels set to delta computation.
R	High limit on rate-of-change alarm	
r	Low limit on rate-of-change alarm	
Т	Delay high limit alarm*	
t	Delay low limit alarm*	

Selectable only when the alarm delay function is enabled. See section 7.15.

#### Note .

On channels set to delta computation, alarms can be detected on the values illustrated in the figure below.



If high limit on rate-of-change alarm or low limit on rate-of-change alarm is specified, set the interval over which the rate-of-change is calculated.

If delay high limit alarm or delay low limit alarm is specified, set the delay time.

<Related Topics> Setting the interval of the high limit on rate-of-change alarm or low limit on rate-of-change alarm: Section 7.1

Setting the delay time of delay high limit alarm or delay low limit alarm: Section 6.10

Enabling the alarm delay function: Section 7.15

Setting the alarm hysteresis: Section 7.1

# Alarm Value

High Limit Alarm/Low Limit Alarm and Delay High Limit Alarm/Delay Low Limit Alarm

The following values can be specified.

- For DC voltage, TC, and RTD input: Values within the measurable range in the specified range (example: -2.000 to 2.000 V for the 2 V range).
- For ON/OFF input (DI): 0 or 1.
- For linear scaling (1-5V, scaling, and square root): A value within –5 to 105% of the scaling span (version 1.11 or later) except within the range of –20000 to 30000 (excluding the decimal point).

#### Note \_

For channels whose the leftmost value of the scale is set to -20000 (excluding the decimal), the alarm value of -20000 is invalid. Set a value that is greater than or equal -19999.

- Difference High Limit Alarm/Difference Low Limit Alarm Values in the measurable range can be specified. Measurable range refers to "Selectable Span Range" in the table on page 5-4.
- High Limit on Rate-of-Change Alarm/Low Limit on Rate-of-Change Alarm A value greater than or equal to 1 digit can be specified. For example, 1 digit corresponds 0.001 for the 2 V range (measurable range: –2.000 to 2.000 V). The maximum value that can be specified is the width of the measurable range (4.000 V for 2 V range).

For ON/OFF input, only "1" can be specified.

#### Relay No.

The selectable relay numbers are listed below.

I01 and I02 on the /A1 option


- 101, 102, 103, and 104 on the /A2 option
- 101, 102, 103, 104, 105, and 106 on the /A3 option

# 5.3 Setting the Unit on Scaled Channels

Units are set on channels whose input range is set to Scaling, 1-5V, or SQRT.

#### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Unit and then press the  $\triangleleft$  key.
- Set each item and press the <→ key.</li>
  Use the \(\nabla \Leq key or \) SHIFT + \(\nabla \Leq key to select values.\)
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 5. Hold down the MENU key for 3 seconds to return to Operation mode.



# Explanation

# **Characters That Can Be Used for Units**

A unit is set using up to six characters. The available characters are as follows:


Alphabet, numbers, symbols (%, #, °, @, +, –, \*, /, (, ),  $\mu$ ,  $\Omega$ , <sup>2</sup>, <sup>3</sup>, .), and space

# 5.4 Changing the Chart Speed

This section explains the details of changing the chart speed.

# Procedure

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- Press the \sigma A key or SHIFT + \sigma A key to select Chart and then press the <⊨ key.</li>
- 3. Set the chart speed and press the <≓ key.</li>
  Use the \\$\sigma \\$ key or SHIFT + \\$\sigma \\$ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊨ key.</li>
   If you are done, press the ESC key.
- 5. Hold down the (MENU) key for 3 seconds to return to Operation mode.



# **Explanation**

# **Chart Speed**

## Pen Model

The chart speed can be selected from 82 settings shown below. Chart speed on the pen model (unit: mm/h)

5	6	8	9	10	12	15	16	18	20
24	25	30	32	36	40	45	48	50	54
60	64	72	75	80	90	96	100	120	125
135	150	160	180	200	225	240	250	270	300
320	360	375	400	450	480	500	540	600	675
720	750	800	900	960	1000	1080	1200	1350	1440
1500	1600	1800	2000	2160	2250	2400	2700	2880	3000
3600	4000	4320	4500	4800	5400	6000	7200	8000	9000
10800	12000								

#### Dot Model


The chart speed can be set in the range of 1 to 1500 mm/h in 1 mm steps.

# 5.5 Setting the Date/Time

This section explains the details of setting the date/time.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Press the \sigma A key or SHIFT + \sigma A key to select Clock and then press the <⊨ key.</li>
- 3. Set the date and time and press the <⊨ key. Use the \\$\Delta\$ key or SHIFT + \\$\Delta\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. Hold down the MENU key for 3 seconds to return to Operation mode.



# Explanation

### Date/Time

0

The year is set with the lower two digits. Values in the range 80 and 99 correspond to 1980 to 1999.

### **Recorders with Version 1.02 or Earlier**

The following is the setting menu.

4/02/17 10:39:47 Set	the time
----------------------	----------

DST=Summer

Select Summer or Winter, whichever the set time belongs to.


<Related Topics> Changing the printout/display format of the date : Section 7.19

# 6.1 Setting the Trend Recording Interval (Dot Model)

This section explains the details of setting the trend recording interval (dot printing interval) on the dot model.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Aux and then press the  $\triangleleft$  key.
- **3.** Press the ∇△ key or **SHIFT** + ∇△ key to select **Trend** and then press the <⊨ key.
- 4. Set the dot printing interval and press the <≓ key. Use the \scale A key or SHIFT + \scale A key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
   If you are done, press the ESC key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.



# Explanation

#### Mode

Auto: The trend recording interval is set according to the chart speed in the range of 10 s to 90 s so that the dots do not overlap many times. The interval is displayed on the System display (see page 12-9).

Fix: The trend recording interval is fixed to 10 s/6 dots. On models with the computation function (/M1 option), the trend recording interval varies depending on the number of measurement and computation channels to be trend recorded.

Number of channels to be recorded	Trend recording interval
6 or less	10 s
7 to 12	15 s
13 to 18	20 s

#### When set to Auto

# When set to Fix

Dot The di paper

The distance between dots printed on the chart paper varies depending on the chart speed.

# 6.2 Setting the Filter (Pen Model)

This section explains the details of setting a filter on the measurement channels on the pen model.

# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\triangleleft$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Filter** and then press the  $\triangleleft$  key.
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\\$ key or SHIFT + \\$\Delta\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.

Set= <mark>Aux</mark>	
Aux=Filter	
CH=01-01	Set the channel range.
First channel Last channel	
Resp.Time= <mark>Off</mark>	Set the filter time constant.
E	
01-01 Channel	The new setting takes effect

### **Explanation**

#### **Filter Time Constant**

The time constant is selectable from 2 s, 5 s, and 10 s. Select Off when not using the filter.

<Related Topics> Enabling the filter function: Section 7.12

# 6.3 Setting the Moving Average (Dot Model)

This section explains the details of setting the moving average function on measurement channels on the dot model.

# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\triangleleft$  key.
- 3. Press the \u2272\u2265 key or SHIFT + \u2272\u2265 key to select Moving\_AVE and then press the \u2272 key.
- 4. Set each item and press the < key.</li>
  Use the ∇△ key or SHIFT + ∇△ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>
   If you are done, press the ESC key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.

]	
	Set the channel range.
+ = <mark>0ff</mark>	Set the number of samples of the moving average. Moving average is not performed when Off is selected.
	The new setting takes effect.

### Explanation

### The Number of Samples of Moving Average

The number of samples can be set to a integer between 2 and 16. Select Off when not using the moving average function.

<Related Topics> Enabling the moving average function: Section 7.11

# 6.4 Setting Recording Zones for Each Channel (Zone Recording)

This section explains the details of setting the recording zone for each measurement channel.

# Procedure

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Aux and then press the  $\triangleleft$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Zone** and then press the  $\langle \exists key \rangle$ .
- 4. Set each item and press the <⊨ key. Use the ∇∆ key or SHIFT + ∇∆ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the **MENU** key for 3 seconds to return to Operation mode.

Set= <mark>Aux</mark>	
Aux= <mark>Zone</mark>	
	1
	Set the channel range.
First channel Last channel	
Left=0	Set the leftmost value of the recording zone.
Right= <mark>1</mark> 00	Set the rightmost value of the recording zone.
ESC/? Setting comple	The new setting takes effect.

# Explanation

#### Zone

The recording zone can be set in the following range.Leftmost position:0 mm to 95 mmRightmost position:5 mm to 100 mmSet a larger value for the rightmost position than the leftmost position.

Set at least 5 mm for the zone width.

#### Note.

If the zone is set to a value less than 40 mm, scale printout of periodic printout cannot be executed.

# 6.5 Setting the Partial Expanded Recording

This section explains the details of expanding a section of the recording range. If you change the input range, set the partial expanded recording again.

# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Aux and then press the  $\triangleleft$  key.
- Press the \u2272 A key or SHIFT + \u2272 A key to select Partial and then press the <⊨ key.</li>
- 4. Set each item and press the < key.</li>
  Use the ∇△ key or SHIFT + ∇△ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>
   If you are done, press the ESC key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.

$\cup$ ,	·
Set= <mark>Aux</mark>	
Aux=Partial	
	Set the channel range.
First channel Last channel	
Partial= <mark>Off</mark>	Select On to use the partial expanded recording function.
Expand= <mark>5</mark> 0	Set the boundary position as a percentage where the recording span
	is assumed to be 100%.
Boundary= 0.000	Set the boundary value within the recording span.
	]
5 01-01 Channel	The new setting takes effect.

# Explanation

#### Expand

Set a value between 1 and 99%. One percent corresponds to 1 mm, because the record width is 100 mm.

Example: To record 0 to 8 V in the 0 to 50% position and 8 to 10 V in the 50% to 100% position with a span of 0 to 10 V, set the boundary position to 50% and the boundary value to 8.00 V.

<Related Topics> Enabling the partial expanded recording function: Section 7.13

# 6.6 Turning Trend Recording (Dot Model) and Periodic Printout ON/OFF for Each Channel

This section explains the details of setting the trend recording and periodic printout for each measurement channel.

The following settings can be entered for each channel.


- Turn trend recording ON/OFF (dot model only).
- Turn the printing of measured values ON/OFF during periodic printout.

# Procedure

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\triangleleft$  key.
- Press the \(\nbox \Lefta \) key or SHIFT + \(\nbox \Lefta \) key to select Print out and then press the <\(\mu\) key.</li>
- **4.** Set each item and press the <⊨ key.

Use the \(\nbox\) A key or SHIFT + \(\nbox\) A key to select values.
For the procedure on how to enter values or characters, see section 4.2.
If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the (MENU) key for 3 seconds to return to Operation mode.



# **Explanation**

### Trend Recording (Dot Model)

On: Turns On the trend recording of the specified channel.

#### **Periodic Printout**


- On: Prints the measured values (instantaneous values or report data) of the specified channel during periodic printout.
- Off: Does not print the channels and measured values during periodic printout.

# 6.7 Setting Tags on Channels

This section explains the details of setting tags to measurement channels.

#### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\triangleleft$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Tag** and then press the  $\triangleleft$  key.
- 4. Set each item and press the < key. Use the ∇△ key or SHIFT + ∇△ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the (MENU) key for 3 seconds to return to Operation mode.



# Explanation

# **Characters That Can Be Used for Tags**

Set the tag using up to 7 characters.

The available characters are as follows:

Alphabet, numbers, symbols (%, #, °, @, +, –, \*, /, (, ),  $\mu$ ,  $\Omega$ , <sup>2</sup>, <sup>3</sup>, .), and space


<Related Topics> Printing tags in place of channel numbers: Section 7.7 Displaying tags in place of channel numbers: Section 8.2

# 6.8 Setting the Message String

This section explains the details of setting the message strings to be printed on the chart paper. Up to five message strings can be registered.

# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\triangleleft$  key.
- Press the \u2272 A key or SHIFT + \u2272 A key to select Message and then press the <⊨ key.</li>
- 4. Set each item and press the <- key. Use the \scale \
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
   If you are done, press the ESC key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.



# Explanation

#### **Characters That Can Be Used for Messages**

Set the message using up to 16 characters.

The available characters are as follows:

Alphabet, numbers, symbols (%, #, °, @, +, -, \*, /, (, ),  $\mu,$   $\Omega,$   $^2,$   $^3,$  .), and space


<Related Topics> Printing messages: Section 3.10

# 6.9 Setting the Secondary Chart Speed (Remote Control Function, /R1)

This section explains the details of setting the secondary chart speed when the chart speed is to be switched using the remote control function (/R1 option).

# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Aux and then press the  $\triangleleft$  key.
- Press the \(\nbox\) A key or SHIFT + \(\nbox\) A key to select Chart2 and then press the <\(\mu\) key.</li>
- 4. Set each item and press the <≓ key.</li>
  Use the \\$\sigma \\$\triangle\$ key or SHIFT + \\$\sigma \\$\triangle\$ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊨ key.</li>
   If you are done, press the ESC key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.



# Explanation

Chart Speed See section 5.4.


<Related Topics> Setting the remote control function: Section 7.18

# 6.10 Setting the Alarm Delay Duration

This section explains the details of setting the duration of the delay alarm.

#### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\triangleleft$  key.
- 3. Press the \u2275 A key or SHIFT + \u2275 A key to select Alm delay T and then press the \u2275 key.
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\\$ key or SHIFT + \\$\Delta\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the (MENU) key for 3 seconds to return to Operation mode.



### Explanation

# Duration

The duration can be set to a value in the range of 1 to 3600 s.

However, if the scan interval on the dot model is 2.5 s, the actual duration is an integer multiple of 2.5 s. If the set value is not equal to an integer multiple of 2.5 s, the duration is the smallest integer multiple of 2.5 s greater than the set value. Example: The actual duration for 1 s and 2 s is 2.5 s.


<Related Topics> Enabling the alarm delay function: Section 7.15

# 6.11 Setting the Brightness of the Display and Internal Light

This section explains the details of setting the brightness of the display and the internal light.

# Procedure

- **1.** Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Aux and then press the  $\triangleleft$  key.
- Press the \(\nbox\) A key or SHIFT + \(\nbox\) A key to select Brightness and then press the A key.
- 4. Set each item and press the <⊨ key.</li>
  Use the \\$\Delta \\$ key or SHIFT + \\$\Delta \\$ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊨ key.</li>
   If you are done, press the ESC key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.



# Explanation

#### **Display Brightness**

The brightness can be set to an integer between 1 and 8. The darkest setting is 1; the brightest setting is 8.

### **Internal Light Brightness**

The brightness of the internal light can be set to an integer between 1 and 4. The darkest setting is 1; the brightest setting is 4. Select Off to turn Off the internal light.

# 6.12 Applying a Bias on the Measuring Input Signal

This section explains the details of setting a bias on the measuring input signal. If you change the input range, set the bias again.

# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select **Bias** and then press the  $\triangleleft$  key.
- 3. Set each item and press the <≓ key. Use the \\$\sigma \\$ key or SHIFT + \\$\\$\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>
   If you are done, press the ESC key.
- 5. Hold down the MENU key for 3 seconds to return to Operation mode.

S		
01-01		Set the channel range.
annel Last channel		
s= <mark>Off</mark>	ľ	Select whether to use the bias.
Bias is On)		l
s= 0.000		Set the bias value.
		l
		The new setting takes effect.
	Annel Last channel s=Off Bias is On) s=O.000 01 Channel	$01 - 01$ $\downarrow \qquad \downarrow$ annel Last channel $\exists s = 0ff$ Bias is On)

# Explanation

#### **Channel Range**

The only case when a bias can be set on multiple channels simultaneously is when the channels are set to the same range type (for example channel 01 and 02 are set to 2 V range). For channels on which scaling is set, the channels must be set to the same range type, same span values, and same scaling values.

#### Bias

The range of bias that can be specified is  $\pm 10\%$  of the span of the measurable range at the specified range type. For example, the range is -0.4 V to 0.4 V for the range type 2 V. For channels on which scaling is set, the range is  $\pm 10\%$  of the scaling span.

#### Note

A bias cannot be set on channels set to ON/OFF input (DI).

<Related Topics> Enabling the bias function: Section 7.15

# 6.13 Performing Calibration Correction (/CC1 Option)

The values of the measuring input signal are corrected using specified segments, and the results are used as measured values.

If you change the input range, set the correction point (measured value) and correction values again.


# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the ∇△ key or SHIFT + ∇△ key to select Calibration and then press the < key.</p>
- Set each item and press the <⊨ key.</li>
  Use the \\$\scrime{\s\scrime{\s\srime{\s\scrime{\s\srime{\s\srime{\s\scrime{\s\scrime{\s\s
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>
   If you are done, press the ESC key.
- 5. Hold down the MENU key for 3 seconds to return to Operation mode.


Set=	-Calibration	
	CH= <mark>01</mark>	Select the channel.
	(Displays the following when	]
	Calibration= <mark>On</mark>	Turn On or Off the calibration correction.
		]
	1 datums= 0.000	Set the first correction point (input value).
		]
	1 revise= 0.000	Set the first correction value.
		Likewise, set the second correction point and correction value.
	Decision= <mark>Yes</mark>	Yes: The setting is fixed. No: The setting becomes invalid.
		]
ESC/?	01CH Calibration Setting complete	The new setting takes effect.

#### Explanation

Setting Correction Points (Measured Values) and Correction Values



Using absolute values



#### Example of a two-point correction

Calibration	Corrected	Measured	Correction Value			
Point	Corrected Value	value (A) Revise Va (B – A)		Absolute Value (B)		
1	10.0°C	9.8°C	0.2°C	10.0°C		
2	90.0°C	90.5°C	– 0.5°C	90.0°C		

# Setup Conditions of Measured and Correction Values

• Setting range of measured and correction values when using revise values  $A1 < A2 \le A3 \le ... \le A16$ 

(A1 + B1) < (A2 + B2) < (A3 + B3) < ... < (A16 + B16)

A and B are within the measurable range or scaling range of the range type\* \* Within the scaling range: -5% to 105% of the scale value or -20000 to 30000 (the decimal place is the same as the setting for the scale value)

- Setting range of measured and correction values when using absolute values A1 < A2  $\leq$  A3  $\leq$  ...  $\leq$  A16

B1 < B2 < B3 < ... < B16

A and B are within the measurable range or scaling range of the range type\*

\* Within the scaling range: -5% to 105% of the scale value or -20000 to 30000 (the decimal place is the same as the setting for the scale value)

#### Note .

- Make sure that the leftmost value is less than the rightmost value for span and scale.
- Calibration correction cannot be set on ON/OFF input (DI), delta computation, and square root computation channels. In addition, calibration correction cannot be used on all channels if the bias function is enabled.

<Related Topics> Enabling the calibration correction function: Section 7.15 Setting the calibration correction function: Section 7.23

# 6.14 Setting Up Start Printout and End printout (/BT1 Option)


Enter settings for Start printout/Start printout 2 when starting recording, and for End printout/End printout 2 when stopping recording.

You cannot enter Basic Setting mode during the time between start printout to end printout.


# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Press the \sigma A key or SHIFT + \sigma A key to select Batch and then press the <⊨ key.</li>
- Set each item and press the <⊨ key.</li>
  Use the \\$\scrime{\s\scrime{\s\srime{\\s
- When the Setting complete screen appears, do either of the following: To correct the setting the <⊢ key.</li>
   If you are done, press the ESC key.
- 5. Hold down the MENU key for 3 seconds to return to Operation mode.


# Setting the Batch Number




# Setting the Lot Number




6









# Setting the Feed Amount, Lot Number Update, and Ejection of Pen Offset Compensating Data

#### **Explanation**

#### Batch No.

You can enter up to 26 characters.

The following are the characters that can be used.

Alphabet, numbers, symbols (%, #,  $^{\circ}$ , @, +, -, \*, /, (, ),  $\mu$ ,  $\Omega$ ,  $^{2}$ ,  $^{3}$ , .), and space

### Lot No.

Enter using a 4 or 6 digit number. Select which number of digits to use (4 or 6) under "Lot No." in Basic Setting mode.

#### Mode

Select Start, End, Start 2, or End 2. Start 2 and End 2 become available when you enable "Dual comment" in Basic Setting mode.

#### Line No.

1 to 5 lines can be printed out.

#### Comment

You can enter up to 32 characters.

The following are the characters that can be used.

Alphabet, numbers, symbols (%, #, °, @, +, -, \*, /, (, ),  $\mu$ ,  $\Omega$ , <sup>2</sup>, <sup>3</sup>, .), and space

6

## Feed

The available setting range is 0 to 50 mm.

## **POC** output

You can eject the portion that is not recorded when recording stops with the pen offset compensating recording function.

# **POC speed**

Select the chart speed when ejecting the portion that was not recorded. Chart speed: Feeds at the specified chart speed. 450mm/h: Fixed to feed at 450 mm/h.

### Note \_

- The following operations are performed when using the header printout function (/BT1 option).
- When the power is interrupted and is reintroduced, recording always stops. End printout/End printout 2 is not performed.
- When recording stop detection is performed (option /F1), recording and printout stop. When chart paper is inserted, the instrument operates as follows.
  - When detected during Start printout and recording: Recording starts after Start printout.
  - When detected during End printout: When stopped, End printout/End printout 2 is not performed.
- Until Start printout/Start printout 2 and End printout/End printout 2 finishes, the instrument cannot transition to the next operation.
- When recording is started, the alarm and message printout information stored in the buffer prior to recording stop is cleared.

<Related Topics> Enabling the batch function: Section 7.24 Setting the number of digits of the lot number and enabling start printout 2 and end printout 2: Section 7.24

# 6.15 Setting the Message Format (/BT1 Option)


In the 5 message printouts, up to 35 characters can be printed out including the date/time and measured values.\*

- Under Message format, you can specify the printout contents of date/time, message string, measured values,\* and the order of these.
- Messages including measured values\* can be printed out even when Start printout or End printout is disabled.
- For entering message strings, see section 6.8.
  - \* Computed values can also be included on models with the /M1 option.

## Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Press the \(\nbox \Lefta\) key or SHIFT + \(\nbox \Lefta\) key to select Batch and then press the <\(\mu\) key.</li>
- Press the \u2272\u2264 key or SHIFT + \u2274\u2264 key to select MSG format and then press the <\u2264 key.</li>
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\\$ key or SHIFT + \\$\Delta\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.

#### Entering message format




# Explanation

#### Message No. Select from 1 to 5.

6

#### MSG format

Choose a message format. Measured values,\* message strings, and date/time can be set arbitrarily.



\* Computed values can also be included on models with the /M1 option.

#### • Date/Time Format and Number of Characters Used

Bate/Time Format and Namber of Onarabters Obea					
H:M	(Hour:Minute)	5 characters			
H:M:S	(Hour:Minute:Second)	8 characters			
M/D H:M	(Month/Day Hour:Minute)	11 characters			
M/D H:M:S	(Month/Day Hour:Minute:Second)	14 characters			
D/M H:M	(Day/Month Hour:Minute)	11 characters			
D/M H:M:S	(Day/Month Hour:Minute:Second)	14 characters			
D.M H:M	(Day.Month Hour:Minute)	11 characters			
D.M H:M:S	(Day.Month Hour:Minute:Second)	14 characters			
M.D H:M	(Month.Day Hour:Minute)	12 characters			
M.D H:M:S	(Month.Day Hour:Minute:Second)	15 characters			
Y/M/D H:M:S	(Year/Month/Day Hour:Minute:Second)	19 characters			
M/D/Y H:M:S	(Month/Day/Year Hour:Minute:Second)	19 characters			
D/M/Y H:M:S	(Day/Month/Year Hour:Minute:Second)	19 characters			
D.M.Y H:M:S	(Day.Month.Year Hour:Minute:Second)	19 characters			
M.D.Y H:M:S	(Month.Day.Year Hour:Minute:Second)	20 characters			

### Format of Measured Values and Computed Values, and Number of Characters Used

- The format for measured values is 01, 02, ...06 (depending on the model). No units are added. 7 characters are used.
- The format for computed (/M1 option) values is: 0A, 0B, 0C, 0D, 0E, 0F, 0G, 0J, 0K, 0M, 0N, and 0P (depending on the model). No units are added. 9 characters are used.

#### Character String Format

The format for message strings is L01 (1 character), L02 (2 characters), .... L16 (16 characters).

In the example above, L09 specifies "Process-1" and L02 specifies "°C ."

<Related Topics> Enabling the message format: Section 7.24

# 6.16 Setting the Date/Time When Switching between Standard Time and DST


This section explains the details of setting the date/time when switching from the standard time to DST and the date/time when switching back from DST to standard time if the recorder is used in a region that has DST. When the preset date/time arrives, the recorder internal clock automatically switches.

# Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Aux and then press the  $\triangleleft \forall$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **DST** and then press the  $\triangleleft$  key.
- 4. Set each item and press the <⊢ key. Press the ∇△ key or SHIFT + ∇△ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.

6

#### 6.16 Setting the Date/Time When Switching between Standard Time and DST



# Explanation

#### DST

Select Use to use DST.

#### Start month, Strt day, and Start time

Set the date/time for switching from standard time to DST. Specify the day as the n th day of the week of the month.

#### End month, End day, and End time

Set the date/time for switching from DST to standard time. Specify the day as the n th day of the week of the month.

# 6.16 Setting the Date/Time When Switching between Standard Time and DST

# **Recorders with Version 1.02 or Earlier**

The following is the setting menu.

Time=Summer	Select standard time (Winter) or DST (Summer).
Summer=Off	Select On to set the time to switch between standard time and DST.

Time=04/07/05 00 Set the time to switch.

DST Setting complete The new setting takes effect.

# 7.1 Changing the Auxiliary Alarm Function

This section explains the details of setting the alarm system items listed below.

- Diagnosis output using the alarm output relay (I01)
- Reflash alarm operation of the alarm output relay (I01 to I03)
- AND/OR operation of alarm output relays
- · Energized/De-energized operation of alarm output relays when alarms occur
- · Hold/Non-hold operation of alarm output relays
- · Hold/Non-hold operation of alarm indications
- The interval of the rate-of-change alarm
- Alarm hysteresis

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

# **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the <--- key with **Alarm** shown on the screen.
- 4. Set each item and press the <⊨ key.</li>
  Use the ∇∆ key or SHIFT + ∇∆ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
   If you are done, press the ESC key.

7

### 7.1 Changing the Auxiliary Alarm Function



### Applying the Changes and Returning to Operation Mode

Press the  $\nabla\Delta$  key or **SHIFT** +  $\nabla\Delta$  key to select **End** and then press the  $\prec \!\!\!\!$  key. Press the  $\nabla\Delta$  key to select **Store** and then press the  $\prec \!\!\!\!$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \!\!\!\!$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

# **Explanation**

### Diagnosis

When set to On, alarm output relay I01 becomes a dedicated diagnosis output relay, and the operation is fixed to OR, de-energized, and non-hold. Diagnosis output is a function which outputs a relay signal when an error is detected in the recording section, burnout detection function, or the A/D converter.

# Reflash

Turns On/Off the reflash alarm operation of alarm output relays I01, I02, and I03. When set to On, alarm output relays I01, I02, and I03 set to reflash alarm operation, and the operation is fixed to OR, de-energized, and non-hold.

# AND

Sets the AND/OR operation of alarm output relays.

None: No relays are set to AND operation. All relays are set to OR operation.

I01: Only I01 is set to AND operation.

I01-I02: I01 and I02 are set to AND operation.

I01-I03: I01 to I03 are set to AND operation.

I01-I04: I01 to I04 are set to AND operation.

I01-I05: I01 to I05 are set to AND operation.

I01-I06: I01 to I06 are set to AND operation.

# Act

Sets whether the output relay is energized or de-energized when an alarm occurs.

Energiz	e:	Energizes the relay when an alarm occurs. The relay is de-energized							zed	1			
		during normal operation.											
-		-											

De\_energize: De-energizes the relay when an alarm occurs. The relay is energized during normal operation.

# Behavior

Specifies whether to set the alarm output relay to hold operation or non-hold operation.			
Nonhold:	Releases the relay output at the same time the alarm is released.		
Hold:	Holds the relay output until the alarm ACK operation is executed.		

# Indicator

Specifies whether to set the alarm indication to hold operation or non-hold operation.Nonhold:Releases the alarm indication at the same time the alarm is released.Hold:Holds the alarm indication until the alarm ACK operation is executed.

# Increase

Set the interval of the high limit on rate-of-change alarm to an integer between 1 and 15. The interval is set to scan interval  $\times$  (1 to 15).

Pen model:	The scan interval is 125 ms. The maximum interval is 1.875 s.
Dot model:	The maximum interval when the scan interval set to 1 s is 15 s. The
	maximum interval when the scan interval set to 2.5 s is 37.5 s.

# Decrease

Set the interval of the low limit on rate-of-change alarm to an integer between 1 and 15. The setup procedure is the same as Increase.

# Hysteresis

Sets the alarm hysteresis of the measurement channels.

The hysteresis width can be set in the range of 0.0% (Off) to 1.0% of the recording span in 0.1 steps.

The hysteresis applies to all high limit and low limit alarms of measurement channels.

# M\_Hysteresis (Models with the Computation Function (/M1 Option))

Sets the alarm hysteresis of the computation channels.

The hysteresis width can be set in the range of 0.0% (Off) to 1.0% of the recording span in 0.1 steps.

The hysteresis applies to all high limit and low limit alarms of computation channels.

# 7.2 Changing the Integration Time of the A/D Converter

This section explains the details of setting the integration time of the A/D converter. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


# Procedure

# **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and < > keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select A/D and then press the  $\triangleleft$  key.
- **4.** Set each item and press the <⊨ key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊨ key.</li>
 If you are done, press the ESC key.



# Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

# Explanation

#### Integrate

Selects the integration time of the A/D converter.

Setting	Integration Time	Scan Interval (Pen Model)	Scan Interval (Dot Model)
50 Hz	20 ms	125 ms	1 s
60 Hz	16.7 ms	125 ms	1 s
Auto	20 ms or 16.7ms <sup>2, 3</sup>	125 ms	1 s
100 ms <sup>1</sup>	100 ms	_	2.5 s

1: Selectable only on the dot model.

2: Automatically switch by detecting the power supply frequency.

3: The integration time is fixed to 20 ms if "Auto" is selected when using the DC power supply on a model with the /P1 option.

# 7.3 Setting the Burnout Detection Function of Thermocouples

This section explains the details of setting the burnout detection function of thermocouples to channels set to 1-5V or TC input.


Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

# Procedure

# **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \u2272 A key or SHIFT + \u2272 A key to select Burnout and then press the <⊨ key.</li>
- 4. Set each item and press the < key. Use the ∇△ key or SHIFT + ∇△ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>

If you are done, press the **ESC** key.



# Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

# Explanation

#### Burnout

Selects the action taken when a burnout is detected at the 1-5V input or the thermocouple input.

Up: Records off the scale on the 100% side.

Down: Records off the scale on the 0% side.

Select Off when not using the burnout detection function.

# 7.4 Setting the RJC Function on Channels Set to TC Input

This section explains the details of setting RJC on channels set to TC input. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

# Procedure

# **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select RJC and then press the  $\triangleleft$  key.
- **4.** Set each item and press the <⊢ key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 When the Setting complete screen appears, do either of the following: Press the <
 <ul>
 key to set other channels.
 If you are done, press the ESC key.

Basic= <mark>RJC</mark>		
	D1	Set the channel range.
First channel	Last channel	
RJC= <mark>Int</mark>	cernal	<ul> <li>Select the RJC mode of the</li> <li>thermocouple input.</li> </ul>
(When RJC is se	et to External)	
Volt=	0	Set the compensation voltage when using the external RJC function.
	E	
ESC/?-Setting	Channel g complete	The new setting takes effect.

## Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

# Explanation

# RJC

Sets the RJC mode.

Internal: Uses the RJC function on the recorder.

External: Uses an external RJC function. If external is selected, set the compensation voltage.

# Volt

Sets the compensation voltage when using an external RJC function. The compensation voltage can be set in the range of –20000  $\mu V$  to 20000  $\mu V.$ 

# 7.5 Changing the Channel Recording Color (Dot Model)

This section explains the details of changing the trend recording color on the dot model. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272A and < > keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \u2275 key or SHIFT + \u2275 key to select Color and then press the <⊨ key.</li>
- 4. Set each item and press the <⊨ key.</li>
   Use the \\\\Delta \key or SHIFT + \\\Delta \key to select values.

For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### **Explanation**

#### Color

Sets the recording color of measurement channels. By default, the recording colors are set as follows: Channel01: Purple Channel 02: Red Channel 03: Green Channel 04: Blue Channel 05: Brown Channel 06: Black

### 7.6 Recording by Compensating for the Pen Offset along the Time Axis (Pen Model)

This section explains the details of setting the compensation for the pen offset along the time axis (pen model).

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and < > keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select POC and then press the  $\triangleleft$  key.
- 4. Set each item and press the <⊨ key.</li>
   Use the \\\\Delta \Lefta key or SHIFT + \\\Delta \Lefta key to select values.

For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
 If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \!\!\!\!$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \!\!\!\!$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \!\!\!\!$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### POC (Pen Offset Compensation)

On: Enables pen offset compensation. Off: Disables pen offset compensation.

Note \_\_\_\_\_

When pen offset compensation is enabled, all pens are aligned with the reference pen (pen that is furthest to the back: pen 2 on the 2-pen model, pen 3 on the 3-pen model, and pen 4 on the 4-pen model) for recording. When recording is started, only the reference pen moves until the offset is compensated. This is not a malfunction.

When pen offset compensation is enabled, an asterisk is printed by the time on the periodic printout.

# 7.7 Turning Printouts ON/OFF

# (Selecting the Channel/Tag Printout and Turning ON/OFF the Channel No., Alarm, Recording Start, New Chart Speed, Scale, and Pen Color Printouts)

This section explains the details of turning ON/OFF the printouts of various items. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Print** and then press the  $\triangleleft$  key.
- 4. Set each item and press the <≓ key. Use the \\$\Delta\$ key or SHIFT + \\$\Delta\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: To correct the setting, press the <<sup>⊥</sup> key.
   If you are done, press the ESC key.

Basic=Print	]	
	1	
CH/Tag=Channel	L	Select whether to use the channel number or tags for the printout.
(Dot model)		
Channel= <mark>On</mark>		Select whether to print the channel number or tag beside the trend recording.
Alarm=On1		Select whether to print the alarm
Alarm=Onl		occurrence/release.
Record On=Off		Select On to enable recording start
		printout.
Chart speed= <mark>O</mark>		Select On to print when the chart
		speed is changed.
Scale= <mark>On</mark>		Select On to print the channel scale in periodic printout.
(Pen model)		
Pen color= <mark>On</mark>		Select On to print the pen color in periodic printout.
		<b>_</b>
ESC/? Setting comple	ete	The new setting takes effect.

#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\triangleleft$  key. The changes are applied, and the screen returns to Operation mode. If you select Abort and press the <- key, the changes are discarded, and the screen returns to Operation mode. Press the ESC key to return to the **Basic=** screen.

#### Explanation

#### CH/Tag

Channel: Prints the channel number. Tag: Prints the tag.

#### **Channel (Dot Model)**

When On is selected channel number or tag is printed by the trend recording.

#### Alarm

- On1: Prints the alarm information when an alarm occurs or releases.
- On2: Prints the alarm information only when an alarm occurs.
- Off: Does not print alarm information.

#### Pen Color Printout (Pen Model)

When On is selected, the recording color of the channel whose scale is printed is printed. This is valid on channels whose scale printout is turned On.

#### Note .

Channel, alarm, recording start, and new chart speed printouts are not performed when the chart speed is greater than or equal to 1600 mm/h and 101 mm/h on the pen model and dot model, respectively.

# 7.8 Setting the Periodic Printout Interval and the Type of Data to Be Printed

This section explains the details of setting the periodic printout interval and the type of data to be printed.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

#### Periodic Printout Interval and Type of Data to Be Printed Changing the Settings

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \(\nbox\) A key or SHIFT + \(\nbox\) A key to select Print1 and then press the <\(\mu\) key.</li>
- **4.** Set each item and press the <⊨ key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊨ key.</li>
 If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla\Delta$  key or **SHIFT** +  $\nabla\Delta$  key to select **End** and then press the  $\prec \!\!\!\!$  key. Press the  $\nabla\Delta$  key to select **Store** and then press the  $\prec \!\!\!\!$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \!\!\!\!$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Types of Report Data to Be Printed

#### Changing the Settings

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \(\nbox\) key or SHIFT + \(\nbox\) key to select Print2 and then press the <\(\mu\) key.</li>
- **4.** Set each item and press the <⊨ key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels.</li>

If you are done, press the **ESC** key.

Bas	ic= <mark>Print2</mark>		
	CH=01-01		Set the channel range.
	First channel Last channel		
	Mode= <mark>AVE</mark>	<b>*</b>	Select the type of report data to print.
	SUM scale= <mark>Off</mark>		Select the sum scale.
	Printout2		The new setting takes effect.
ESC/?	Setting comple	ete	

#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Periodic Printout Interval and Type of Data to Be Printed

#### Periodic

Select the periodic printout interval mode.

Auto:Automatically sets the printout interval in sync with the chart speed.Manual:Set the printout interval manually.

#### Ref. Time

Sets the reference time for determining the times for executing the periodic printout. The reference time is set in the range of 00 to 23 in 1 hour steps. Minutes cannot be specified.

#### Interval

Select the interval from 10, 12, 15, 20, 30 minutes, 1, 2, 3, 4, 6, 8, 12, and 24 hours. However, printout might not take place at the specified interval depending on the chart speed and items printed (for details, see appendix 2).

#### Mode

Sets the type of measured values to be printed.

 Inst:
 Prints the measured value or computed value (/M1 option) at that point.

 Report:
 Prints the report over the interval. If Report is selected, set the types of report data to be printed as described in "Types of Report Data to Be Printed" below (computation channels are set in section 9.15).

 Off:
 Disables periodic printout.

#### Types of Report Data to Be Printed

#### Mode

Sets the type of report data to be printed.

- AVE: Prints the average value over the interval.
- MIX: Prints the minimum, maximum, and average values over the interval.
- SUM: Prints the sum value over the interval. If SUM is selected, set the sum scale.
- MIN: Prints the minimum value over the interval.
- MAX: Prints the maximum value over the interval.
- INST: Prints the instantaneous value.

#### SUM scale

Set this item only when SUM is selected.

SUM sums the data every computation interval. For flow values that have units /s, /min, or /h, a simple summation results in the actual value not matching the computed result, because the scan interval and the unit of the input values are different. In such cases, set the sum scale to match the unit of the input value. In effect, the sum value with the same unit as that of the input value is calculated.

For example, if the scan interval is 1 s, and the input value is  $100 \text{ m}^3/\text{min}$ , a simple summation would add 100 every 1 s resulting in 6000 after one minute. However, if the sum scale is set to /min, then 1 s/60 s is multiplied every scan interval before the value is added giving a result with an m<sup>3</sup>/min unit.

- Off: Simply sums the measured values.
- /s: Sums by converting the measured values to a value over 1 second.
- /min: Sums by converting the measured values to a value over 1 minute.
- /h: Sums by converting the measured values to a value over 1 hour.
- /day: Sums by converting the measured values to a value over 1 day.

### 7.9 Setting the Bar Graph Display Mode

This section explains the details of setting the bar graph display mode. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the \(\nabla \Leq \key \text{ or SHIFT} + \(\nabla \Leq \key \text{ to select Bar graph and then press the \(\leq \mathcal{L} \key. \)
- 4. Set each item and press the <≓ key.</li>
  Use the \\$\Delta \\$ key or SHIFT + \\$\Delta \\$ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels.</li>
   If you are done, press the ESC key.

Basic= <mark>Bar</mark>	graph	
	01	Set the channel range.
First channel	Last channel	」 〗 ] Select the display mode of the bar graph.
	Channel	] 〗 ] The new setting takes effect.
	g complete	

#### Applying the Changes and Returning to Operation Mode


Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec =$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec =$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec =$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Graph

- Normal: Sets the base point of the bar graph to the left or right of the recording span whichever is smaller in value.
- Center: Sets the base point of the bar graph to the 50% position of the recording span.

#### Starting point of the bar graph



Setup Operations for Changing/Adding Functions (Basic Setting Mode)

# 7.10 Setting the Key Lock Function

This section explains the details of setting the keys that can be locked and the password for releasing the key lock.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- **1.** Hold down the  $\widehat{\text{MENU}}$  key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \u2275 key or SHIFT + \u2275 key to select Keylock and then press the <⊨ key.</li>
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\\$ key or SHIFT + \\$\Delta\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
   If you are done, press the ESC key.

ic= <mark>Keylock</mark>	
Keylock= <mark>Use</mark>	Select whether to use the key lock function.
(Displays the following when the Keylock is set to Use)	
Password=	Set the password for releasing the key lock.
RCD= <mark>Free</mark>	Select Lock to apply the key lock functio to the RCD key.
Feed=Free	☑ ☐ Select Lock to apply the key lock functio
	to the FEED key.
Menu= <mark>Free</mark>	⊐ ] Select Lock to apply the key lock functio ] to the MENU key.
	2 2
Disp Menu= <mark>Free</mark>	Select Lock to apply the key lock functio to the DISP MENU.
Alarm ACK= <mark>Free</mark>	Select Lock to apply the key lock functio to the alarm ACK operation.
(/M1 option)	의 ] Select Lock to apply the key lock functio
	」 to the computation start/stop operation. ▣
Printout=Free	<ul> <li>Select Lock to apply the key lock function</li> <li>to the various printout operations.</li> </ul>
	-
Message= <mark>Free</mark>	Select Lock to apply the key lock functio to the message printout operation.
Buffer clear= <b>Free</b>	Select Lock to apply the key lock functio
builer Ciear-riee	to the operation of clearing the printout buffer.
Periodic= <mark>Free</mark>	Select Lock to apply the key lock function to the operation of resetting the report
	data in periodic printout.
(Pen model)	Select Lock to apply the key lock function the operation of moving the pen to a positio where the pen can be easily replaced.
(Dot model)	Select lock to apply the key lock to the
R. exchange=Free	operation of replacing the ribbon casset with the power turned ON.
Keylock Setting complete	<sup>⊿</sup> (version 1.11 or later) The new setting takes effect.
secting complete	

#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### **Keylock**

Sets whether to use or not use the key lock function. If Not is selected, the setup ends here.

#### Password

Sets the password for releasing the key lock. Set the password using numbers and spaces within 4 digits.

#### **Operation of Keys to Be Key-Locked**

Sets the operation of the keys to be key-locked. Select Lock or Free for each key operation.

oporation	
RCD:	RCD key
Feed:	FEED key
Menu:	MENU key
Disp Menu:	(TMENU key
Alarm ACK:	Alarm ACK operation under the FUNC key
Math:	Computation start/stop/reset operation under the orune key (/M1 option)
Print out:	Printout start/stop/reset operation under the orunc key
Message:	Message printout operation under the FINC key
Buffer clear:	Clear operation of the printout buffer memory under the OFUNC key
Periodic:	Clear operation of the report data of periodic printout under the OFUNC
	key
Pen exchange:	Operation of moving the pen to an easily accessible position of
	replacement under the larunc key (pen model)
R. exchange:	Operation carried out when replacing the ribbon cassette with the power
	turned ON under the offunc key (dot model)

<Related Topics> Activating/Releasing the key lock: Section 3.13

# 7.11 Enabling the Moving Average Function (Dot Model)

This section explains the details of enabling/disabling the moving average function on the dot model.


Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the \u2272\u2265 key or SHIFT + \u2272\u2265 key to select Moving\_AVE and then press the <\u2272 key.</p>
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\\$ key or SHIFT + \\$\Delta\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.





#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla\Delta$  key or **SHIFT** +  $\nabla\Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla\Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Moving\_AVE

- Use: Enables the setting of the number of samples of the moving average in Setting mode.
- Not: The Moving\_AVE item does not appear in Setting mode.

<Related Topics> Setting the moving average function: Section 6.3

#### **Enabling the Filter Function (Pen Model)** 7.12


This section explains details of enabling/disabling the input filter function on the pen model.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Hold down the  $\nabla \Delta$  and  $\triangleleft \triangleright$  keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Filter** and then press the  $\langle \neg \rangle$  key.
- **4.** Set each item and press the <- key. Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the  $\lt \exists$  key. If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\triangleleft$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select Abort and press the <- key, the changes are discarded, and the screen returns to Operation mode. Press the ESC key to return to the Basic= screen.

#### Explanation

#### Filter

Use: Enables the setting of the filter time constant in Setting mode. Not:

The Filter item does not appear in Setting mode.

<Related Topics> Setting the filter: Section 6.2

#### 7.13 **Enabling the Partial Expanded Recording** Function


This section explains the details of enabling/disabling the partial expanded recording function.


Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Hold down the  $\nabla \Delta$  and  $\triangleleft \triangleright$  keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the ∇△ key or SHIFT + ∇△ key to select Partial and then press the < kev.
- **4.** Set each item and press the  $\triangleleft$  key. Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the  $\triangleleft$  key.





#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\triangleleft$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\triangleleft$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the <- key, the changes are discarded, and the screen returns to Operation mode. Press the ESC key to return to the Basic= screen.

#### **Explanation**

#### Partial

- Enables the setting of the boundary position and boundary value of the partial Use: expanded recording function in Setting mode.
- Not: The Partial item does not appear in Setting mode.

<Related Topics> Setting the partial expanded recording function: Section 6.5

### 7.14 Changing the Display/Printout Language

This section explains the details of changing the display/printout language. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the \u2275 key or SHIFT + \u2275 key to select Language and then press the <\u2272 key.</p>
- **4.** Set each item and press the <⊢ key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
 If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Lang (Language)

English (E):	Uses the English alphabet, numbers, and symbols for display and printout.
German (G)*:	Uses the German alphabet, numbers, and symbols for display and printout.
French (F)*:	Uses the French alphabet, numbers, and symbols for display and printout.
Japanese (J):	Uses the English alphabet, katakana, numbers, and symbols for display
	and printout.

\*: German and French are supported on version 1.21 or later. The setup items of the customized menu and header printout (/BT1 option) are displayed in English.

### 7.15 Enabling the Bias, Low-Cut, Alarm Delay, Calibration Correction (/CC1 Option) Functions


This section explains the details of enabling/disabling the bias, low-cut, alarm delay, and calibration correction (/CC1 option) functions.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- 4. Press the <- key with Add function shown on the screen.
- 5. Set each item and press the <⊨ key.</li>
  Use the ∇△ key or SHIFT + ∇△ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
   If you are done, press the ESC key.



7

IM 04P01B01-01E

#### 7.15 Enabling the Bias, Low-Cut, Alarm Delay, Calibration Correction (/CC1 Option) Functions

#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Bias

Enables/Disables the bias function.

- Use: Enables the setting of the bias value in Setting mode.
- Not: The Bias item does not appear in Setting mode.

#### SQRT low-cut

Enables/Disables the square root low-cut function.

- Use: Enables the setting of the low-cut function when a channel is set to square root computation in Setting mode.
- Not: The SQRT low-cut item does not appear in Setting mode.

#### 1-5V low-cut

Enables/Disables the 1-5V low-cut function.

- Use: Enables the setting of the low-cut function when a channel is set to 1-5V in Setting mode.
- Not: The 1-5V low-cut item does not appear in Setting mode.

#### Alarm delay

Enables/Disables the alarm delay function.

- Use: Enables the setting of delay high limit alarm or delay low limit alarm for the alarm type.
- Not: The delay high limit alarm and delay low limit alarm items do not appear as possible selections for the alarm type.

#### **Calibration correction**

Enables/Disables the calibration correction function.

- Use: Enables the setting of the correction mode and the number of calibration points in Basic Setting mode and the setting of the correction points and correction values in Setting mode.
- Not: The calibration item does not appear in Basic Setting or Setting mode.

#### Note

The bias and calibration correction functions (/CC1 option) cannot be enabled simultaneously.

**Related Topics>** Setting the bias value: Section 6.12 Setting the low-cut value to the measured value: Section 5.1 Setting the delay high/low limit alarm: Section 5.2 Setting the correction mode and the number of calibration points for calibration correction: Section 7.23 Performing calibration correction: section 6.13


# 7.16 Changing the Time Printout Format

This section explains the details of changing the time printout format of alarm printout, message printout, recording start printout, and new chart speed printout. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \(\nbox \Lefta\) key or SHIFT + \(\nbox \Lefta\) key to select Personalize and then press the <\(\not\) key.</li>
- Press the \(\nbox\) A key or SHIFT + \(\nbox\) A key to select Time print and then press the <\(\not\) key.</li>
- 5. Set each item and press the <⊨ key. Use the ∇∆ key or SHIFT + ∇∆ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: To correct the setting, press the < ⊨ key. If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Alarms

Sets the time printout format of the alarm printout.		
HH:MM:	Hour:Minute	
HH:MM:SS:	Hour:Minute:Second	
M/D H:M:	Month Day Hour:Minute	
M/D H:M:S:	Month Day Hour:Minute:Second	
YMD H:M:S:	Month Day Year Hour:Minute:Second	

#### Message

Sets the time printout format of the message printout.		
HH:MM:	Hour:Minute	
HH:MM:SS:	Hour:Minute:Second	
M/D H:M:	Month Day Hour:Minute	
M/D H:M:S:	Month Day Hour:Minute:Second	
YMD H:M:S:	Month Day Year Hour:Minute:Second	
None: Does not print the date/time.		

#### **RCD On**

Sets the time printout format of the record start time printout The format is the same as that of the alarm printout.

#### C. Speed

Selects the time printout format of the new chart speed printout. The format is the same as that of the alarm printout.

#### Note

The printout format of the year, month, and day varies depending on the printout/display format of the date (see section 7.19).

# 7.17 Initializing the Settings

This section explains the details of initializing the recorder settings to their factory default. Be careful, because all settings except the date/time and the adjustment values of the pen/dot printing position will be initialized.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure


- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \scale A key or SHIFT + \scale A key to select Initialize and then press the <⊨ key.</li>
- - Set: Initializes the settings in Setting mode.

Setup+Set: Initializes the settings in Basic Setting mode and Setting mode.

5. To execute the initialization, press the \sigma A key to select Yes and then press the < lambda key.</p>

The settings are initialized, and the recorder returns to Operation mode. To cancel the initialization, press the **ESC** key The screen returns to the **Basic=Initialize** screen.

If you press the  $\nabla \Delta$  key to select **No** and press then the  $\prec \exists$  key, nothing happens.



#### Explanation

#### Items That Are Not Initialized

The following items are not initialized.

- Adjustment value of the pen position and the adjustment value of the printer carriage position (Basic Setting mode)
- Date/Time (Setting mode)

#### **Assigning Functions to the Remote Control** 7.18 Input Terminals (/R1 Option)

This section explains the details of assigning functions to the input terminals of the remote control function.


Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- 2. Hold down the  $\nabla \Delta$  and  $\triangleleft \triangleright$  keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Remote and then press the  $\triangleleft$ key.
- **4.** Set each item and press the  $\triangleleft$  key. Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the  $\triangleleft$  key.

If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\lt \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\triangleleft$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the <- key, the changes are discarded, and the screen returns to Operation mode. Press the ESC key to return to the Basic= screen.

#### Explanation

#### Remote No.

The remote control terminal numbers are from 1 to 5.

#### Function to Be Assigned

Record On/Off:	Starts/stops recording.
Alarm ACK:	Executes alarm output release.
Time adjust:	Adjusts the internal clock to the nearest hour.
Manual print:	Executes manual printout.
Message #:	Prints message # (where # is a value between 1 and 5).
Chart speed:	Changes the chart speed.
Math start/stop:	Starts/stops the computation on the computation function (/M1
	option).
Math reset:	Resets the computed result of the computation function (/M1 option).
Priority R_RCD:	Starts/stops recording (/BT1 option).
BatchCMT switch:	Start printout and Start printout 2, End printout and End printout 2
	switches according to the status of the "BatchCMT switch" signal
	during the rising or falling of the "Record On/Off" or "Priority R_RCD"
	signal (/BT1 option).
None:	No function is assigned.

#### Note.

When you select "Priority R\_RCD" and start recording remotely, you cannot stop recording using key operation or communications.

<Related Topics> Setting the secondary chart speed: Section 6.9

#### Changing the Printout/Display Format of the 7.19 Date

This section explains how to change the printout/display format of the year, month, and day. This function is available on version 1.11 or later.


Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- 2. Hold down the  $\nabla \Delta$  and  $\triangleleft \triangleright$  keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Date format and then press the <₽ kev.
- **4.** Set each item and press the  $\triangleleft$  key. Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the  $\triangleleft$  key.

If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\triangleleft$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the <- key, the changes are discarded, and the screen returns to Operation mode. Press the ESC key to return to the Basic= screen.

#### Explanation

#### **Date Format**

Dato i officia		
Setting	Format Example	Note
Y/M/D	2005/8/31	
M/D/Y	8/31/2005	
D/M/Y	31/8/2005	
D.M.Y	31.8.2005	
M.D.Y	Aug.31.2005	Default value

## 7.20 Selecting to Show/Hide the FUNC Key Menus

Select the menu for showing/hiding the FUNC key menus. This function is available on version 1.31 or later.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

#### Changing the Settings

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272 \u03c1 and \u2272 \u2274 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \u2272\u0211 key or SHIFT + \u2272\u0111 key to select Select menu and then press the <\u2272 key.</li>
- 4. Press the <- key with Function shown on the screen.
- **5.** Set each item and press the  $\triangleleft$  key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 6. When the Setting complete screen appears, do either of the following: To correct the setting the <- key.</li>
 If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

- On: Display operation menus using the FUNC key.
- Off: Do not display the operation menu using FUNC keys when Customized Menu is enabled.

<Related Topics> Enabling the Customized Menu: Section 7.22

## 7.21 Selecting to Show/Hide Setting Mode Menus

Select the menu for showing/hiding the Setting mode menus. This function is available on version 1.31 or later.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

#### Changing the Settings

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the \u03c6 \u03c6 key or SHIFT + \u03c6 \u03c6 key to select Select menu and then press the <\u03c9 key.</p>
- 4. Press the <- key with Set mode shown on the screen.
- **5.** Set each item and press the  $\triangleleft$  key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 6. When the Setting complete screen appears, do either of the following: To correct the setting the <⊢ key. If you are done, press the ESC key.



#### 7.21 Selecting to Show/Hide Setting Mode Menus

From th	e previo	ous page
---------	----------	----------

	(/CC1 option)	
	Calibration= <mark>On</mark>	Select whether to display Calibration in
		Setting mode. Select On or Off.
	(/M1 option)	
	Math= <mark>On</mark>	Select whether to display Math in Setting mode. Select On or Off.
		ล
	(/BT1 option)	
	Batch name=On	Select whether to display Batch No. and Lot No. in Setting mode. Select On or Off.
		 ] ]
	(/BT1 option)	Oslastudistlanta diaulau Datah datailin
	Batch detail= <mark>On</mark>	Select whether to display Batch detail in Setting mode. Select On or Off.
	Select set menu	The new setting takes effect.
ESC/?	Setting complete	

#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

On: Display the menu in Setting mode.

Off: Do not display the menu in Setting mode when Customized Menu is enabled.

<Related Topics> Enabling the Customized Menu: Section 7.22

## 7.22 Enabling/Disabling the Customized Menu

When the Customized Menu is enabled, the following changes can be made. This function is available on version 1.31 or later.

- · Hide specified menu items from the FUNC key menu.
- · Hide specified Setting mode menu items.
- · Lock Basic Setting mode.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


#### Procedure

#### Enabling the Customized Menu

#### Changing the Settings

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \(\nbox\) A key or SHIFT + \(\nbox\) A key to select Cust. menu and then press the A key.
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\$ key or SHIFT + \\$\Delta\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: To correct the setting the <⊢ key.</li>

If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### **Disabling the Customized Menu**

#### Changing the Settings

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Lock** and then press the  $\triangleleft$  key.
- 4. Set each item and press the < key. Use the ∇∆ key or SHIFT + ∇∆ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: To correct the setting the <- key.</li>

If you are done, press the  $\ensuremath{\text{ESC}}$  key.

Men	u kind= <mark>Lock</mark>	Select Lock.
		Enter the Password.
Pas	sword=	Enter the Password.
	Enter E	Basic Setting mode.
Bas	ic= <mark>Cust. menu</mark>	Select Cust. menu.
	Cust. menu= <mark>Not</mark>	Select Not.
	Basic Cust. me	The new setting takes effect.
ESC/?	Setting comple	te

#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Cust. menu (Customized Menu)

- Use: Displays only the desired Setting mode and FUNC key menus, and locks Basic Setting mode.
- Not: Displays all Setting mode and FUNC key menus, and releases the Basic Setting mode lock.

#### Password

The password required to release the customized menu or to enter Basic Setting mode. Set a password of four digits or fewer, using numbers and spaces.

#### Note.

### Changing the Settings in Basic Setting Mode without Disabling the Basic Setting Mode Lock

The settings in Basic Setting mode can be changed without disabling the customized menu. Procedure

- Enter a password in the same manner as the procedure for "Disabling the Customized Menu," press the <⊢ key, and enter Basic Setting mode.</li>
- 2. Change settings in the usual manner.
- 3. The instrument returns to Operation mode with Customized Menu still enabled.

<Related Topics> Selecting to show/hide the FUNC key menus: Section 7.20 Selecting to show/hide setting mode menus: Section 7.21 Adjusting the pen position/dot printing position: Sections 11.5 and

11.6

#### **Setting the Calibration Correction Function** 7.23 (/CC1 Option)

This section explains the details of setting the correction mode and the number of calibration points.


Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- 2. Hold down the  $\nabla \Delta$  and  $\triangleleft \triangleright$  keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Calibration and then press the <₽ kev.
- **4.** Set each item and press the  $\triangleleft$  key. Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the  $\triangleleft$  key.

If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\triangleleft$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\triangleleft$  key. The changes are applied, and the screen returns to Operation mode. If you select Abort and press the <- key, the changes are discarded, and the screen returns to Operation mode. Press the ESC key to return to the Basic= screen.

#### Explanation

#### Mode

Revise Value:	Sets the correction value using the revise value (corrected value -
	measured value).
•• • • •	

Abs. Value: Sets the correction value using the corrected value.

#### Point

Selects the number of points that make up the segments (including the start and end points) in the range of 2 to 16.

<Related Topics> Enabling the calibration correction function: Section 7.15 Setting the correction values: Section 6.13

### 7.24 Enabling Start Printout, End printout, and Message Format (/BT1 Option)

This section explains the details of enabling/disabling the Start printout, End printout, and Message format.


Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \u2275 key or SHIFT + \u2275 key to select Batch and then press the <⊨ key.</li>
- 4. Set each item and press the <⊨ key. Use the \scale A key or SHIFT + \scale A key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting the <- key.</li>

If you are done, press the **ESC** key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Explanation

#### Batch

- Use: When starting/stopping recording, performs Start printout and End printout. You can now set up "Lot No.," "Dual comment," and, in Setting mode, "Batch."
- Not: Do not perform Start printout/End printout.

#### Lot No.

Batch name = Batch No. (character string) and Lot No. (number)

- 4: Prints out a 4-digit lot number. You can now set this under "Lot No." in Setting mode.
- 6: Prints out a 6-digit lot number. You can now set this under "Lot No." in Setting mode.
- Not: Does not perform printout of the lot number.

#### **Dual comment**

- Use: You can now select Start printout 2 and End printout 2 in Setting mode's Mode.
- Not: There are no Start printout 2 and End printout 2 choices in Setting mode's Mode.

#### **MSG Format**

- Use: You can now set the MSG format in Setting mode.
- Not: The MSG format item is not displayed in Setting mode.

<Related Topics> Setting the start printout and end printout: Section 6.14 Setting the batch comment switch: Section 7.18 Setting the message format: section 6.15

#### **Changing the Temperature Unit** 7.25


This section explains the details of changing the temperature unit on the temperature measurement channels.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

#### Procedure

#### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Hold down the  $\nabla \Delta$  and  $\triangleleft \triangleright$  keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Temperature and then press the <₽ key.
- **4.** Set each item and press the <⊨ key. Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 5. When the Setting complete screen appears, do either of the following: To correct the setting, press the  $\triangleleft$  key. If you are done, press the ESC key.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\triangleleft$  key. The changes are applied, and the screen returns to Operation mode. If you select Abort and press the <- key, the changes are discarded, and the screen returns to Operation mode. Press the ESC key to return to the **Basic=** screen.

#### Explanation


#### **Temp (Temperature)**

The setting is applied to all temperature measurement channels. °C: Use Celsius. °F: Use Fahrenheit.

### 8.1 Key Operations for Changing the Displayed Information

#### **Displaying the Data Display Setup Screen**

Hold the **WHENU** key for 3 seconds to show the data display setup screen.



The panel keys are set to the functions marked above the keys as shown below.




#### Returning from the Data Display Setup Screen to Data Display Screen

Hold the **GMENU** key for 3 seconds to return from the data display setup screen to data display screen.

Note \_

When the data display setup screen is shown, operations such as measurement, alarm, and recording continue.

### Data Display Setup Menu



The display update rate corresponds to "Interval" in the setup menu. It is the time interval at which the displayed channel is switched.

## 8.2 Changing the Displayed Information

This section explains the details of registering display types to screens 01 to 15. As an example, the procedure to set 1-channel digital display (tag display) and the display in which different channels are assigned to top and bottom sections is explained below.


### Procedure

### 1-Channel Digital Display (Tag Display)

- 1. Hold the **(WENU** key for 3 seconds to show the data display setup screen.
- Press the \sigma A key or SHIFT + \sigma A key to select the screen number and then press the <⊨ key.</li>

A sample screen of the display type appears. A section of the display blinks to indicate that this is a data display setup screen.

- Press the \(\nabla \Lefta \) or SHIFT + \(\nabla \Lefta \) key to switch the display. Select the TAG001A (Tag\_1CH digital) display and then press the <\(\mu\) key.</li>
- **4.** Press the \(\sigma\) key or **SHIFT** + \(\sigma\) key to select the channel switching interval and then press the <\=" key.
- When the Setting complete screen appears, press the <- key.</li>
   Hold the (MIENN) key down for 3 seconds to exit from the data display setup screen.



### Explanation

Tag Display Ty			
TAG001A:200. TAG002A:200.	0	m	V
TAG002A:200.	0	m	V
TAG001A			
	· ·	•	-
TAG001A			

Diamles Tune

Tag\_1CH digital + 1CH bargraph

Tag\_1CH digital + 4CH bargraph (Pen model)

### Interval

Sets the channel switching interval.

Select the interval from 1 s, 2 s, 3 s, 4 s, 5 s, and manual.

1s, 2s, 3s, 4s, 5s: Switches the channels at the specified interval.

Tag\_2CH digital

Manual: Use the CHUP key to switch the channel. If you select Manual, specify the channels to be displayed.

#### **Assigning Other Display Types**

- When assigning the flag display, specify whether to display the flag for each channel.
- The display in which different screens can be assigned to the top and bottom sections is explained on the next page.

#### <Related Topics> Display types: Section 12.4

#### Procedure

Display in Which Different Screens Can Be Assigned to the Top and Bottom Sections (Top: 2-Channel Digital Display, Bottom: Date/Time)


- **1.** Hold the **(MENU**) key for 3 seconds to show the data display setup screen.
- Press the \(\nbox\) \(\Lambda\) key or SHIFT + \(\nbox\) \(\Lambda\) key to select the screen number and then press the \(\nbox\) \(\Lambda\) key.

A sample screen of the display type appears. A section of the display blinks to indicate that this is a data display setup screen.

- Press the \u2275 A or SHIFT + \u2275 A key to switch the display. Select the display in which different screens can be assigned to the top and bottom sections (display in which UP and DW are shown at the left edge) and press the <\u2274 key.</li>
- Set the display type for the top section.
   Press the ∇△ key or SHIFT + ∇△ key to select 2-channel digital display, and then press the <≓ key.</li>

Set the channel switching interval and other settings.

- 5. Set the display type for the bottom section.
   Press the ∇∆ key or SHIFT + ∇∆ key to select date/time, and press the <= key.</li>
- When the Setting complete screen appears, press the <- key.</li>
   Hold the (DMENU) key down for 3 seconds to exit from the data display setup screen.



### **Explanation**

# Display in Which Different Screens Can Be Assigned to the Top and Bottom Sections

You can select the display type (see page 12-12) for the top and bottom sections. **Interval:** 

See "Interval" on the previous page.

# 9.1 Starting/Stopping/Resetting the Computation

This section explains the details of starting/stopping the computation and resetting the computed values of computation channels.

### Procedure

### Starting the Computation

- 1. Press the OFUNC key.
- **2.** Press the  $\nabla \Delta$  key to show **Math** and then press the  $\triangleleft$  key.
- Press the <⊨ key with Start shown on the screen. The computation starts, and the screen switches to the data display screen. The word MATH in the status display comes on.



### Stopping the Computation


- 1. Press the oFunc key.
- **2.** Press the  $\nabla \Delta$  key to show **Math** and then press the  $\triangleleft$  key.
- Press the <⊨ key with Stop shown on the screen. The computation stops, and the screen switches to the data display screen. The word MATH in the status display clears.

Math= <mark>St</mark>	op	

### Resetting the Computed Values of All Computation Channels to 0

This operation can be executed only when the computation is stopped.

- 1. Press the OFUNC key.
- **2.** Press the  $\nabla \Delta$  key to show **Math** and then press the  $\triangleleft$  key.
- Press the \sigma A key to show Reset and then press the <⊨ key. The computed values of all computation channels are reset, and the screen switches to the data display screen.



When the  $\triangleleft \triangleright$  key or  $\bigtriangledown \triangle$  key is pressed while holding down the SHIFT key, the operation is reversed as when the respective key is pressed by itself.

## 9.2 Setting the Computing Equation

The computing equation cannot be entered when the computation is in progress. If you change the computing equation or the recording span, set the alarm and the partial expanded recording again.

### Procedure

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\triangleleft$  key.
- **3** Press the <--- key with **Formula** shown on the screen.
- 4. Set each item and press the < key.</li>
  Use the ∇△ key or SHIFT + ∇△ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC/? key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC/? key.
- 6. Hold down the MENU key for 3 seconds to return to Operation mode.

Set= <mark>Math</mark>	
Math=Formula	
	Set the channel range.
First channel Last channel	]
Mode= <mark>Off</mark>	Select On to use the computing equation.
f.= <mark>01</mark>	Set the equation.
Span_L= -200.00	Set the left span value.
Span_R= 200.00	Set the right span value.
♥ 0A-0A Channel	The new setting takes effect.
ESC/? Setting complete	

### Setting the Computing Equation

The **CHARACTER**,  $\bigtriangledown \triangle$ , and  $\lhd \triangleright$  keys are used to set the computing equation. Use the  $\lhd \triangleright$  key or **SHIFT** +  $\lhd \triangleright$  key to select the position for entering a character. Use the **CHARACTER** key or **SHIFT** + **CHARACTER** key to select the character type. Use the  $\bigtriangledown \triangle$  key or **SHIFT** +  $\bigtriangledown \triangle$  key to select the character. Each time you press the **CHARACTER** key the display changes as shown below. Pressing the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key switches the character within the selected character type and displays the character at the cursor position.

Display (CHARACTER key)	Description	Character (∇∆ key)
01	Measurement channel	Pen model: 01 to 04
	numnber	Dot model: 01 to 06
0A	Computation channel	Pen model: 0A, 0B, 0C, 0D, 0E, 0F, 0G, 0J
	number	Dot model: 0A, 0B, 0C, 0D, 0E, 0F, 0G, 0J,
		0K, 0M, 0N, 0P
+, -, *, /	Symbol and space	+, -, *, /, (, ), space
Function	Function	SQR(, ABS(, LOG(, EXP(, .EQ., .NE., .GT.,
		.LT., .GE., .LE., AND, NOT, XOR, OR,
		TLOG.AVE(, TLOG.MAX(, TLOG.MIN(,
		TLOG.SUM(, TLOG.P-P(, space
K01-K30	Constant	K01 to K30
D01-D05	Status of the remote	D01 to D05
		control terminals
C01-C12	Communication input data	Pen model: C01 to C08
		Dot model: C01 to C12
Ins DISP	Insert a character	
Del DISP	Delete a character	
Clear DISP	Delete the entire string	
Copy DISP	Store the entire string in	
	the memory	
Past DISP	Paste the string in the	
	memory	

### **Inserting a Character**

Press the  $\triangleleft \triangleright$  key or **SHIFT** +  $\triangleleft \triangleright$  key to move the cursor to the position where the character is to be inserted.

Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Ins DISP** and then press the  $\nabla \Delta$  key. A space for one character is inserted. Enter the character.

### **Deleting a Character**

Use the  $\triangleleft \triangleright$  key or **SHIFT** +  $\triangleleft \triangleright$  key to move the cursor to the character to be deleted. Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Del DISP** and then press the  $\neg \Delta$  key. The character is deleted.

### **Deleting an Entire Character String**

Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Clear DISP** and then press the  $\nabla \Delta$  key. The entire character string is deleted.

### **Copying & Pasting a Character String**

Show the copy source character string.

Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Copy DISP** and then press the  $\nabla \Delta$  key. The character string is saved to the memory.

Show the copy destination.

Press the **CHARACTER** key or **SHIFT** + **CHARACTER** key to show **Paste DISP** and then press the  $\nabla \Delta$  key. The character string is pasted.

### Explanation

### **Computing Equation**

- Follow the rules below when writing computing equations.
- Use up to 120 characters to write equations.
- The precedence of computing terms can be specified using parentheses.
- Specify the channels in the equation using 2-digit channel numbers. Example: 01, 0A
- Specify the constants (K), communication input data (C), and remote control input terminal status (D) in the computing equation using 2-digit numbers.
   Example: K01, C01, D01
- The data value for its own channel and channels that are greater in number than its own channel are substituted with the data from the previous scan.

### Order of Precedence in Computations

The order of precedence of computation in equations is as follows:

Туре	Operator
	(high order of precedence)
Function	ABS(), SQR(), LOG(), EXP(), TLOG.MAX(),
	TLOG.MIN(), TLOG.P-P(), TLOG.SUM(), TLOG.AVE()
Power	**
Logical negation	NOT
Multiplication and division	*, /
Addition and subtraction	+,
Greater than and less than	.GT., .LT., GE., LE.
Equal and not equal	.EQ., .NE.
Logical product	AND
Logical sum and exclusive logical sum	OR, XOR
	(low order of precedence)

### Data That Can Be Used in Equations

In TLOG computation, the measured values of measurement channels or computed values of computation channels can only be used. For all other computations, all of the data types below can be used.

- Measured Values on Measurement Channels
   Specified by the channel number. For channels that have linear scaling enabled, the
   scaled values are used in the computation.
   Pen model: 01 to 04, dot model: 01 to 06
- Computed Values on Computation Channels Specified by the channel number.
   Pen model: 0A, 0B, 0C, 0D, 0E, 0F, 0G, 0J
   Dot model: 0A, 0B, 0C, 0D, 0E, 0F, 0G, 0J, 0K, 0M, 0N, 0P
- Constants (K01 to K30)
   Enter the values as K01 to K30 in the equations.
   Range of values (maximum significant digits is 5):
   -9.9999E+29 to -1.0000E-30, 0, 1.0000E-30 to 9.9999E+29
- Communication Input Data (Pen model: C01 to C08, dot model: C01 to C12)

Enter the data as C01 to C12 in the equations.

Range of values (maximum significant digits is 5):

-9.9999E+29 to -1.0000E-30, 0, 1.0000E-30 to 9.9999E+29

For the procedure of setting the communication input data, see the  $\mu R10000/\mu R20000$ Communication Interface User's Manual (IM04P01B01-17E). • Status of the Remote Control Input Terminal (D01 to D05, /R1 option) The status of the remote control input signal (1 or 0) can be used in the computation. Use D01 to D05 (the number following the letter D is the remote control input terminal number) to specify the status in the equations.

### **Four Arithmetic Operation**

The data that can be used in equations are measured values, computed values, constants, communication input data, and remote control input terminal status.

### **Equation Examples**

- Addition 01+02
  - (Determines the sum of the measured values of channel 1 and channel 2.)
  - Subtraction 01-02
    - (Determines the difference of the measured values of channel 1 and channel 2.)
  - Multiplication 01\*K03
- (Multiplies constant K03 to the measured value of channel 1.)Division 01/K02
  - (Divides the measured value of channel 1 by constant K02.)

### Note \_

By setting an equation similar to the one shown below, you can determine the accumulation of a specified channel (in this case channel 01) and make the result the computed value of computation channel 0A.

Computing equation of computation channel 0A: 0A+01

### **Power and Other Computations**

The data that can be used in equations are measured values, computed values, constants, communication input data, and remote control input terminal status. You can nest a computing element inside the parentheses of another computing element.

### **Equation Examples**

Equation Example	
<ul> <li>Power</li> </ul>	01**02
	(Determines the measured value of channel 1 to the power of
	the measured value of channel 2.)
<ul> <li>Square root</li> </ul>	SQR(02)
	(Determines the square root of the measured value of channel
	2.)
<ul> <li>Absolute value</li> </ul>	ABS(02)
	(Determines the absolute value of the measured value of
	channel 2.)
Common logarithr	n LOG(01)
	(Determines the common logarithm (log10) of the measured
	value of channel 1.)
<ul> <li>Exponent</li> </ul>	EXP(01)
	(Determines e to the power of the measured value of channel 1.)
Note	
You can determine	the natural logarithm by setting an equation like the following.
From log <sub>b</sub> X = log <sub>a</sub> >	/loga, we obtain logeX = log10X/log10e
Hence, to determin	e the natural logarithm of channel 1, we set
Constant	$K01 = 0.43429(log_{10}e)$ , and
Computing equ	ation LOG(01)/K01.

### Relational Computation

The data that can be used in equations are measured values, computed values, constants, communication input data, and remote control input terminal status. You can specify a computing equation that performs relational computation on a computing element. (Example: 01.LT.ABS(02))

### **Equation Examples**

#### 02.LT.03

If the measured value of channel 2 is less than the measured value of channel 3, the computed result is "1." Otherwise, the result is "0."

#### 02.GT.03

If the measured value of channel 2 is greater than the measured value of channel 3, the computed result is "1." Otherwise, the result is "0."

#### 02.EQ.03

If the measured value of channel 2 is equal to the measured value of channel 3, the computed result is "1." Otherwise, the result is "0."

#### 02.NE.03

If the measured value of channel 2 is not equal to the measured value of channel 3, the computed result is "1." Otherwise, the result is "0."

### 02.GE.03

If the measured value of channel 2 is greater than or equal to the measured value of channel 3, the computed result is "1." Otherwise, the result is "0."

#### 02.LE.03

If the measured value of channel 2 is less than or equal to the measured value of channel 3, the computed result is "1." Otherwise, the result is "0."

### Logical Computation

Checks whether the two data values, e1 and e2 (e1 only for NOT), are zeroes or non-zeroes, and computes according to the conditions. The data that can be used in equations are measured values, computed values, constants, communication input data, and remote control input terminal status. You can specify a computing equation that performs logical computation on a computing element.

### AND

Logical Product		
(Syntax)	e1ANDe2	
(Condition)	If the two data values e1 and e2 are both non-zeroes, the computed result is "1." Otherwise, it is "0."	
(Explanation)	e1 = 0 $e2 = 0 \rightarrow$	e1ANDe2 = 0
	$\begin{array}{c} e1 \neq 0 \\ e2 = 0 \end{array} \longrightarrow$	e1ANDe2 = 0
	$\begin{array}{c} e1 = 0 \\ e2 \neq 0 \end{array} \longrightarrow$	e1ANDe2 = 0
	$\begin{array}{c} e1 \neq 0 \\ e2 \neq 0 \end{array} \longrightarrow$	e1ANDe2 = 1

### OR

 Logical sum

 (Syntax)
 e1ORe2

 (Condition)
 If the two data values e1 and e2 are both zeroes, the computed result is "0." Otherwise, it is "1."

 (Explanation)
 e1 = 0

 e10Pe2 = 0

$e2 = 0 \xrightarrow{\rightarrow}$	e10Re2 = 0
$e1 \neq 0$ e2 = 0 $\rightarrow$	e10Re2 = 1
$\begin{array}{c} e1 = 0 \\ e2 \neq 0 \end{array} \longrightarrow$	e10Re2 = 1
$\begin{array}{c} e1 \neq 0 \\ e2 \neq 0 \end{array} \longrightarrow$	e10Re2 = 1

### XOR

Exclusive OR		
(Syntax)	e1XORe2	
(Condition)	If the two data values e1 and e2 are zero and non-zero or non-zero and zero, the computed result is "1." Otherwise, it is "0."	
(Explanation)	e1 = 0 $e2 = 0 \rightarrow$	e1XORe2 = 0
	$\begin{array}{c} e1 \neq 0 \\ e2 = 0 \end{array} \rightarrow$	e1XORe2 = 1
	$\begin{array}{c} e1 = 0 \\ e2 \neq 0 \end{array} \rightarrow$	e1XORe2 = 1
	$\begin{array}{c} e1 \neq 0 \\ e2 \neq 0 \end{array} \longrightarrow$	e1XORe2 = 0

### NOT

Logical negation(Syntax)NOTe1(Condition)The result is the inverse of the status of data e1 (zero or non-zero).(Explanation) $e1 = 0 \rightarrow NOTe1 = 1$  $e1 \neq 0 \rightarrow NOTe1 = 0$ 

# Equation Example 01-02OR03.GT.04

Determines the OR of the computed results of "01-02" and "03.GT.04".

### **TLOG Computation**

Only measured values and computed values can be used in TLOG computation. In the explanation below, e1 is used to represent a measurement or computation channel. You cannot specify an equation that contains a computing element inside e1. In addition, only one TLOG computation can be specified in a single computing equation.

### TLOG.MAX()

Maximum value (Syntax) TLOG.MAX(e1) (Condition) Determines the maximum value of channel e1.

### TLOG.MIN()

Minimum value (Syntax) TLOG.MIN(e1) (Condition) Determines the minimum value of channel e1.

### TLOG.AVE()

 Average value

 (Syntax)
 TLOG.AVE(e1)

 (Condition)
 Determines the average value of channel e1.

### TLOG.SUM()

Sum value(Syntax)TLOG.SUM(e1)(Condition)Determines the sum of channel e1.

### TLOG.P-P()

Maximum – minimum value(Syntax)TLOG.P-P(e1)(Condition)Determines the maximum – minimum value of channel e1.

#### **Equation Example**

TLOG.MAX(01) + K01\*SQR(02)

### **Examples of Equations That Are Not Allowed**

TLOG.AVE(01) + TLOG.AVE(02) Reason: TLOG appears twice in one equation.

TLOG.AVE(ABS(01)) Reason: A computing element is used inside the parentheses.

# 9.3 Setting the Unit

This section explains the details of setting the unit on computation channels.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\triangleleft \forall$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Unit** and then press the  $\triangleleft$  key.
- 4. Set each item and press the < key.</li>
  Use the ∇△ key or SHIFT + ∇△ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊢ key to set other channels.</li>
   If you are done, press the ESC key.
- 6. Hold down the (MENU) key for 3 seconds to return to Operation mode.

Set=Math	
CH=OA-OA First channel Last channel	Set the channel range.
Unit=	Set the unit.
OA-OA Channel <b>ESC</b> /? Setting complet	✓ The new setting takes effect.

### Explanation

### **Characters That Can Be Used for Units**

Set the unit using up to 6 characters.

The available characters are as follows:


Alphabet, numbers, symbols (%, #, °, @, +, -, \*, /, (, ),  $\mu$ ,  $\Omega$ , <sup>2</sup>, <sup>3</sup>, .), and space

### 9.4 Setting the Constants Used in Equations

This section explains the details of setting constants to be used in computing equations.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\triangleleft \forall$  key.
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\\$ key or SHIFT + \\$\Delta\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the (MENU) key for 3 seconds to return to Operation mode.



### Explanation

### Constant


Up to 30 constants can be registered. Enter the values as K01 to K30 in the equations. Set the constants in the range shown below. The maximum number of significant digits is 5. -9.9999E+29 to -1.0000E-30, 0, 1.0000E-30 to 9.9999E+29

# 9.5 Setting the Alarm

This section explains the details of setting alarms for each computation channel. If you change the computing equation or the recording span, set the alarm again.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- **2.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\triangleleft$  key.
- 4. Set each item and press the <⊨ key. Use the \\$\Delta\\$ key or SHIFT + \\$\Delta\\$ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the (MENU) key for 3 seconds to return to Operation mode.



### 9.5 Setting the Alarm

### Explanation

e	
Name	
High limit alarm	
Low limit alarm	
Delay high limit alarm*	
Delay low limit alarm*	
	Name High limit alarm Low limit alarm Delay high limit alarm*

\* Selectable only when the alarm delay function is enabled. See section 7.15.

If delay high limit alarm or delay low limit alarm is specified, set the alarm delay time.

### <Related Topics>

Setting the delay time of the delay high limit alarm or delay low limit alarm: Section 9.11 Enabling the alarm delay function: Section 7.15 Setting the alarm hysteresis: Section 7.1

### **Alarm Value**

Can be set to a value in the range of –99999999 to 99999999 excluding the decimal (–99999999 to 999999999 is the displayable range).

### Relay No.

The selectable relay numbers are listed below.

I01 and I02 on the /A1 option

- 101, 102, 103, and 104 on the /A2 option
- 101, 102, 103, 104, 105, and 106 on the /A3 option

### 9.6 Specifying the Timer Used in Statistical Calculations (TLOG)

On channels that perform statistical calculation (TLOG), the timer for determining the interval is specified. The sum scale is also specified when using statistical calculation. The timer is also used for the periodic printout of computed values.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Math and then press the  $\triangleleft$  key.
- Press the \\\\Delta \Log key or SHIFT + \\\Delta \Log key to select TLOG and then press the <\\\= key.</li>
- 4. Set each item and press the <- key. Use the \scale \
- When the Setting complete screen appears, do either of the following: Press the <⊢ key to set other channels. If you are done, press the ESC key.
- 6. Hold down the (MENU) key for 3 seconds to return to Operation mode.

Set= <mark>Math</mark>	
Math=TLOG	
CH= <mark>0A</mark> -0A	Set the channel range.
First channel Last channel	
Timer No=Periodic	Select the timer number (Periodic, 1, or 2).
	a
SUM scale= <mark>Off</mark>	Select the sum scale.
	a
♥ 0A-0A Channel	┘ ]The new setting takes effect.
ESC/? Setting complete	_

### Explanation

### Timer No.

There are three timers.

- Periodic: The timer for determining the periodic printout interval. The computed result is printed every interval, and the computed TLOG value is reset.
- 1: The timer of timer No. 1. Specify whether the computed value is printed every interval and whether to reset the computed value.
- 2: The timer of timer No. 2. Specify whether the computed value is printed every interval and whether to reset the computed value.

### Timer operation

The table below shows how each timer operates.

Item Timer #	Periodic	1 and 2*
Application	Periodic	TLOG computation
Target channel	Measurement and computation channels	Computation channels
Timer mode**	Absolute time mode	Absolute or relative time mode
Reset computed TLOG value	Yes	Yes/No selectable
Print when computation stops	No	Yes

\* For the timer 1 and 2 settings, see section 9.12.

\*\* Absolute time mode: Keeps time from the reference time.Relative time mode: Starts the time in sync with the starting of the computation.

### SUM scale

Set the sum scale when using statistical calculation (TLOG.SUM).

For the definition of the term "sum scale," see page 7-14.

- Off: Simply sums the computed values.
- /s: Sums by converting the computed values to a value over 1 second.
- /min: Sums by converting the computed values to a value over 1 minute.
- /h: Sums by converting the computed values to a value over 1 hour.
- /day: Sums by converting the computed values to a value over 1 day.

<Related Topics> Setting the periodic printout timer: Section 7.8 Setting Timer 1 and Timer 2: Section 9.12

# 9.7 Setting Recording Zones for Each Channel (Zone Recording)

This section explains the details of setting the recording zone for each computation channel.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Math and then press the  $\triangleleft$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\triangleleft$  key.
- **4.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Zone** and then press the  $\triangleleft$  key.
- 5. Set each item and press the < key.</li>
  Use the ∇△ key or SHIFT + ∇△ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 7. Hold down the (MENU) key for 3 seconds to return to Operation mode.

Set= <mark>Math</mark>	
Math=Aux	
Aux= <mark>Zone</mark>	
CH= <mark>0A</mark> -0A	Set the channel range.
First channel Last channel	
Left=0	Set the leftmost value of the recording zone.
Right=100	Set the rightmost value of the recording zone.
CA-OA Channel ESC/? Setting complete	The new setting takes effect.

### **Explanation**

#### Zone

The recording zone can be set in the following range.

Leftmost position: 0 mm to 95 mm

Rightmost position: 5 mm to 100 mm

Set a larger value for the rightmost position than the leftmost position.

Set at least 5 mm for the zone width.

### Note \_

If the zone is set to a value less than 40 mm, scale printout of periodic printout cannot be executed.

9

**Operations Related to the Computation Function (/M1 Option)** 

### 9.8 Setting the Partial Expanded Recording


This section explains the details of expanding a section of the recording range. If you change the computing equation or the recording span, set the partial expanded recording again.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Math and then press the  $\triangleleft$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\langle \exists$  key.
- 4. Press the \(\nabla \Leq \key\) or SHIFT + \(\nabla \Leq \key\) to select Partial and then press the \(\neq \Leq \key\).
- **5.** Set each item and press the  $\triangleleft$  key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 7. Hold down the MENU key for 3 seconds to return to Operation mode.



<Related Topics> Enabling the partial expanded recording function: Section 7.13

9.9 Turning Trend Recording (Dot Model) and Periodic Printout (Including the Printout Using the TLOG Timer) ON/OFF for Each Channel


This section explains the details of setting the trend recording and periodic printout for each computation channel.

The following settings can be entered for each channel.

- Turn trend recording ON/OFF (dot model only).
- Turn the printing of computed values ON/OFF during periodic printout.

### Procedure

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Math and then press the  $\lt \exists$  key.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Aux and then press the  $\triangleleft$  key.
- 4. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Print out and then press the  $\prec \exists$  key.
- 5. Set each item and press the <≓ key. Use the ∇∆ key or SHIFT +∇∆ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 7. Hold down the MENU key for 3 seconds to return to Operation mode.



### Explanation

### **Periodic Printout**

- On: Prints the computed values (instantaneous values or report data) of the specified channel during periodic printout.
- Off: Does not print the channels and computed values during periodic printout.

9

**Operations Related to the Computation Function (/M1 Option)** 

## 9.10 Setting Tags on Channels

This section explains the details of setting the tag on computation channels.

### Procedure

- 1. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Math and then press the  $\triangleleft \forall key$ .
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\langle \dashv$  key.
- 4. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Tag and then press the  $\triangleleft$  key.
- 5. Set each item and press the <⊨ key.</li>
  Use the \\$\scrime{\s\scrime{\strime{\scrime{\s\scrime{\strime{\strime{\scrime{\strime{\s\scrime{\strme{\strme{\strime{\strme{\strime{\strime{\strme{\strime{\strime{
- When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels. If you are done, press the ESC key.
- 7. Hold down the (MENU) key for 3 seconds to return to Operation mode.

Set= <mark>Math</mark>	
Math= <mark>Aux</mark>	
¥ Aux= <mark>Tag</mark>	
CH= <mark>OA</mark> -OA	Set the channel range.
First channel Last channel	
Tag=	Set the tag.
[	
0A-0A Channel	The new setting takes effect
ESC/? Setting complete	

### Explanation

### Characters That Can Be Used for Tags

Set the tag using up to 7 characters.

The available characters are as follows:

Alphabet, numbers, symbols (%, #, °, @, +, –, \*, /, (, ),  $\mu$ ,  $\Omega$ , <sup>2</sup>, <sup>3</sup>, .), and space

<Related Topics> Printing tags in place of channel numbers: Section 7.7 Displaying tags in place of channel numbers: Section 8.2

## 9.11 Setting the Alarm Delay Duration

This section explains the details of setting the duration of the delay high limit and delay low limit alarms.

### Procedure

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- 2. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Math and then press the  $\triangleleft$  key.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Aux** and then press the  $\langle \exists key \rangle$ .
- 4. Press the \u2275 key or SHIFT + \u2275 key to select Alm delay T and then press the <\u2272 key.</p>
- 5. Set each item and press the <≓ key. Use the ∇∆ key or SHIFT + ∇∆ key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels. If you are done, press the ESC key.
- 7. Hold down the (MENU) key for 3 seconds to return to Operation mode.

Set= <mark>Math</mark>	
Math= <mark>Aux</mark>	
Aux=Alm delay T	
CH=0A-0A	Set the channel range.
First channel Last channel	]
Duration= 10	Set the alarm delay time.
	]
0A-0A Channel	The new setting takes effect.
ESC/? Setting complete	

### Explanation

### Duration

The duration can be set to a value in the range of 1 to 3600 s. However, if the scan interval on the dot model is 2.5 s, the actual duration is an integer multiple of 2.5 s. If the set value is not equal to an integer multiple of 2.5 s, the duration is the smallest integer multiple of 2.5 s greater than the set value. Example: The actual duration for 1 s and 2 s is 2.5 s.

<Related Topics> Enabling the alarm delay function: Section 7.15

### 9.12 Setting the Timer Used in TLOG Computation and Periodic Printout

This section explains the details of setting the timer used in TLOG computation and periodic printout.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


### Procedure

### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\prec \exists$  key.
- 4. Press the <- key with Timer (TLOG) shown on the screen.
- **5.** Set each item and press the  $\triangleleft$  key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 6. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊨ key.</li>
 If you are done, press the ESC key.



IM 04P01B01-01E

### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

### Explanation

### Timers

Timer features

- The timer determines the interval used to calculate the report data (the average, minimum, maximum, sum value), etc.
- The timer is also used to set the interval at which the computed values are printed on the chart paper.

### **Number of Timers**

There are two timers: Timer No. 1 and 2. The timer that is used can be set for each channel.

### **Timer Type**

There are two timer modes, absolute time mode and relative time mode. For absolute time mode timers, set the reference time and interval; for relative time mode timers, set the interval.

### • Absolute (Absolute Time Mode)

After the computation is started, the timer times out at the times determined by the reference time (on the hour) and the interval. The **Ref. Time** (reference time) is set on the hour (00 to 23).

Example 1: Reference time: 14:00

Interval: 12h

The timeout times are hour 2 and hour 14.

Example 2: Reference time: 00:00

Interval: 10min

The timeout times are 0 hour, 0 hour 10 min, 0 hour 20 min, ... 23 hour 40 min, and 23 hour 50 min. For example, if computation is started at 9 hour 36 min, the timeout times are 09 hour 40 min, 09 hour 50 min, 10 hour, and so on.

### Relative (Relative Time Mode)

The clock is started in sync with the starting of the computation, and the timer times out every specified interval. In this mode, the timer and the clock stop when a power failure occurs.

Example: Interval: 00:15

The timer times out every 15 minutes after the computation is started.

### • Off

If Off is selected, the TLOG computation continues, but reset and printout are not performed. To reset computed result, use the remote control function (/R1 option) or carry it out manually (using the FUNC key).


### Interval

Select from 10, 12, 15, 20, 30min, 1, 2, 3, 4, 6, 8, 12, and 24h.

<Related Topics> Setting the timer to be used for each channel: Section 9.6 Resetting the computation remotely: Section 7.18 Resetting the computation manually: Section 9.1

### Reset

Selects whether to reset the TLOG computed value at each interval. The figure below illustrates the reset operation for sum computation (TLOG.SUM).



When reset is ON, the sum value is calculated over each interval. When set to Off, the sum value from computation start is calculated.

### Print

- On: Prints the computed value every interval specified by the timer. Computation channels set to Off do not apply.
- Off: Does not print.

# 9.13 Changing the Channel Recording Color (Dot Model)


This section explains the details of changing the recording colors of computation channels.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

### Procedure

### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and < > keys simultaneously for 3 seconds to enter Basic Setting mode.
- 3. Press the  $\nabla \Delta$  key or SHIFT +  $\nabla \Delta$  key to select Math and then press the  $\triangleleft$  key.
- **4.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Color** and then press the  $\prec \exists$  key.
- **5.** Set each item and press the  $\triangleleft$  key.
  - Use the ∇△ key or SHIFT + ∇△ key to select values.
    For the procedure on how to enter values or characters, see section 4.2.
    If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 6. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊢ key.</li>
   If you are done, press the ESC key.



### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\triangleleft$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\triangleleft$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\triangleleft$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

### Explanation

#### Color

This section explains the details of changing the recording colors of computation channels.

The default values are as follows:

Purple: channel 0A, 0G, Red: channel 0B, 0J, Green: channel 0C, 0K, Blue: channel 0D, 0M, Brown: channel 0E, 0N, Black: channel 0F, 0P

# 9.14 Changing the Channel Assignments of Recording Pens (Pen Model)

Measurement channels and computation channels can be arbitrarily assigned to recording pens.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


### Procedure

### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and < > keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\triangleleft$  key.
- 4. Press the \\\\Delta \Lefta key or SHIFT + \\\Delta \Lefta key to select Output pen and then press the <\\\Press key.</p>
- **5.** Set each item and press the  $\triangleleft$  key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 6. When the Setting complete screen appears, do either of the following: To correct the setting, press the <⊨ key.</li>
 If you are done, press the ESC key.



### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

### Explanation

### Output pen

Measurement channels and computation channels can be arbitrarily assigned to recording pens.

The default values are as follows:

Pen No. 1 (red): Channel 01

- Pen No. 2 (green): Channel 02
- Pen No. 3 (Blue): Channel 03
- Pen No. 4 (violet): channel 04

### 9.15 Changing the Type of Report Data Printed in Periodic Printout

This section explains the details of selecting the type of report (the average, minimum, maximum, or sum) printed in periodic printout.

To print the report data during periodic printout, set the type of data to be printed to report (see section 7.8).

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


### Procedure

### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\triangleleft$  key.
- 4. Press the \\\\Delta \Lefta key or SHIFT + \\\Delta \Lefta key to select Print2 and then press the \\\Pm\\\\key.
- **5.** Set each item and press the  $\triangleleft$  key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

6. When the Setting complete screen appears, do either of the following: To correct the setting, press the <≓ key.</p>



### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

### Explanation

### Mode

Sets the type of report data to be printed.

- AVE: Prints the average value over the interval.
- MIX: Prints the minimum, maximum, and average values over the interval.
- SUM: Prints the sum value over the interval. If SUM is selected, set the sum scale.
- MIN: Prints the minimum value over the interval.
- MAX: Prints the maximum value over the interval.
- INST: Prints the instantaneous value.

### SUM scale

Set this item only when SUM is selected.

For the definition of the term "sum scale," see page 7-14.

- Off: Simply sums the computed values.
- /s: Sums by converting the computed values to a value over 1 second.
- /min: Sums by converting the computed values to a value over 1 minute.
- /h: Sums by converting the computed values to a value over 1 hour.
- /day: Sums by converting the computed values to a value over 1 day.
- <Related Topics> Setting the periodic printout interval and the type of data to be printed: Section 7.8

## 9.16 Setting the Bar Graph Display Mode


This section explains the details of setting the bar graph display mode. Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).

### Procedure

### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0191 and < \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\prec \exists$  key.
- 4. Press the \(\nabla \Leq \key \text{ or SHIFT} + \(\nabla \Leq \key \text{ to select Bar graph and then press the \(\leq \Leq \key. \)
- 5. Set each item and press the <≓ key.</li>
  Use the \\$\scrime{\sigma}\$ key or SHIFT + \\$\scrime{\sigma}\$ key to select values.
  For the procedure on how to enter values or characters, see section 4.2.
  If you press the ESC key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.
- 6. When the Setting complete screen appears, do either of the following: Press the <⊨ key to set other channels.

If you are done, press the **ESC** key.



### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

### Explanation

### Graph

- Normal: Sets the base point of the bar graph to the left or right of the recording span whichever is smaller in value.
- Center: Sets the base point of the bar graph to the 50% position of the recording span.

9

**Operations Related to the Computation Function (/M1 Option)** 

### 9.17 Setting the Procedure Taken When the Computed Result Is in Error

This section explains the details of setting the procedure taken when the computed result is in error.

Basic Setting mode cannot be entered when recording is in progress or when computation is in progress on models with the computation function (/M1 option).


### Procedure

### **Changing the Settings**

- 1. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and \u2172 keys simultaneously for 3 seconds to enter Basic Setting mode.
- **3.** Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **Math** and then press the  $\triangleleft$  key.
- 4. Press the \u2275 key or SHIFT + \u2275 key to select Error data and then press the \u2275 key.
- 5. Set each item and press the <- key.

Use the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select values. For the procedure on how to enter values or characters, see section 4.2. If you press the **ESC** key in the middle of the operation, the settings entered up to then are cancelled, and the display returns to a higher level menu.

 When the Setting complete screen appears, do either of the following: Press the <≓ key to set other channels. If you are done, press the ESC key.



### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

### Explanation

### Error

Specifies how to display or print the computed result when computation errors occur.

+Over: Set to +over. Displayed/Printed as "+Over."

-Over: Set to -over. Displayed/Printed as "-Over."

Computation that result in errors

- x/0
- SQR(-x)
- LOG(-x)
- When a channel set to Skip is included in the equation

#### Over

Selects the procedure when an "over" value<sup>\*</sup> is input for TLOG.SUM or TLOG.AVE computation.

- \* An "over" value on a measurement channel refers to +Over or –Over. See section 12.4. An "over" value on a computation channel refers to a value that is less than or equal to
- -100000000 or greater than or equal to 100000000 excluding the decimal.
- Skip: The "over" value is not used in the computation. Limit: The following limit value is used for the computation.

Channel	Limit Value
Measurement channel	<ul> <li>For scaling (1-5V, scaling, and square root)</li> </ul>
	-Over: -315000, +Over: 31500 (excluding the decimal)
	<ul> <li>For input types other than scaling</li> </ul>
	-Over: The minimum measurable value at the specified range type
	(Example: –2.000 at 2 V range)
	+Over: The maximum measurable value at the specified range type
	(Example: 2.000 at 2 V range)
Computation channel	-Over: -100000000, +Over: 100000000 (excluding the decimal)

### A List of Error Messages 10.1

There are cases in which error codes and messages are displayed on the screen during operation. The error messages and their description are listed below.

### **Setting Errors**

Code	Message	Explanation/Countermeasures	
1	System error.	Contact your nearest YOKOGAWA dealer.	
2	Incorrect date or time setting.	Check the setting.	
3	A disabled channel is selected.	The channel does not exist.	
4	Incorrect function parameter.	Incorrect communication parameter.	
5	The input numerical value exceeds the set range.	_	
6	Incorrect input character string.	The entered character cannot be used.	
7	Too many characters.		
8	Incorrect input mode.	Incorrect range mode (Volt, TC, Scale, etc.) setting.	
9	Incorrect input mode.	Incorrect range type (2 V, R, PT100, etc.) setting.	
10	Format error.	Incorrect character string format.	
11	Range settings are not same within the selected	Channels whose range differs cannot be set simultaneously.	
	channels.		
12	An invalid characters.	Contains an invalid character.	
13	Ref. CH error.	Specify a channel whose range is set to voltage, TC, or RTD for the reference channel.	
15	Too many characters for printout.	Too many characters in the message printout including	
		measured/computed values.	
16	Too many characters for message.	Cannot enter a setting that exceeds the message string (16 characters).	
21	Cannot set an alarm for a SKIPPED channel.	-	
22	The upper and lower span limits are equal.	This is not allowed.	
23	The upper and lower scale limits are equal.	This is not allowed.	
24	The lower span limit is greater than the upper span		
25	limit. The lower scale limit is greater than the upper scale limit.	-	
26	Bias cannot be set to the SKIPPED channel.	-	
27	Bias cannot be set to the DI channel.		
30	The partial boundary value exceeds the range of the	-	
50	span.		
31	Partial is invalid on the SKIPPED channel.	_	
35	The upper and lower limits of the printing zone are equal.	Set the rightmost value of the zone – the leftmost value $\ge$ 5 mm.	
36	The lower limit of the printing zone is greater	Set the rightmost value of the zone – the leftmost value $\ge$ 5 mm.	
37	than the upper limit. The printing zone is narrower than the minimum	Set the rightmost value of the zone – the leftmost value $\geq$ 5 mm.	
	width (5 mm).		
38	Partial is invalid on the DI channel.	-	
39	The bias and the calibration cannot be used simultaneously.	-	
40	Datume value (1 >= 2)	Set the correction point (measured value) of the first point less than that of the second point in the calibration correction.	
41	Datume value (n-1 > n)	Set the correction point (measured value) of the n–1 <sup>th</sup> point less than or equal to that of the n <sup>th</sup> point in the calibration correction.	
42	Revise value (n-1 >= n)	Set the correction value of the n–1 <sup>th</sup> point less than that of the n <sup>th</sup> point in the calibration correction.	
47	All items in DISP menu parameters are set to SKIP.	-	
48	Start = Finish.	The DST start time and end time cannot be set to the same time.	
49	Invalid or missing DST time settings.	Since the time gains one hour when the DST starts, the set-up	
61	There is no channel specified by the MATH	time does not exist. Set a computation channel.	
	expression.		
62	MATH expression grammar is incorrect.	Enter the equation correctly.	
63	MATH expression sequence is incorrect.	Enter the equation correctly.	

### 10.1 A List of Error Messages

Code	Message	Explanation/Countermeasures		
64	MATH upper and lower span values are equal.	This is not allowed.		
70	MATH constant description is incorrect.	Incorrect computation constant syntax.		
71	The range of the MATH constant is exceeded.	-		
72	MATH channel is turned off	-		
81	All space or 'quit' string cannot be specified.	-		
86	The key-lock release password is incorrect.	Enter the correct password.		
87	This key is locked.	-		
91	Password is incorrect.	Enter the correct password.		
100	IP address doesn't belong to class A, B, or C.	-		
101	The result of the masked IP address is all 0s or 1s.	-		
102	SUBNET mask is incorrect.	Set a correct subnet mask.		
103	The net part of default gateway is not equal to	Set the correct default gateway.		
	that of IP address.			
151	This action is invalid during calculation.	-		
160	This action is invalid during chart end.	-		
161	This action is invalid during pen hold.	-		
162	Cannot set an number for a skipped data.	-		
163	This action is invalid during record.	-		
164	This action is invalid during manual printing.	-		
165	This action is invalid during list printing.	-		
166	This action is invalid during setup list printing.	-		
167	This action is invalid during chart feed.	-		
169	This action is invalid during ribbon hold.	-		
170	This action is invalid during priority remote record.	Recording stop via communications or key operation cannot be		
		accepted under the current settings. Perform the Stop using the		
		remote control function.		
171	This action is invalid during batch.	Cannot enter Basic Setting mode during header printout (until		
		End printout is finished).		

### **Operation Errors**

Code	Message	Explanation/Countermeasures
232	There is no available data.	There is no data for periodic printout or data for calculating
		TLOG when the timer expired.

### **Communication Errors**

Code	Message	Explanation/Countermeasures	
300	Command is too long.	-	
301	Too many number of commands delimited with ';'.	Keep the number of commands separated by sub delimiters under 10.	
302	This command has not been defined.	-	
303	Data request command can not be enumerated with sub-delimiter.	-	
350	Command is not permitted to the current user level.	-	
351	This command cannot be specified in the current mode.	_	
352	The option is not installed.	-	
353	This command cannot be specified in the current setting.	-	
354	This command is not available during calculation.	-	
390	Command error.	-	
391	Delimiter error.	-	
392	Parameter error.	-	
393	No permission.	-	
394	No such connection.	-	
395	Use "quit" to close this connection.	Attempted to disconnect its own connection.	
396	Failed to disconnect.	-	
397	No TCP control block.	The control block of the specified connection cannot be found.	
400	Input username.	-	
401	Input password. –		

Code	Message	Explanation/Countermeasures
402	Select username from 'admin' or 'user'.	If the recorder is configured not to use the user name and password, use user names 'admin' or 'user'.
403	Login incorrect, try again!	_
404	No more login at the specified level is acceptable.	-
420	Connection has been lost.	-
421	The number of simultaneous connection has been exceeded.	-
422	Communication has timed-out.	_

### Warning Messages


	0	0
Code	Message	Explanation/Countermeasures
600	Initialized.	Settings and measured data have been initialized.


### System Errors

Message	Explanation/Countermeasures
RAM failure.	Contact your nearest YOKOGAWA dealer.
A/D error.	Contact your nearest YOKOGAWA dealer.
A/D calibration value error.	Contact your nearest YOKOGAWA dealer.
A/D calibration is in the wrong order.	Contact your nearest YOKOGAWA dealer.
Memory acquisition failure.	Contact your nearest YOKOGAWA dealer.
The ethernet module is down.	Contact your nearest YOKOGAWA dealer.
A/D number error.	Contact your nearest YOKOGAWA dealer.
EEPROM write error.	Contact your nearest YOKOGAWA dealer.
Ribbon error	Contact your nearest YOKOGAWA dealer.
Printer error	Contact your nearest YOKOGAWA dealer.
Plotter error	Contact your nearest YOKOGAWA dealer.
Pen 1 error	Contact your nearest YOKOGAWA dealer.
Pen 2 error	Contact your nearest YOKOGAWA dealer.
Pen 3 error	Contact your nearest YOKOGAWA dealer.
Pen 4 error	Contact your nearest YOKOGAWA dealer.
(No messages)	Contact your nearest YOKOGAWA dealer.
(No messages)	Contact your nearest YOKOGAWA dealer.
	RAM failure.         A/D error.         A/D calibration value error.         A/D calibration is in the wrong order.         Memory acquisition failure.         The ethernet module is down.         A/D number error.         EEPROM write error.         Ribbon error         Printer error         Plotter error         Pen 1 error         Pen 3 error         Pen 4 error         (No messages)


# **10.2 Troubleshooting Flow Charts**

Follow the flow charts to correct the problem.





#### **10.2 Troubleshooting Flow Charts**




# 11.1 Periodic Inspection


Check the operation periodically to keep the recorder in good working order. Perform the following checks and replace worn parts as needed.

- Is the indication and recording functioning properly? If not, see chapter 10.
- Are recorded lines or printed characters clear (not blurred)?
  - For the replacement procedure of felt pens and plotter pens, see section 3.3 (pen model).

For the replacement procedure of the ribbon cassette, see section 3.4 (dot model).

- Is the chart paper feeding properly (no paper jams)? If not, see chapter 10.
- Is there enough chart paper remaining? Remaining chart length is printed on the left margin of the chart at intervals of 20 cm. For the chart paper replacement procedure, see section 3.2.





# 11.2 Cleaning the Recorder

## CAUTION


- When cleaning, be sure not to scratch the flexible printed circuit board of the plotter carriage.
- Do not apply lubricating oil to the shaft.

## Pen Model

To maintain smooth operation, it is recommended that the plotter carriage shaft be cleaned once a year.


#### **Cleaning Procedure**

Wipe the dust off the plotter carriage shaft using a soft lint-free cloth or paper. If the dirt does not come off easily, apply ethyl alcohol to the cloth or paper.



## **Dot Model**

To maintain smooth operation, wipe the dust off the two shafts of the printer carriage using a soft lint-free cloth or paper. It is recommended that these shafts be cleaned once a year.



# 11.3 Replacing the Internal Light LED


If the brightness of the internal light degrades with time, replace the LED. For the replacement parts, see section 11.7.

## CAUTION


- The LED is connected to the internal circuitry through the flexible printed circuit board. Do not pull the LED with force.
- · Be sure not to break the flexible printed circuit board.

#### **Replacement Procedure**

- 1. Open the door and turn OFF the power switch.
- 2. Open the display and key panel section.
- Pull out the internal light LED assembly that is attached to the end of the display and key panel section.




4. Remove the LED assembly from the connector of the flexible printed circuit board.



- 5. Connect the new LED assembly.
- **6.** Push the LED assembly back into the display and key panel section. Be sure not to bend or scratch the flexible printed circuit board.

Stored condition of the flexible printed circuit board



**7.** Turn the power switch ON and check that the internal light comes on a few seconds later.

# 11.4 Calibrating the Recorder

Calibrate the measured value against the input.

It is recommended that the recorder be calibrated once a year to assure its measurement accuracy.

For details regarding calibration, contact your nearest YOKOGAWA dealer.

## **Required Instruments**

A calibration instrument with appropriate resolution is required for calibrating the recorder.

#### **Recommended Instrument**

- DC voltage standard: Model 9100 by FLUKE or equivalent
  - Main Specifications

Output accuracy:  $\pm (0.005\% + 1 \mu V)$ 

Decade resistance box: Yokogawa Meters & Instruments Model 2793-01 or equivalent
 Main Specifications

Accuracy of output range 0.1 to 500  $\Omega$ : ±(0.01% + 2 m $\Omega)$  Resolution: 0.001  $\Omega$ 

 0°C standard temperature device: ZC-114/ZA-10 by Coper Electronics or equivalent Main Specifications

Standard temperature stability accuracy: ±0.05°C

For information on purchasing the calibration instruments, contact your nearest YOKOGAWA dealer.

### **Calibration Procedure**


- **1.** Wire the recorder and the calibration instrument as shown in the following figure, and adequately warm up the instruments (the warm-up time of the recorder is at least 30 minutes).
- **2.** Check that the operating environment such as ambient temperature and humidity is within the normal operating conditions (see section 12.6).
- **3.** Apply appropriate input signals corresponding to 0%, 50%, and 100% of the input range and calculate the errors from the readings.


If the error is outside the accuracy specifications, contact your nearest YOKOGA-WA dealer.

#### Note.


For thermocouple inputs, you must measure the temperature of the input terminal and apply a voltage taking into account the reference junction temperature.

### DC Voltage Measurement





Input terminals



(0°C standard temperature device ZC-114/ZA-10 by Coper Electronics)

#### **RJC of TC input**

As the measurement terminal of the recorder is generally at room temperature, the actual output of the thermocouple is different from the values given on the thermoelectromotive force table based on 0°C. The recorder performs compensation by measuring the temperature at the input terminal and adding the corresponding thermoelectromotive force to the actual output of the thermocouple. Therefore, when the measurement terminal is shorted (equivalent to the case when the detector tip is 0°C), the measured value indicates the temperature of the input terminal.

When calibrating the recorder, this compensation voltage (thermoelectromotive force of 0°C reference corresponding to the input terminal temperature) must be subtracted from the output of the DC voltage standard before application. As shown in the figure, by using the 0°C standard temperature device to compensate the reference junction at 0 °C, you can input the thermoelectromotive force of 0 °C reference from the DC voltage standard and perform the calibration.

# 11.5 Adjusting the Pen Position (Pen Model)

This section explains the details of adjusting the pen position on the chart paper. It is recommended that the pen be adjusted once a year to assure its recording accuracy.

#### Note -

Pen position is adjusted under standard operating conditions when the recorder is shipped from the factory. Because the chart paper may expand or contract depending on the environment in which the recorder is used, it is recommended that the position be readjusted before use.

#### Procedure


- 1. Warm up the recorder for at least 30 minutes.
- **2.** Check that the operating environment such as ambient temperature and humidity is within the normal operating conditions (see section 12.6).
- 3. Hold down the MENU key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and < > keys simultaneously for 3 seconds to enter Basic Setting mode.
- 5. Press the  $\nabla \Delta$  key or SHIFT+ $\nabla \Delta$  key to select **P\_Adj** and then press the  $\triangleleft$  key.
- Press the \\rightarrow \Left key to select Zero (left edge of the chart paper) or Full (right edge of the chart paper) and then press the <\= key. Adjust Zero first and then Full.

Increase or decrease the setting to align the pen position with the scale line on the chart paper. Then, press the  $\prec \exists$  key. To change the setting, press the  $\triangleleft \triangleright$  key to move the cursor and  $\nabla \Delta$  key to change the value.

The pen moves after the  $\triangleleft\!$  key is pressed.

A value change of 1 corresponds to 0.033 mm change in the pen position. Decreasing the value moves the pen to the left and increasing the value moves the pen to the right.

- 7. Select the Pen No.
- 8. Press the <⊨ key to set adjust other pens.</li>
   Press the ESC key to finish the adjustment. The screen returns to the Basic=P\_Adj screen.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla \Delta$  key or **SHIFT** +  $\nabla \Delta$  key to select **End** and then press the  $\prec \exists$  key. Press the  $\nabla \Delta$  key to select **Store** and then press the  $\prec \exists$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \exists$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Note.

When the Customized Menu is enabled, the operation is different.

- When "P\_Adj" in the Customized Menu is On
  - 1. Perform steps 1-4 of "Adjusting the Pen Position."
  - 2. When the instrument enters Basic Setting mode, "Menu kind" appears. Select "Free" then press a <⊢ key.
  - 3. Perform the steps starting with step 5 of "Adjusting the Pen Position."
- When "P\_Adj" in the Customized Menu is Off See "Disabling the Customized Menu" or "Changing the Settings without Disabling the Basic Setting Mode Lock."
- <Related Topics> Enabling/Disabling the customized menu: Section 7.22

Changing the settings without releasing the basic setting mode lock: Section 7.22

# 11.6 Adjusting the Dot Printing Position (Dot Model)

This section explains the details of adjusting the dot printing position on the chart paper. It is recommended that the position be adjusted once a year to assure its recording accuracy.

#### Note

Dot printing position is adjusted under standard operating conditions when the recorder is shipped from the factory. Because the chart paper may expand or contract depending on the environment in which the recorder is used, it is recommended that the position be readjusted before use.

#### Procedure

- 1. Warm up the recorder for at least 30 minutes.
- **2.** Check that the operating environment such as ambient temperature and humidity is within the normal operating conditions (see section 12.6).
- 3. Hold down the (MENU) key for 3 seconds to enter Setting mode.
- Hold down the \u2272\u0111 and < \u2272 keys simultaneously for 3 seconds to enter Basic Setting mode.
- Press the \sigma A key or SHIFT + \sigma A key to select P\_Adj and then press the <⊨ key.</li>
- Press the < > key to select Hysteresis, Zero (left edge of the chart paper), or Full (right edge of the chart paper) and then press the <⇒ key. Adjust Hysteresis first followed by Zero and then Full.


#### Adjusting the Hysteresis

A line is drawn on the chart paper. If the line appears as shown in Figure a, increase the displayed setting. Then press the  $\prec \exists$  key. If the line appears as shown in Figure b, decrease the displayed setting. Then, press the  $\prec \exists$  key.

To change the setting, press the  $\triangleleft \triangleright$  key to move the cursor and  $\bigtriangledown \triangle$  key to change the value.

Repeat this procedure until the line becomes straight.

A value change of 1 corresponds to 0.1 mm change in the dot printing position.



#### Adjusting Zero and Full


A line is drawn to the left edge for Zero and right edge for Full.

Increase or decrease the displayed setting so that the drawn line is aligned with the scale line on the chart paper. Then, press the <- key. The procedure of changing the setting is the same as with the adjustment of hysteresis.

The line moves after the  $\triangleleft\!\!\!\!\!\!\!\!\!\!$  key is pressed.

A value change of 1 corresponds to 0.1mm change in the dot printing position. Decreasing the value moves the line to the left and increasing the value moves the line to the right.

 Press the ESC key to finish the adjustment. The screen returns to the Basic=P\_Adj screen.



#### Applying the Changes and Returning to Operation Mode

Press the  $\nabla\Delta$  key or **SHIFT** +  $\nabla\Delta$  key to select **End** and then press the  $\prec \!\!\!\!$  key. Press the  $\nabla\Delta$  key to select **Store** and then press the  $\prec \!\!\!\!$  key. The changes are applied, and the screen returns to Operation mode. If you select **Abort** and press the  $\prec \!\!\!\!$  key, the changes are discarded, and the screen returns to Operation mode. Press the **ESC** key to return to the **Basic=** screen.

#### Note \_

#### When the Customized Menu is enabled, the operation is different.

- When "P\_Adj" in the Customized Menu is On
- 1. Perform steps 1-4 of "Adjusting the Dot Printing Position."
- 2. When the instrument enters Basic Setting mode, "Menu kind" appears. Select "Free" then press a <⊢ key.
- 3. Perform the steps starting with step 5 of "Adjusting the Dot Printing Position."
- When "P\_Adj" in the Customized Menu is Off See "Disabling the Customized Menu" or "Changing the Settings without Disabling the Basic Setting Mode Lock."

### <Related Topics> Enabling/Disabling the customized menu: Section 7.22

Changing the settings without releasing the basic setting mode lock: Section 7.22

# 11.7 Recommended Replacement Periods for Worn Parts

To preserve the reliability of the recorder and to use the recorder in good condition for an extended time, it is recommended that periodic replacements be made on parts. The replacement parts may change to accommodate preventive maintenance over extended time. Be sure to check with your nearest YOKOGAWA dealer.

The table below shows the recommended replacement period for expendable parts. The replacement period shown here applies when the recorder is used under standard operating conditions. For the actual replacement period, consider the actual conditions of use.

Replacement of parts other than the chart paper, pen, ribbon cassette, and internal light LED will be carried out by a YOKOGAWA engineer or an engineer certified by YOKOGAWA. Contact your nearest YOKOGAWA dealer when such replacement is necessary.

#### Note

The replacement period of the display and the internal light LED is the half life of the brightness. The deterioration of brightness varies depending on the condition of use, and its determination is subjective. Consider these facts for determining the actual replacement period.

### Pen Model

Item	Replacement Period	Part Name	Part No.	Note	Quantity Used
Z-fold chart paper	33 days	CHART	B9565AW	When used at 20 mm/h	1
Felt pen	2 km	PEN ASSY	B9902AM B9902AN B9902AP B9902AQ	Red Green At a pen speed Blue of 10 cm/s	1 each
Plotter pen	100,000 characters	PEN ASSY	B9902AR	When printing continuously	1
Display	5 years*	DISPLAY ASSY	B8800CA		1
Chart paper feed motor	5 years	MOTOR ASSY	B9962EJ		1
Plotter carriage	5 years	CARRIAGE ASSY	B8800DJ		1
Plotter motor	5 years	MOTOR ASSY	B8800DT	For the X-axis	1
Lever bearing	5 years	BEARING	B9900RP	For the plotter	1
Pen servo	5 years	SERVO ASSY	B8800GG	Shared by all pens (excludes the pen arm ASSY)	1 to 4
Internal light LED	2 years*	LED ASSY	B8800CR		1

\* The half life of the brightness at the factory default brightness setting.

### **Dot Model**

Item	Replacement Period	Part Name	Part No.	Note	Quantity Used
Z-fold chart paper	33 days	CHART	B9565AW	When used at 20 mm/h	1
Ribbon cassette	3 months	RIBBON CASSETTE	B9901AX		1
Display	5 years*	DISPLAY ASSY	B8800CA		1
Chart paper feed motor	5 years	MOTOR ASSY	B9962EJ		1
Lever	3 years	LEVER ASSY	B9901EK	For the carriage	1
Pulley	3 years	PULLY	B9963CJ	For the carriage	2
Carriage motor	5 years	MOTOR ASSY	B9963CF		1
Carriage	5 years	CARRIAGE ASSY	B9963CL		1
Ribbon shift motor	5 years	MOTOR ASSY	B9962EJ		1
Ribbon shift gear	5 years	GEAR	B8801BX B8801BW		1 each
Ribbon feed motor	5 years	MOTOR ASSY	B9901PJ		1
			B9901HL		
Ribbon feed gear	5 years	GEAR	B9901HM B9901HN		1 each
Internal light LED	2 years*	LED ASSY	B8800CR		1

The half life of the brightness at the factory default brightness setting.

# 12.1 Input Specifications

## Number of Inputs and Scan Interval on the Pen Model

Item	Specifications	
Number of inputs	1, 2, 3, or 4	
Scan interval	125 ms	

# Number of Inputs and Scan Interval on the Dot Model

Item	Specifications
Number of inputs	6
Scan interval	1 s (when the integration time of the A/D converter is 20 ms or 16.7 ms)
	2.5 s (when the integration time of the A/D converter is 100 ms)

# Input Type

Item	Specifica	ifications				
Input type	•	DC voltage, 1-5V, TC, RTD, DI (ON/OFF input), DC current (by adding an external shunt resistor)				
Input Type and Mea	asurable Range					
	Input	Range Type	Measurable Range			
	Volt	20 mV	-20.00 to 20.00 mV			
		60 mV	-60.00 to 60.00 mV			
		200 mV	-200.0 to 200.0 mV			
		2 V	-2.000 to 2.000 V			
		6 V	-6.000 to 6.000 V			
		20 V	-20.00 to 20.00 V			
		50 V	-50.00 to 50.00 V			
		1-5V	(0.800 to 1.200 V range) t	o (4.800 to 5.200 V range)		
	TC	R <sup>1</sup>	0.0 to 1760.0°C	32 to 3200°F		
		S <sup>1</sup>	0.0 to 1760.0°C	32 to 3200°F		
		B <sup>1</sup>	0.0 to 1820.0°C	32 to 3308°F		
		K <sup>1</sup>	–200.0 to 1370.0°C	-328 to 2498°F		
		E <sup>1</sup>	–200.0 to 800.0°C	-328.0 to 1472.0°F		
		$J^1$	–200.0 to 1100.0°C	-328.0 to 2012.0°F		
		T <sup>1</sup>	–200.0 to 400.0°C	-328.0 to 752.0°F		
		N <sup>1</sup>	0.0 to 1300.0°C	32 to 2372°F		
		$W^2$	0.0 to 2315.0°C	32 to 4199°F		
		L <sup>3</sup>	–200.0 to 900.0°C	-328.0 to 1652.0°F		
		U <sup>3</sup>	–200.0 to 400.0°C	-328.0 to 752.0°F		
		WRe <sup>4</sup>	0.0 to 2400.0°C	32 to 4352°F		
	RTD	PT (Pt100) <sup>5</sup>	–200.0 to 600.0°C	-328.0 to 1112.0°F		
		JPT (JPt100) <sup>5</sup>	–200.0 to 550.0°C	-328.0 to 1022.0°F		
	DI	Level	0: Less than 2.4 V, 1: Great Within ±6 V	ater than or equal to 2.4 V		
		Contact	0: Open, 1: Closed			
	1 R	, S, B, K, E, J, T, N: IEC	584-1 (1995), DIN IEC584, J	IS C1602-1995		
	2 W	/: W-5% Re/W-26% Re	(Hoskins Mfg. Co.), ASTM E9	988		
	3 L:	Fe-CuNi, DIN43710, L	J: Cu-CuNi, DIN43710			
	4 W	/Re: W-3%Re/W-25%R	e (Hoskins Mfg. Co.)			
		t100: JIS C1604-1997, Pt100: JIS C1604-1989	IEC751-1995, DIN IEC751-19 , JIS C1606-1989	996		
	M	easurement current: i =	= 1 mA (Pt100, JPt100)			

### 12.1 Input Specifications

Item	Specifications			
Input type	Floating unbalanced input.			
	Isolation betw	veen channels (except, b terminal is shared for RTD input).		
Burnout Detection of TC	Can be set fo	r each channel.		
	Upscale/Dow	nscale switchable.		
	Input Type	Operating Conditions		
	TC input	2 k $\Omega$ or less: normal, 10 M $\Omega$ or more: burnout, detection current: approx. 10 $\mu A$		
	1-5V input	0.2 V or less: burnout		
RJC of TC input	Set whether to use the recorder RJC function or an external RJC function for each channel.			
	Set the compensation voltage when using an external RJC function.			
	Compensation voltage range: –20000 µV to 20000 µV.			
A/D converter				
Resolution	16 bits			
Integration time	Pen model:	Selectable from 20 ms (50 Hz), 16.7 ms (60 Hz), and Auto (auto switch between		
		20 ms and 16.7 ms according to the power supply frequency).		
	Dot model:	Selectable from 20 ms (50 Hz), 16.7 ms (60 Hz), 100 ms and Auto (auto switch		
		between 20 ms and 16.7 ms according to the power supply frequency).		
Filter function (pen model)	Filter ON/OF	F switchable for each channel.		
	Time constant selectable from 2, 5, and 10 s.			
Moving average function	Moving avera	ge ON/OFF switchable for each channel.		
(dot model)	The number of samples of the moving average is selectable between 2 and 16.			

# Input Computation (Standard Function)

Calculates the difference between two channel inputs using the following equation.
Delta = (the input value of the channel set to delta computation) – (the input value of the
reference channel)
where (reference channel number) < (channel number set to delta computation).
Computable input type: DC voltage, TC, and RTD. The channel set to delta computation and the
reference channel is set to the same range type.
Scales the input value to a value with a unit suitable for the application.
Computable input type: DC voltage, TC, RTD, DI
Value after scaling
Mantissa: -20000 to 30000
Decimal position: Can be set arbitrarily
Unit: Can be set arbitrarily (up to 6 characters)
Displayable and printable range
-19999 to 31500
nput
Linearly scales the 1-5V signal.
Value after scaling: Same as linear scaling.
Displayable and printable range: Same as linear scaling.
Sets values below 0% of the recording span to the leftmost value of the scale. The leftmost value of
scale must be less than the rightmost value of scale.
Takes the square root of the input value and linearly scales the result.
Computable input type: DC voltage
Value after scaling: Same as linear scaling.
Displayable and printable range: Same as linear scaling.
Sets values below the low-cut point to the leftmost value of scale. The leftmost value of scale must
be less than the rightmost value of scale.
Low-cut point range: 0.0 to 5.0% of the recording span (0.1% steps)
Adds a bias to the measuring input value.
Bias value range: ±10% of the span of the measurable range at the specified range type.
±10% of the scaling span if linear scaling is used.

# 12.2 Alarm Function Specifications

Item	Specifications				
Number of alarms	Up to four alarms (level) for each measurement channels.				
Alarm types	High limit (H), low limit (L), difference high limit (h), difference low limit (I), high limit on rate-of- change (R), low limit on rate-of-change (r), delay high limit (T), delay low limit (t). The symbol indicating the alarm is given in parentheses.				
	Rate-of-change calculation interval of rate-of-change alarms (can be set individually for the high limit on rate-of-change and low limit on rate-of-change alarms)				
	Rate-of-change calculation interval = Scan interval × the number of sampled data where the number of sample data is a value between 1 and 15				
	Alarm delay time of delay high and low limit alarms (can be set for each channel, common within a channel)				
	1 to 3600 s (1 hour)				
	However, if the alarm delay time setting is not an integer multiple of the scan interval, the alarm delay time is set to a value that is the first integer multiple of the scan interval exceeding the delay time setting.				
Hysteresis	Set a width to the value for detecting alarm occurrence/release (common to all channels and all levels)				
	Applied to high limit alarm and low limit alarm.				
	Hysteresis range: Approx. 0.0% to 1.0% of the recording span (0.1% steps)				
Display	Indicates the alarm occurrence status on the display.				
	Indication for each channel: Displays the alarm type (display precedence: H, L, T, t, h, I, R, and r)				
	Alarm summary display: Displayed using an icon.				
	Displays the alarm point mark and status on the bar graph.				
	Non-hold/hold operation of alarm indication				
	Turn ON/OFF the indication along with the alarm occurrence/release (non-hold) or hold the				
	indication until the alarm ACK operation.				
Alarm relay contact ou	tput (optional specifications)				
	See section 12.5				

# 12.3 Recording Function Specifications

# Trend Recording (Pen Model)

Item	Specifications
Recording pen	Disposable felt pen
Step response time	Approx. 1 s (using the IEC61143 measurement method)
Number of pens	Up to 4
Recording color	Pen 1: Red, pen 2: Green, pen 3: Blue, pen 4: Violet
Trend recording	Updates the data at the scan interval. Continuous recording.
Pen offset compensation	Records by compensating for the offset of each pen along the time axis.
Chart speed	5 to 12000 mm/h (82 steps).
Zone recording	Recording zone can be specified for each channel.
	Recording width: 5 mm or more (1 mm steps)
Partial expanded recording	g Records by expanding the right or left side of the boundary position (the other section is reduced).
	Boundary position: 1 to 99%
	Boundary value: Within the recording span range

# Trend Recording (Dot Model)

Item	Specifications			
Recording method	Trend recording by a 6-color wire dot printer			
Recording color	Channel 1: Purple, channel 2: Red, channel 3: Green, channel 4: Blue, channel 5: Brown, channel 6: Black			
Trend recording interval	Records at the following interval through a raster scan system.			
	Auto: Synchronizes to the chart speed and automatically sets to the interval			
	Fix: 10 s/6 channels (see section 12.5 for the recording interval on models with the computation function (/M1 option)			
Chart speed	1 to 1500 mm/h (1 mm steps)			
Recording ON/OFF	Recording can be turned ON/OFF for each channel.			
Zone recording	Same as the pen model.			
Partial expanded recording	g Same as the pen model.			

## **Chart Paper**

Item	Specifications
Printing width	100 mm
Type/Length	Z-fold type. Approx. 16 m.
Chart paper feeding	accuracy
	Within ±0.1% After feeding 1000 mm and with respect to the print scale on the chart paper.

Item	Specifications						
Recording pen (color)	Plotter pen (purple)						
Alarm printout	Prints alarm occurrence/re	elease.					
Printout contents	Occurrence $(\triangle)$ /release $(\bigtriangledown)$ marks, channel number or tag, alarm type, alarm level, time, printout						
	buffer overflow mark.						
Time printout format	Selectable from hour:minute, hour:minute:second, month:day:hour:minute,						
nino printout lorniat	month:day:hour:minute:se						
Alarm printout buffer	Stores 8 occurrences of a		5				
Periodic printout		ints at specified time intervals from the reference time.					
Interval	•	ference time: 00 hour 00 minute to 23 hour 00 minute (1 hour steps, minute fixed)					
(see appendix 2)		determined from the ch	<b>N</b>	(U)			
(see appendix 2)			1, 30 min, 1 hour, 2 hours, 3 hours	a 4 hours			
		rs, 12 hours, or 24 hour		s, <del>4</del> 110013,			
Mode	-			art data (rapart			
Wode		erioaic printout, print ins	stantaneous values, and print repo	ort data (report			
	mode).						
	•	0	um, maximum, minimum/maximu	m/average, sum			
	value, and instantaneous						
Printout contents	For instantaneous values:		pensation ON/OFF, channel infor				
		(	rm status, unit, delta computation	, ,			
		channel number or ta	g, recording color), chart speed (v	vith time ticks)			
	For report data: Report st	art/end date/time, offse	t compensation ON/OFF, events,	channel			
	informatio	on (value, unit, range cl	nange occurrence, scale, recordin	ig color), chart			
	speed (w	ith time ticks)					
Message printout	Prints preset message str	ings.					
Number of messages	5	0					
Printout contents	Time, message (up to 16	characters), printout bu	ffer overflow mark.				
Time printout format	Selectable from hour minu	ute, hour:minute:second	d, month:day:hour:minute,				
			hour:minute:second, and not print				
Message printout buffer	Stores 5 messages waitin		·····, -····	-			
Recording start printout	Prints at the start of record						
Printout contents	Time and chart speed, pri		ark				
Time printout format							
nine printout format	Selectable from hour:minute, hour:minute:second, month:day:hour:minute, month:day:hour:minute:second, and year:month:day:hour:minute:second.						
New chart speed printout	Prints when the chart spe		day.nour.minute.second.				
Printout contents	Chart speed and time, pri	Ũ	ark				
Time printout format							
nine printout format	Selectable from hour:minute, hour:minute:second, month:day:hour:minute,						
Manual printout	month:day:hour:minute:second, and year:month:day:hour:minute:second.						
Manual printout	Prints the measured values of all channels.						
Printout contents	Measured values of all channels at that point.						
<u> </u>	Trend recording is tempor						
Setting printout (List)	Prints the settings of item	0					
Printout contents	Range setting, alarm setting, etc.						
	Trend recording is tempor						
Setting printout (Setup)	Prints the settings of items						
Printout contents	Basic alarm specifications	, U I	fications, etc.				
	Trend recording is tempor	arily suspended.					
Items dependent on the cha	art speed						
			Alarm printout				
			Message printout				
	Chart speed	Periodic printout	Becord start printout				

# Printouts (Pen Model)

	Chart speed	Periodic printout	Alarm printout Message printout Record start printout New chart speed printout
	5 to 9 mm/h	Not printed	Printed
	10 to 1500 mm/h	Printed	Printed
	1600 mm/h or higher	Not printed	Not printed
	Chart speed	Periodic printout interva	al
	10 to 18 mm/h	8 hours	
	20 to 36 mm/h	4 hours	
	40 to 72 mm/h	2 hours	
	75 to 135 mm/h	1 hour	
	150 to 180 mm/h	30 minutes	
	200 to 320 mm/h	20 minutes	
	350 to 1500 mm/h	10 minutes	
Date printout format		at of the date from Y/M/D, out of all printout items (ve	M/D/Y, D/M/Y, D.M.Y, and M.D.Y. Thersion 1 11 and later)

## Printout (Dot Model)

Item	Specifications		
Recording	Dot printing.		
Channel printout	Prints the channel number or tag beside the trend recording every approx. 25 mm of cha		
	Channel printout ON/OFF select	able.	
Alarm printout	Prints alarm occurrence/release.		
Printout contents	Occurrence (△, red)/release (▽, blue) marks, channel number or tag, alarm type, alarm level, time, printout buffer overflow mark.		
Time printout format	Selectable from hour:minute, hour:minute:second, month day hour:minute,		
·	month day hour:minute:second,	and month day year hour:minute:second.	
Alarm printout buffer	Stores 12 occurrences of alarm information waiting to be printed.		
Periodic printout	Prints at specified time intervals from the reference time.		
Interval (see appendix 2)	Same as the pen model.		
Measured value	Same as the pen model.		
Printout contents		as the pen model except offset compensation ON/OFF and ling color are not printed.	
	•	as the pen model except offset compensation ON/OFF and ling color are not printed.	
Message printout	Same as the pen model.		
Recording start printout	Same as the pen model. With tir	ne ticks.	
New chart speed printout	Same as the pen model. With tir	ne ticks.	
Manual printout	Same as the pen model.		
Setting printout (List)	Same as the pen model.		
Setting printout (Setup)	Same as the pen model.		
Items dependent on the cha	art speed		

Items dependent on the chart speed

	Chart speed	Channel printout	Periodic printout	Alarm printout Message printout Record start printout New chart speed printout
	1 to 9 mm/h	Printed	Not printed	Printed
	10 to 100 mm/h	Printed	Printed	Printed
	101 to 1500 mm/h	Not printed	Not printed	Not printed
	Chart speed	Periodic printout in	nterval	
	10 to 19 mm/h	8 hours		
	20 to 39 mm/h	4 hours		
	40 to 79 mm/h	2 hours		
	80 to 100 mm/h	1 hour		
Date printout format	Same as the pen mod	del.		

#### Values for Special Measured Values

Same as "Special values" for the digital display on page 12-8.

# 12.4 Display Function Specifications

## **Display and Displayed Contents**

This section explains the specifications of the display functions of measurement channels and computation channels (/M1 option). Display examples are illustrations used to explain the displayed contents and differ in appearance from the actual displays.

Item	Specifications			
Display	VFD (101 × 16, dot matrix)			
	Up to 11 characters using large fonts. 17 characters × 2 lines using normal fonts.			
Number of screens	15 (switched using keys)			
Displayed information				
Display type	1CH digital display			
	2CH digital display			
	4CH digital display			
	6CH digital display (dot model)			
	1CH digital + 1CH bargraph display			
	1CH digital + 4CH bargraph display (pen model)			
	2CH digital + 2CH bargraph display			
	4CH bargraph display (pen model)			
	6CH bargraph display (dot model)			
	Flag display			
	Channel alarm status display			
	Date, time, and chart speed display			
	DI/DO status display (/Ax or /R1 option)			
	1CH digital display (tag display)			
	2CH digital display (tag display)			
	1CH digital + 1CH bargraph display (tag display)			
	1CH digital + 4CH bargraph display (tag display) (pen model)			
	Status display System display			
	Batch name display (/BT1 option)			
	Lights out			
	Skip Multiple display			
	Multiple display			
	The following screens can be assigned arbitrarily to the top and bottom sections of the display			
	1CH digital display			
	2CH digital display			
	Date/Time			
	Chart speed display			
	Channel alarm status display			
	1CH digital display (tag display)			
	Status display			
	Lights out			
Display update of measu	red values / computed values			
When displayed chan	nels are fixed			
	Dot model: Updated at the scan interval			
	Pen model: Updated every 2 s			
When displayed chan	nels are automatically switched			
	Switches the channel and measured values at 1, 2, 3, 4, or 5 second intervals.			
Status display				
RECORD	This indicator turns ON when recording is started and turns OFF when stopped.			
ALARM	The indicator turns ON when an alarm occurs and turns OFF when the alarm is released.			
	If the alarm indication is set to hold operation, the indicator blinks when an alarm occurs. When			
	alarm ACK operation is performed, the indicator turns ON or OFF.			
MATH	This indicator turns ON when computation on the computation function (/M1 option) is started and			
	turns OFF when stopped.			
KEYLOCK	This indicator turns ON when key lock is activated and turns OFF when released.			
CHART END	This indicator turns ON when the remaining amount of chart paper falls to approximately 2 cm on			

#### 12.4 Display Function Specifications

Item	Specificati	ons	
Display type specification	IS		
Digital display			
Measured value or co	mputed value		
	measurab of the rang	le range" and ' ge (example: –	ys values between "the min. measurable value $-5\%$ of the span of the "the max. measurable value $+5\%$ of the span of the measurable range" 2.200 to 2.200 V for the 2 V range).
	and "the n	nax. measurab	ays values for input values between "the min. measurable value – 10°C" le value + 10°C" (example: –10.0°C to 1770.0°C for TC R)
		• • • •	lays the input value 0 or 1.
	leftmost v span" (exa during sca above 315	alue of scale – ample: –5.0 to aling is from –1 500 are display	ling, and square root): Displays value for input values between "the 5% of scaling span" and "the rightmost value of scale + 5% of scaling 105.0 when scaled to 0.000 to 100.0). However, the displayable range 9999 to 31500 (excluding the decimal). Values below –19999 and values ed as –Over and +Over, respectively.
Channel number	<ul> <li>Computation channel (/M1 option): Displays values in the range of –99999999 to 99999999.</li> </ul>		
Channel number	Displayed with 1 character as follows: Measurement channels:1, 2, 3, 4, 5, 6		
Alarm	Computation channels:A, B, C, D, E, F, G, J, K, M, N, P Alarms are displayed using the symbols below. If multiple alarms are occurring simultaneously, the		
Aldini	alarm with higher precedence is shown.		
		0 1	T, t, h, I, R, r (Lower precedence)
Special values	Measurement channel		
	Status	Display	Description
	+Over	+Over	See below.
	–Over	–Over	See below.
	Skip	SKIP	A value for channels set to skip.
	Error	ERROR	Values such as when both the reference channel and measurement channel are +Over or –Over in delta computation.
	+Burnout	B.out	A value displayed when a burnout is detected on a channel set to burnout up scale.
	-Burnout	B.out	A value displayed when a burnout is detected on a channel set to burnout down scale.

computed value" above. For example,

- $\bullet$  For 2 V range, values below –2.200 V are –Over and values over 2.200 V are +Over.
- For TC R, values below -10.0°C are -Over and values over 1770.0°C are +Over.
- If scaled to 0.0 to 100.0, values below -5.0 are -Over and values above 105.0 are +Over. However, the displayable range during scaling is from -19999 to 31500 (excluding the decimal). Values below -19999 and values above 31500 are displayed as -Over and +Over, respectively.

Computation channel

Status	Display	Description	
+Over	+Over	When the computed result exceeds 999999999.	
-Over	–Over	When the computed results is less than –99999999.	
OFF	SKIP	A value for channels set to Off.	

Channel switching

The switching interval of displayed channels can be set to 1 s, 2 s, 3 s, 4 s, or 5 s.

#### interval

Item	Specificatio	ns		
Bar graph display		e measured value on a bargraph.		
Relationship between				
relationship between	0 1	same channel on the digital display and bargraph. On the 2CH digital + 2CH bargraph		
	display, the	top bargraph is the left digital display channel and the bottom graph is the right digital		
Scale		display channel. Displays 10 equally spaced scale marks.		
Alarm point mark				
Alami point mark	channels, th	For a channel set to delta computation, the alarm point marks of h and I are displayed. For all othe channels, the alarm point marks of H, L, T, and t are displayed.		
		he bargraph when an alarm occurs. Stops blinking when the alarm is released.		
Bar graph display mo		rom the two modes below.		
	<ul> <li>Set the bas value.</li> </ul>	se point of the bargraph to the left or right of the recording span whichever is smaller in		
		se point of the bargraph to the 50% position of the recording span.		
Flag display		asured values using flags.		
		be turned ON/OFF for each channel.		
Display channel	-			
Scale		overlap, the channel with the smallest number is displayed on top) equally spaced scale marks.		
		equally spaced scale marks.		
Channel alarm status dis	1 5	rm status of all shannals using the symbols halow		
		rm status of all channels using the symbols below.		
	Symbol	Description		
	•	Alarm is not set.		
	-	Alarm is not occurring.		
	Channel	Alarm is occurring.		
	number	Displays the channel number when an alarm occurs and clears when the alarm is		
		released.		
		If the alarm indication is set to hold operation, the indicator blinks when an alarm		
		occurs. When alarm ACK operation is performed, the indicator turns ON (stop		
		blinking) or OFF.		
Date/time and chart spee	od display			
Date/time and chart spec		date/time on the left and chart speed on the right.		
		splay format can be selected. The format is common with the "Date printout format." the ON/OFF state of the remote control input terminal (/R1 option).		
DI/DO status display				
Multiple display (display		the relay operation (active) of the alarm output terminal (/A1, /A2, or /A3 option).		
multiple display (display		nt screens can be assigned to the top and bottom sections)		
Tag diaplay		bes (see page 12-7) can be assigned to the top and bottom sections of the display (VFD)		
Tag display		ligit tags in place of channel numbers.		
Status display		tal display and bar graph display sections.		
Status display		status below. The display condition is the same as the status display under the main		
	display (see	hart end (/F1 option)		
Sustam diaplay				
System display		stem information by switching screens every 3 seconds. The main displayed contents		
		are as follows:		
	-	Analog: Number of inputs		
		Option1, Option2: Options that are installed		
		Math: Number of computation channels		
		Periodic: Periodic printout interval		
		nd recording interval (dot model)		
		ffset compensation ON/OFF (pen model)		
		ss: MAC address		
		corder version number (firmware version number)		
Batch name display		: Batch number (up to 26 characters) and lot number (4 or 6 digit number, or none)		
	(/BT1 option			
		Displays nothing.		
Lights out Skip	Displays not			

Name	Display Example	Description
1CH digital display	Measurement channel	Channel number (1 digit), alarm (1 digit), measured value (6 digits), unit (3 digits) Displays using 5 x 7 dots when the unit
	└─Alarm └─Measured └─Unit └─Channel number value	exceeds 3 digits.
	Computation channel	Channel number (1 digit), alarm (1 digit), computed value (9 digits)
2CH digital display	Measurement channel 1H-1999.9ABCDEF 2L 2000.0PQRSTU	Channel number (1 digit), alarm (1 digit), measured value (7 digits), unit (6 digits)
	Computation channel AH-999999.9ABCDEF BL9999999.9PQRSTU	Channel number (1 digit), alarm (1 digit), computed value (9 digits), unit (6 digits)
CH digital display	Measurement channel           1H3000.0         1H3000.0           3H3000.0         4H3000.0           Computation channel         4H3000.0	Channel number (1 digit), alarm (1 digit), measured value (6 digits)
	AH-1999.9 BH-1999.9 CH9999.9 DH9999.9	Channel number (1 digit), alarm (1 digit), computed value (6 digits) Displayable values are –19999 to 99999 and a decimal. If this range is exceeded, the value is displayed as"–####" or "+####."
CH digital display Dot model)	999.9 999.9 999.9 999.9 999.9 999.9	Measured value (5 or 6 digits)
ICH digital + 1CH bargraph display	1H3000.0ABC	Channel number (1 digit), alarm (1 digit), measured value (6 digits), unit (3 digits) Bar graph, scale, alarm (bar graph) Value and bar graph of the same channel.
2CH digital + 2CH bargraph lisplay	Measurement channel	Channel number (1 digit), alarm (1 digit), measured value (6 digits) Bar graph, scale
	Computation channel	Channel number (1 digit), alarm (1 digit), computed value (6 digits) Bar graph, scale
		Displayable values are –19999 to 99999 and a decimal. If this range is exceeded, the value is displayed as"–####" or "+####."
CH digital + 4CH bargraph lisplay (Pen model)	Measurement channel	Channel number (1 digit), alarm (1 digit), measured value (7 digits), unit (6 digits)
	Computation channel	Channel number (1 digit), alarm (1 digit), computed value (9 digits), unit (6 digits)
CH bargraph display Pen model)		Bar graph, scale
CH bargraph display Dot model)		Bar graph, scale
lag display		Flag, scale
Channel alarm status display	•):12·-·6 ABC-·-G··P	Alarm is not set.     Alarm is not occurring.     Channel number Alarm is occurring.
ime/Chart speed display	Sep.21.2004 1200 11:26:37 mm/h	Displays the date/time on the left and chart speed on the right.

Name	Display Example	Description
DI/DO display		DI (remote control input, /R1 option) status.
		DO (alarm output relay, /Ax option) status.
Multiple display	1H-1999.9ABCDEF 05/09/21 11:26:37	See the next page.
	Display in which different screens are assigned to the top and bottom sections.	
Tag_1CH digital display	Measurement channel	Tag (7 digits), alarm (1 digit),
	H-1999.9ABCDEF	measured value (7 digits), unit (6 digits)
	└──Alarm └─ Measured └─ Unit └─Tag value	
	Computation channel	Tor (7 digita) clarm (1 digit)
	abcdefg H9999999.9ABCDEF	Tag (7 digits), alarm (1 digit), computed value (9 digits), unit (6 digits)
Tag_2CH digital display	abcdefgH-1999.9ABC abcdefgH9999999.9	Measurement channel Tag (7 digits), alarm (1 digit),
	The top section is measurement channel;	measured value (6 digits), unit (3 digits) Computation channel
	bottom section is computation channel	Tag (7 digits), alarm (1 digit), computed value (9 digits)
Tag_1CH digital + 1CH	Measurement channel	The digital display is the same as
bargraph display	abcdefgH-1999.9ABC	the Tag_2CH digital display.
	Computation channel	Bar graph, scale, alarm (bar graph) Value and bar graph of the same channel.
	abcdefgH9999999.9	
Tag 1CH digital + 4CH	Measurement channel	The digital display is the same as
bargraph display (Pen model)	abcdefgH-1999.9ABC	the Tag_2CH digital display. Bar graph
	Computation channel	
	abcdefgH9999999.9	
Status display	•)) <b>E</b>	Displays the appropriate mark.
	Chart end	
	Alarm	
System display	100mm Dot model Analog: 6	<ul> <li>Product information Number of signal inputs, options installed,</li> </ul>
	The displayed contents switch every	number of computation channels, MAC
	3 seconds.	address, and recorder version (firmware version)
		Setup data     Device discussion intervelse deterministing
		Periodic printout interval, dot printing interval (dot model), and pen offset compensation On/Off (pen model)
Batch name display	Batch No0002	For models with the Header printout
		(/BT1 option)
	Lot number	
	Automatically added wh	nen batch number and lot number are enabled.
		No diaplay
Lights out		No display.

### 12.4 Display Function Specifications

Name	Display Example	Description
1CH digital display	Computation channel	
	1H-1999.9ABCDEF	Channel number (1 digit), alarm (1 digit), measured value (7 digits), unit (6 digits)
	Measurement channel	
	AH9999999.9ABCDEF	Channel number (1 digit), alarm (1 digit), computed value (9 digits), unit (6 digits)
2CH digital display	Computation channel	
	1H-1000.0 2H3000.0	Channel number (1 digit), alarm (1 digit), measured value (6 digits)
	Measurement channel	
	АН-1999.9 ВН9999.9	Channel number (1 digit), alarm (1 digit), measured value (6 digits)
Date/Time	Sep21.04 11:26:37	Date/Time
Chart speed	25mm/h	Chart speed
Channel alarm status	=):12·-·6 ±2	Alarm is not set.     Alarm is not occurring.
display	Alarm summary display ─┘	Channel number Alarm is occurring.
	of computation channels	<b>.</b>
Tag_1CH digital display	abcdefgH-1999.9ABC abcdefgH9999999.9	The digital display is the same as the Tag 2CH digital display.
	The top section is measurement channel;	0_ 0 1 9
	bottom section is computation channel	
Status display	(m)) (X)	Displays the appropriate mark.
Lights out		No display.

# **12.5 Specifications of Optional Functions**

Item	Specifications	
Operation	Outputs relay contact signals from the dedicated terminals on the rear panel when alarms	
	occur.	
Number of outputs	2 outputs (/A1), 4 outputs (/A2), 6 outputs (/A3)	
Relay contact rating	250 VDC/0.1 A (for resistance load)	
	250 VAC (50/60 Hz)/3 A	
Output format	NO-C-NC	
Auxiliary functions	Energized/De-energized operation selectable (common to all relays)	
	Hold/Non-hold operation selectable (common to all relays)	
	AND/OR operation selectable	
	Reflash operation (Fixed to relay I01, I02, and I03. Relay release time is approx. 500 ms.)	
Diagnosis output	Relay I01 can be used for diagnosis output.	
	Diagnosis output: Outputs a relay signal when an error in the recording section (plotter on the	
	pen model), a burnout, or an error in the A/D converter is detected. Relay operation is fixed to	
	de-energized and non-hold.	

## Alarm Output Relay (/A1, /A2, and /A3)

# RS-422A/485 Communication Interface (/C3)

Item	Specifications	
Connection	Complies with EIA RS-422A/485	
Connection type	Multi-drop connection 1:32 (four-wire system), 1:31 (two-wire system, version 1.11 and later)	
Transmission mode	Half-duplex	
Synchronization	Start-stop synchronization	
Baud rate	1200, 2400, 4800, 9600, 19200, or 38400 bps	
Start bit	Fixed to 1 bit	
Data length	7 bits or 8 bits	
Stop bit	Fixed to 1 bit	
Parity	Odd, even, or none (no parity)	
Received buffer length	2047 bytes	
Escape sequence	Open and close	
Protocol	Dedicated protocol, Modbus slave protocol (version 1.11 and later)	
Communication mode	ASCII for input/output for control and setting	
	ASCII or binary for input/output of measured data	
Communication distance	1.2 km	

## Ethernet Communication Interface (/C7)

Item	Specifications				
Function					
Setting/Measurement server	Uses a dedicated protocol				
	Measured/computed data, se	tup data, status byte			
Maintenance/Test server	Connection information, netw	ork statistics, etc.			
Instrument information server	Model, serial number, etc.				
Electrical and mechanical specif	fications				
	Conforms to IEEE 802.3.				
Interface	Basic specifications				
	Connection Ethernet (	10BASE-T)			
		DP, ICMP, and ARP			
	The maximum number of sim	ultaneous connections a	and the number of simult	ane	ous use
	Function	Maximum Number of	Number of		
	Administrators	<b>Connections Users</b>	Simultaneous Users	Ро	rt Number
	Setting/Measurement server	3	1	2	34260/tcp
	Maintenance/Test server	1	1	1	34261/tcp
	Instrument information server	· -	-	-	34264/udp
Miscellaneous					
User authentication	Administrator: 1, users: 6 (limitations placed on users)				
Keepalive	Drops the connection if there selectable.	is no response to an ins	pection packet. Use or r	not u	se is

FAIL/Chart End	Detection and	Output (	( <b>/F1</b> )
----------------	---------------	----------	----------------

Item	Specifications
FAIL output	Relay output on CPU error
Relay operation	Energized during normal operation and de-energized on CPU error. Non-hold operation.
Chart end detection output	Stops recording and outputs a relay signal when the remaining amount of chart paper is approx. 2 cm. Also, turns ON the words CHART END on the display.
Relay operation	The relay is energized when the above conditions are met. Non-hold operation.
Contact rating	250 VAC (50/60 Hz)/3 A, 250 VDC/0.1 A (for resistor load)

# Clamped Input Terminal (/H2)

	. ,
Item	Specifications
Measuring input terminal	Uses clamped input terminals.

# Non-Glare Door Glass (/H3)

Item	Specifications
Door glass	Uses a door glass with minimal reflection.

# Computation Function (/M1)

Item	Specifications			
Number of computation cha	annels			
	Pen model: 8 channels, dot mo	del: 12 channels		
Operation	General arithmetic operations:	logarithm, expone	perations, square root, absolute, common ntial, power, relational operations (<, ≤ , >, ≥ , =, ≠ (AND, OR, NOT, XOR)	
	Statistical operations (TLOG):	Average, max., m	in., sum, and max. – min. for each interval	
Constants	Up to 30 constants can be defi	ned		
	Range: -9.9999E+29 to -1.0000E-30, 0, 1.0000E-30 to 9.9999E+29			
	Symbol: K01 to K30			
Communication input data	Digital data via communication can be used in computations other than statistical computation (TLOG)			
	Number of communication input	ut data points: 8 (pe	en model), 12 (dot model)	
	Range: -9.9999E+29 to -1.0	0000E-30, 0, 1.000	0E-30 to 9.9999E+29	
	Symbol: C01 to C12			
Remote input	Use remote input status (0/1) in	n equations		
	Number of inputs: 5			
	Symbol: D01 to D05			
Computation accuracy	32-bit floating-point computation			
Computation range	Computed values throughout the	ne computation rem	nains within approx. ±3.4×10 <sup>38.</sup>	
Equation	Defined using up to 120 charac	cters.		
Execution interval	Scan interval			
TLOG timer	Performs statistical calculation	for each interval sp	pecified by the timer.	
Number of timers	3 (periodic printout timer, timer	1, and timer 2).		
Timer 1 and 2 modes	Absolute or relative			
Reset	TLOG data can be reset at eac	h interval.		
Printout	Printout at each interval is pose	sible.		
Trend recording				
Recording span	-99999999 to 99999999, decim	al position arbitrary		
Unit	Up to 6 characters			
Recording methods	Zone recording and partial expanded recording available.			
Pen			s can be assigned arbitrarily to pens.	
Dot printing	Trend recording of measureme follows:	ent and computatior	n channels. The fastest dot printing interval is as	
	Number of channels being	trend recorded	Fastest dot printing interval	
	6 or less		10 s	
	7 to 12		15 s	
	13 to 18		20 s	

Item	Specifications
Alarms	
Number of alarms	Up to four alarms (level) for each measurement channels.
Alarm types	High limit (H), low limit (L), delay high limit (T), delay low limit (t). The alarm symbol is shown in parentheses.
	Alarm delay time of delay high and low limit alarms (can be set for each channel, common within a channel) See section 12.2
Hysteresis	Applied to high limit alarm and low limit alarm.
	Hysteresis range: Approx. 0.0% to 1.0% of the recording span (0.1% steps)
Miscellaneous	See section 12.2.
Display	See section 12.4.

## Cu10, Cu25 RTD Input (/N1)

 Item
 Specifications

 Cu10, Cu25 RTD
 This option allows Cu10 and Cu25 inputs to be added to the standard input types.

 Input type and measurable range
 Finite content of the standard input types.

Input Type		Measurable Range	
	Cu10 (GE)		
RTD (Measurement current i: 2 mA)	Cu10 (L&N)		
	Cu10 (WEED)		
	Cu10 (BAILEY)	–200.0 to 300.0°C –328.0 to 572.0°F	
	Cu10: α = 0.00392 at 20°C	-320.0 10 372.0 1	
	Cu10: α = 0.00393 at 20°C		
	Cu25*: α = 0.00425 at 0°C		

\* Measurement current i = 1 mA

#### Measurement and recording accuracy

Input Type	Measurement Accuracy	Recording Accuracy
Cu10 (GE)		
Cu10 (L&N)		
Cu10 (WEED)	1/0.4% of rdg $1.4.0%$	Measurement accuracy
Cu10 (BAILEY)	±(0.4% of rdg + 1.0°C)	±(0.3% of recording span)
Cu10: α = 0.00392 at 20°C		
Cu10: α = 0.00393 at 20°C		
Cu25: α = 0.00425 at 0°C	±(0.3% of rdg + 0.8°C)	

## 3 Legs Isolated RTD (/N2)

Item	Specifications
Input terminal isolation	Applies to the dot model.
	The RTD input terminals are isolated between channels (on the standard dot model, input terminal
	b are common to all channels)

## **Expansion Inputs (/N3)**

Specifications

#### Input type and measurable range

Adds the input types shown in the table below.

Input Type		Measurable Range		
	PR40-20	0.0 to 1900.0°C	32 to 3452°F	
	PLATINEL	0.0 to 1400.0°C	32 to 2552°F	
Thermocouple	NiNiMo	0.0 to 1310.0°C	32 to 2390°F	
Thermocoupie	W/WRe26	0.0 to 2400.0°C	32 to 4352°F	
	Type N (AWG14)	0.0 to 1300.0°C	32 to 2372°F	
	Kp vs Au7Fe	0.0 to 300.0 K		
	Pt25	–200.0 to 550.0°C	-328.0 to 1022.0°F	
	Pt50	–200.0 to 600.0°C	-328.0 to 1112.0°F	
RTD	Ni100 (SAMA)	–200.0 to 250.0°C	-328.0 to 482.0°F	
	Ni100 (DIN)	–60.0 to 180.0°C	-76.0 to 356.0°F	
(Measuring current i = 1 mA)	Ni120	-70.0 to 200.0°C	-94.0 to 392.0°F	
	J263*B	0.0 to 300.0 K		
	Cu53	–50.0 to 150.0°C	-58.0 to 302.0°F	
	Cu100: α = 0.00425 at 0°C	-50.0 to 150.0°C	-58.0 to 302.0°F	

ltem	Specifications	Specifications		
Measurement ar	nd recording accuracy			
	Inpu	ut Type	Measurement Accuracy	Recording Accuracy
		0 to 450°C	Not warranted	
	PR40-20	450 to 750°C	±(0.9% of rdg + 3.2°C)	
	PR40-20	750 to 1100°C	±(0.9% of rdg + 1.3°C)	
		1100 to 1900°C	±(0.9% of rdg + 0.4°C)	
	PLATINEL		±(0.25% of rdg + 2.3°C)	
	NiNiMo		±(0.25% of rdg + 0.7°C)	
	W/WRe26	0 to 400°C	±15.0°C or less	
	W/WRezo	400 to 2400°C	±(0.2% of rdg + 2.0°C)	
	Type N (AWG14)		±(0.2% of rdg + 1.3°C)	Measurement
		0 to 20 K	±4.5 K	accuracy
	Kp vs Au7Fe	20 to 300 K	±2.5 K	±(0.3% of
	Pt25		±(0.15% of rdg + 0.6°C)	recording span)
	Pt50		±(0.3% of rdg + 0.6°C)	]
	Ni100 (SAMA)		±(0.15% of rdg + 0.4°C)	-
	Ni100 (DIN)			
	Ni120			
	J263*B	0 to 40 K	±3.0 K	1
	J203"B	40 to 300 K	±1.0 K	
	Cu53	· ·	±(0.15% of rdg + 0.8°C)	
	Cu100		±(0.2% of rdg + 1.0°C)	1
	Note) No RJC for	PR40-20 (fixed to 0	°C)	

# Remote Control 5 Points (/R1)

Item	Specifications			
Number of input terminals	5			
Input type	Isolated from the main circuitry through a photocoupler, built-in isolated power supply for the input terminals, and shared common			
Input type and signal level				
Voltage-free contact	Contact closed at 200 $\Omega$ or less and contact open at 100 k $\Omega$ or greater			
Open collector	ON voltage: 0.5 V or less (sink current 30 mA or more), leakage current when OFF: 0.25 mA or les			
Signal type	Edge, level, or trigger (250 ms or more)			
Operation	Perform the following control operations by applying a given signal to the remote signal input terminal.			
	Start/stop recording (edge)			
	Alarm ACK (trigger)			
	Set the clock (adjust the clock to the nearest hour with the contact input, trigger)			
	Time When Signal Is Input Procedure			
	00 min 00 s to 01 min 59 s Truncates the minutes and seconds. Example: $10:00:50 \rightarrow 10:00:00$			
	58 min 00 s to 59 min 59 s Rounds up the minutes and seconds. Example: $10.59:50 \rightarrow 11:00:00$			
	02 min 00 s to 57 min to 59 s No operation			
	Manual printout (trigger)			
	Message 1 to 5 printout (trigger)			
	Switch the chart speed (level)			
	Start/stop computation (/M1 option) (edge)			
	Reset computation (/M1 option) (trigger)			
	Priority to remote recording (/BT1 option) (edge)			
	Batch comment switching (/BT1 option) (level)			

# Portable Type (/H5x)

Item	Specifications
Installation	Desktop type (with a carrying handle)
External dimensions	144 (W) × 187 (H) × 285 (D) mm (including the handle and feet)
Weight	Add 1.0 kg to the weight given in General Specifications (see section 12.6, excluding the power cord)
Standard accessories*	With a power cord

\* Panel mounting brackets are not included.

# 24 VDC/AC Power Supply Operation (/P1)

Item	Specifications			
Rated supply voltage	24 VDC/AC			
Allowable power supply	voltage range			
	21.6 to 26.4 VDC/AC			
Withstand voltage	1000 VAC at 50/60 H	z for one minute (betwe	een the power terminal and	d the ground terminal)
Rated power supply freq	luency			
	50/60 Hz (for AC ope	ration)		
Allowable power supply	frequency range			
	50 Hz ± 2% or 60 Hz	± 2% (for AC operation	)	
Effects of power supply	voltage fluctuation			
	The fluctuation in the	measured values is with	thin ±1 digit and that in the	e recording is within $\pm 0.1\%$ in
	the recording span fo	r the 21.6 to 26.4 VAC/	DC range.	
Effects of power supply	frequency fluctuation			
	The fluctuation in the	measured values and	recording is ±(0.1% of rdg	+ 1 digit) at the rated
	frequency ±2 Hz.			
Rated power	25 VA (for DC) or 35	VA (for AC)		
Power consumption				
	Model	24 VDC	24 VAC	Maximum
	1 to 4 pen models	Approx. 7 VA*	Approx. 13 VA*	Approx. 35 VA
	6 dot model	Approx. 8 VA*	Approx. 13 VA*	Approx. 35 VA
	* When balanced			

# Calibration Correction (/CC1)

Item	Specifications
Number of calibration points	2 to 16 (can be specified for each channel)
Correction mode	Revise or absolute value (can be specified for each channel)
Correctable range	DC input (DC voltage, TC, and RTD) and linear scaling (DC voltage, TC, RTD, and 1-5V)
	(Not allowed on ON/OFF input (including linear scaling), delta computation, square root computation, and computation channels)
Correction range	<ul> <li>(1<sup>st</sup> correction point + 1<sup>st</sup> correction value) &lt; (2<sup>nd</sup> correction point + 2<sup>nd</sup> correction value) &lt;</li> <li>Corrected value (revise value: correction point + correction value, absolute value: correction value) within the measurable range and scaling range (-5% to 105% or -20000 to 30000) of each input range</li> <li>Setting limits Left span (0%) &lt; Right span (100%) Left scale (0%) &lt; Right scale (100%)</li> </ul>
Others	Calibration correction and bias functions cannot be used simultaneously (common to all channels)

# Header Printout (/BT1)

Item	Specifications		
Printout function	When recording starts or stops, prints out the batch name, comment, date/time, and chart speed.		
	Messages can also be printed out including measured values*.		
Printed items			
Recording start/recor	ding end printouts		
	Batch name: Batch number (up to 26 characters) and lot number (4 or 6 digit number, or Off)		
	Comment (up to 32 characters x 5 lines)		
	Chart speed		
	Date/time: Year, month, date, time, minute, second (date format depends on the date printout/		
	display format)		
	Printout On/Off selection: Batch name, chart speed, and date/time		
Message printouts	In the 5 message formats, measured values*, strings (up to 16 characters), and date/time can be		
	arbitrarily combined and printed out (up to 35 characters total).		

\* Computed values can also be included on models with the /M1 option.

# 12.6 General Specifications

# Construction

Item	Specifications
Mounting	Flush panel mounting (on a vertical plane)
Mounting angle	Inclined backward up to 30 degrees from a horizontal plane.
Allowable panel thickness	2 to 26 mm
Material	Case: drawn steel
	Front door: Aluminum die-cast
Color	Case: Charcoal gray light (Munsell 10B3.6/0.3 or equivalent)
	Front door: Charcoal gray light (Munsell 10B3.6/0.3 or equivalent)
Front panel	Water and dust-proof (complies with DIN40050-IP54)
Dimensions	144(W) × 144(H) × 220(D) mm (D: depth from the panel mounting plane)
Weight	1-pen: approx. 2.1 kg, 2-pen: approx. 2.2 kg, 3-pen: approx. 2.3 kg, 4-pen: approx. 2.4 kg
	6-dot: approx. 2.5 kg

# **Normal Operating Conditions**

Item	Specifications		
Ambient temperature	0 to 50°C		
Ambient humidity	20 to 80%RH (at 5 to 40°C)		
Allowable power supply vo	bltage range		
	90 to 132, 180 to 264 VAC		
Power supply frequency	50 Hz ±2%, 60 Hz ±2%		
Vibration	10 to 60 Hz 0.2 m/s <sup>2</sup> or less		
Shock	Not acceptable.		
Magnetic field	400 A/m or less (DC and 50/60 Hz)		
Noise	Normal mode (50/60 Hz)		
	Volt: The peak value including the signal must be less than 1.2 times the rated value of the range (Example: 2 V for 2 V range).		
	TC: The peak value including the signal must be less than 1.2 times the rated value of the range. RTD: 50 mV or less		
	Common mode noise (50/60 Hz): 250 VACrms or less for all ranges		
	Maximum noise voltage between channels (50/60 Hz): 250 VACrms or less. 6-dot model with the 3 legs isolated RTD (/N2 option) installed: 200 VACrms or less.		
Mounting position	Up to 30° of backward tilt angle allowed, no tilt to the left or right		
Warm-up time	At least 30 minutes after power on		
Altitude	2000 m or less above sea level		

# **Power Supply**

Item	Specifications			
Rated supply voltage	100 to 240 VAC			
Allowable power supply	voltage range			
	90 to 132, 180 to 264	VAC		
Rated power supply free	quency			
	50 Hz, 60 Hz			
Rated power	Pen model: 40 VA, do	ot model: 40 VA		
Power consumption	Model	100 VAC	240 VAC	Maximum
	1- to 4-pen model	Approx. 12 VA*	Approx. 17 VA*	Approx. 40 VA
	6-dot model	Approx. 13 VA*	Approx. 18 VA*	Approx. 40 VA
	* When balanced			

Item	Specifications
Insulation resistance	Each terminal to ground terminal: 20 M $\Omega$ or more (at 500 VDC)
Dielectric strength	Power supply to ground terminal: 1500 VAC (50/60 Hz), 1 minute
	Contact output terminal to ground terminal: 1500 VAC (50/60 Hz), 1 minute
	Measuring input terminal to ground terminal: 1000 VAC (50/60 Hz), 1 minute
	Between measuring input terminals: 1000 VAC (50/60 Hz), 1 minute (except for RTD input terminal
	Remote input terminal to ground terminal: 500 VDC, 1 minute
Grounding	Grounding resistance: 100 $\Omega$ or less

## **Transport and Storage Conditions**

Item	Specifications
Ambient temperature	–25 to 60°C
Ambient humidity	5 to 95%RH (no condensation)
Vibration	10 to 60 Hz, 4.9 m/s <sup>2</sup> maximum
Shock	392 m/s <sup>2</sup> maximum (in packaged condition)

## **Supported Standards**

Item	Specifications
CSA	Certified by CSA22.2 No. 61010-1 (certified by NRTL/C), installation category II <sup>1</sup> , measurement category II <sup>2</sup> , pollution degree 2 <sup>3</sup>
	* "US" (USA) and "C" (Canada) are indicated to the right and left of the CSA mark, respectively, to show that NRTL is included.
CE	
EMC	EN61326 (Emission: Class A, Immunity: Annex A)
	EN61000-3-2
	EN61000-3-3
	EN55011 compliance Class A Group 1
Low voltage directive	EN61010-1 compliance, Installation category II, Measurement category II, Pollution degree 2
C-Tick	AS/NZS CISPR 11 compliance Class A Group 1

1 Installation category (overvoltage category) describes a number which defines a transient overvoltage condition. It implies the regulation for impulse withstand voltage. "II" applies to electrical equipment which is supplied from the fixed installation like a distribution board.

2 Applies to measuring circuits connected to low voltage installation, and electrical instruments supplied with power from fixed equipment such as electric switchboards.

3 "Pollution degree" describes the degree to which a solid, liquid, or gas which deteriorates dielectric strength or surface resistivity is adhering. "2" applies to normal indoor atmosphere. Normally, only non-conductive pollution occurs.

### **Standard Performance**

allualu Pel	Tormanic				
m		ications			
asurement and re					
	The fo	llowing specifications apply to ope	eration of the r	ecorder under standard	operation conditions:
	Tempe	rature: $23 \pm 2^{\circ}C$			
	Humid	ity: 55% ± 10%R	Н		
	Power	supply voltage: 90 to 132 or 1	180 to 264 VA0	2	
	Power	supply frequency: 50/60 Hz ± 19	%		
	Warm-	up time: At least 30 m	inutes.		
	Other a	ambient conditions such as vibrat	ion should not	adversely affect the ope	eration
		Measurement (Digital D	isplay)	Recording	(Trend)
Input Type	Range Type	Measurement Accuracy	Highest Res.	Recording Accuracy	Resolution
	20 mV		10 µV	Measurement	Pen model:
	60 mV		10 µV	accuracy	Dead band 0.2%
	200 mV		100 µV	±(0.3% of recording	of recording span
DC voltage	2 V	$\pm(0.1\% \text{ of rdg} + 2 \text{ digits})$	1 mV	span)	Dot model:
Do voltage	6 V		1 mV		Resolution 0.1 mm
	20 V		10 mV		
	50 V	±(0.1% of rdg + 2 digits)	10 mV		
DC voltage	1-5 V	$\pm (0.1\% \text{ of rdg} + 2 \text{ digits})$ $\pm (0.1\% \text{ of rdg} + 2 \text{ digits})$	1 mV		
DC Voltage	1-5 V	$\pm (0.1\% \text{ of rdg} + 2 \text{ digits})$ $\pm (0.15\% \text{ of rdg} + 1)$	0.1°C		
	R S	except R,S: 0 to 100°C, ±3.7°C	0.10		
		-			
		100 to 300°C, ±1.5°C			
	В	B: 400 to 600°C, ±2°C			
		Accuracy not warranted for values less than 400°C			
		$\pm (0.15\% \text{ of rdg} + 0.7\% \text{C})$	-		
тс	к	, °			
		except ±(0.15% of rdg + 1°C) for –200 to –100°C			
(excludes	E	$\pm (0.15\% \text{ of } rdq + 0.5^{\circ}C)$	-		
RJC	J	except $\pm (0.15\% \text{ of rdg} + 0.5\%)$			
accuracy)	T	for J: -200 to -100°C			
	N	$\pm (0.15\% \text{ of rdg} + 0.7\% \text{C})$			
	W		-		
	VV	$\pm (0.15\% \text{ of } rdg + 1^{\circ}C)$	1		
	L	$\pm (0.15\% \text{ of rdg} + 0.5\%)$			
	U	except ±(0.15% of rdg + 0.7°C) for L: -200 to -100°C			
	WRe		1		
		±(0.2% of rdg + 1°C)	1		
RTD	Pt100 JPt100	±(0.15% of rdg + 0.3°C)			
	51 (100	Threshold level (2.4 V)	_	_	
		accuracy ± 0.1 V	-		
ON/OFF input	Level	≤ 1 kΩ: ON, ≥ 100 kΩ: OFF			
	Contact	(Parallel capacitance			
		0.01 µF or less)			
	l In an an a <b>f</b> line a	, ,	1		

Measuring accuracy in case of linear scaling

Accuracy during scaling (digits) = measuring accuracy (digits) × multiplier + 2 digits (rounded up) where the multiplier = scaling span (digits)/measuring span (digits).

Example: Assuming that

• range type:1-5 V

- measuring span:1.000 to 5.000 V
- scaling span:0.000 to 2.000 Then,  $= \pm (0.1\% \times 5 V + 2 \text{ digits})$

Measuring accuracy

 $= \pm (0.005 \text{ V} [5 \text{ digits}] + 2 \text{ digits})$ 

Multiplier = {2000 digits (0.000 to 2.000)}/4000 digits (1.000 to 5.000) = 0.5

Accuracy during scaling =  $\pm(7 \times 0.5 + 2)$  digits = 6 digits (rounded up)

Item	Specifications			
Measuring accuracy and re	ecording accuracy in case of squa	are root computation		
	A: Voltage measurement accura	acy (digits)		
	B: Voltage span (digits)			
	C: Scaling span (digits, upper lir	nit of scaling – lower limit of scaling)		
	Input Range	Computed Value Accuracy Equation (Digits),	), Recording Accuracy	
		Rounded up to the decimal place		
	0% or more, less than 1.5%*	0.1 × C + 2	Left value + 0.3% of	
	1.5% or more, less than 6.25%	A / B × C × 5 + 2	recording span	
	6.25% or more, less than 25%	A / B × C × 2 + 2		
	25% or more, 100% or less	A / B × C + 2		
	* Includes case when:			
	(input voltage – lower limit o	f the specified voltage range) / used range × 2	20000 < 256.	
	If the specified range is, for	example, 1–5 V, the lower limit of the specifie	d voltage range is 1.	
Reference junction compe	nsation			
	Internal/External selectable for e	each channel		
Reference junction compet	nsation accuracy			
	Above 0°C with input terminal te	emperature balanced (60 minutes after power	on)	
	Type R, S, B, W, WRe: ±1.0°	С		
	Type K, J, E, T, N, L, U: ±0.5°	С		
Maximum input voltage	±10 VDC (continuous) for ranges of 200 mV or less, TC, RTD, and DI ranges			
	±60 VDC (continuous) for 2 VDC	C or higher ranges		
Input resistance	Approximately 10 M $\Omega$ or more for ranges of 200 mV or less and TC			
	Approximately 1 M $\Omega$ for 2 VDC	or higher ranges		
Input source resistance	Volt, TC: 2 kΩ or less			
	RTD input: 10 Ω or less per win	e (The resistance of all three wires must be e	qual).	
Bias current	10 nA or less (except when burnout detection function is enabled)			
Common mode rejection ratio	120 dB (50/60 Hz ± 0.1%, 500 G	2 unbalanced, between the minus terminal an	d ground)	
Normal mode rejection ratio	40 dB or more (50/60 Hz ± 0.1%	b)		
Noise rejection	By the integrating A/D converter: The integration time is 16.7 ms, 20 ms, or 100 ms (dot model)			
-	Low-pass filtering (pen model):	Filter time constant is 2 s, 5 s, or 10 s	. ,	
	Moving average (dot model):	The number of samples is 2 to 16.		

ltem	Specifications
Ambient temperature	With temperature variation of 10°C:
	Measurement: ±(0.1% of rdg + 1 digit) or less
	Recording: Measurement fluctuation + ±0.2% of the recording span or less
	* Excluding the error of reference junction compensation
Power supply fluctuation	With variation within 90 to 132 V and 180 to 264 VAC (50/60 Hz):
	Measurement: ±1 digit or less
	Recording: ±0.1% of the recording span or less
	With variation of ±2 Hz from rated power frequency (power supply voltage 90 to 132, 180 to
	264 VAC):
	Measurement: ±(0.1% of rdg + 1 digit) or less
	Recording: Same as the measurement fluctuation
Magnetic field	AC (50/60 Hz) and DC 400 A/m fields:
	Measurement: ±(0.1% of rdg 10 digit) or less
	Recording: ±0.5% of the recording span or less
Input source resistance	
DC voltage range	With variation of +1 k $\Omega$ :
	Ranges of 200 mV or less: Within ±10 μV
	Ranges of 2V or more: ±0.1% of rdg
TC range	With variation of +1 k $\Omega$ : ±10 µV or less
RTD range	With variation of 10 $\Omega$ per wire (resistance of all three wires must be equal):
	Measurement: ±(0.1% of rdg + 1 digit) or less
	Recording: Measurement fluctuation + ±0.1% of the recording span or less
	With maximum difference of 40 m $\Omega$ between wires: Approx. 0.1°C (for Pt100)
Mounting position	With a backward tilt of 30° or less
	Measurement: ±(0.1% of rdg + 1 digit) or less
	Recording: Indication fluctuation + ±0.1% of the recording span or less
Vibration	When a sinusoidal vibration along all three axis at a frequency between 10 to 60 Hz and an
	acceleration of 0.2 m/s <sup>2</sup> is applied for 2 hours
	Measurement: ±(0.1% of rdg + 1 digit) or less
	Recording: Indication fluctuation + ±0.1% of the recording span or less


# Effects of Operating Conditions

# **Other Specifications**


Item	Specifications
Clock	With a calendar function
Accuracy of clock	±100 ppm, excluding a delay (of 1 second, maximum) caused each time the power is turned on.
DST	The date/time for switching between standard time and DST can be specified.
Memory backup	A built-in lithium battery backs up the setup parameters and runs the clock
	(battery life: approximately ten years at room temperature).
Key lock function	Password for releasing the key lock can be set.
Key lock items	RCD key, MENU key, DISP MENU key, FEED key, and function under the FUNC key (Alarm ACK
	computation start/stop, print, message, printout buffer clear, periodic printout reset, and pen or
	ribbon cassette exchange)
Internal light	Lights up the recording area of the chart paper. Uses a dedicated LED.
Noise	Machine Noise Information Ordinance 3.GSGV, Jan 18, 1991
	Maximum noise level: 60 dB (A) or less (complies with ISO7779)


# 12.7 Dimensional Drawings

# Panel Mount Type



When mounting the recorder to a panel, use two brackets, top and bottom or left and right.






# Appendix 1 Periodic Printout and Printout Using the TLOG Timer (/M1 Option)

## **Periodic Printout**

This section explains the contents of the periodic printout. The periodic printout contents vary between the pen model and dot model. The contents also vary depending on whether the periodic printout is in instantaneous mode, report mode, or Off. Instantaneous mode or report mode is specified using **Print1 > Mode** in Basic Setting

The figure below illustrates the printout contents. The font used in the figure differs from that of the actual printout. The printout positions may also differ from those of the actual printout.



#### Pen Model

mode.

#### Date/Time

The date/time when the periodic printout was printed on the chart paper.

#### • Time tick

Indicates the reference pen position at the time the periodic printout was printed on the chart paper.

#### • Time tick cancel mark

Prints an exclamation point (!) when the time tick is not printed correctly.

- Offset compensation mark
- Prints an asterisk (\*) when offset compensation is enabled.

#### Channel data

Prints the channel numbers (1 to 4 or A to J) or tags, measured/computed values, and unit.

Prints the letter "d" on channels set to delta computation.

Alarm

Prints the alarm that is occurring. If multiple alarms are occurring, the alarm with the highest precedence is printed.

Alarm printout precedence: (Higher) H, L, T, t, h, I, R, r (Lower)


#### Scale

Prints the leftmost and rightmost values of the recording span and the channel number or tag for channels that have scale printout specified. The scale is printed for one channel at each periodic printout. The channel whose scale is printed changes in ascending order. The scale of channels that are being zone recorded is printed within the recording range of the zone.

#### Recording color

Prints the recording colors of channels that have scale printout and recording color printout specified.

• Chart speed Prints the chart speed.



#### • Report start date/time and report end date/time

The start date/time and end date time of the report (statistical calculation) (periodic printout interval).

- **Time tick and time tick cancel mark** These are the same as with the instantaneous mode.
- Offset compensation mark


This is the same as with the instantaneous mode.

- Event
  - Prints the events that occurred in the interval.
  - T: Time change
  - P: Power failure or power OFF/ON
  - R: Data reset

#### Channel data

Prints the channel numbers (1 to 6 or A to J) or tags, report data, and unit. An asterisk (\*) is printed for channels whose range type was changed in the interval.

• Scale, recording color, and chart speed These are the same as with the instantaneous mode.



Date/Time

The date/time when the periodic printout was executed.


## Time tick

Indicates the position at the time the periodic printout was executed. If the time tick cannot be printed correctly, it is not printed.

• Channel data, alarm, scale printout, and chart speed

These are the same as with the instantaneous mode of the pen model.





#### Report start date/time and report end date/time The start date/time and end date time of the report (statistical calculated)

The start date/time and end date time of the report (statistical calculation) (periodic printout interval).

Time tick

This is the same as with the instantaneous mode.

Event

This is the same as with the report mode of the pen model.

# • **Channel data** This is the same as with the report mode of the pen model. However, the channel numbers are 1 to 6 or A to P.


Scale and chart speed

These are the same as with the instantaneous mode of the pen model.

Appendix

### Printout Using the TLOG Timer (/M1 Option)

Prints the computed values of computation channels for each interval determined by the TLOG timer.



#### Date/Time

The date/time when the printout using the TLOG timer was executed.

• Offset compensation mark, scale, and recording color These are the same as with the periodic printout of the pen model.

- Event
  - This is the same as with the report mode of the periodic printout of the pen model.
- Channel data

Prints the computation channel numbers (A to J) or tags, computed values, and unit.


Alarm

This is the same as with the instantaneous mode of the periodic printout of the pen model.

Timer

Prints the timer number being used.

### **Dot Model**



#### • Date/Time

The date/time when the printout using the TLOG timer was executed.

• Event

This is the same as with the report mode of the periodic printout of the pen model.

Channel data

Prints the computation channel numbers (A to P) or tags, computed values, and unit.

• Alarm

This is the same as with the instantaneous mode of the periodic printout of the pen model.

Scale

These are the same as with the periodic printout of the pen model.

• Timer

Prints the timer number being used.

### **Special Cases**

This section explains the operation of the periodic printout report (statistical calculation) and the TLOG computation for special cases. In the explanation below, statistical calculation represents computation in periodic printout report mode or TLOG computation.

#### **Operation during Power Failures**

If a power failure occurs in the middle of statistical calculation, the operation is as follows when the power recovers.

The statistical calculation resumes when the power recovers. The exact operation will vary depending on whether the power is restored before or after the printout time.

Time of Recovery	Туре	Statistical Calculation Operation
After the printout time	TLOG computation	Statistical calculation data is printed immediately after power is restored. The measured/computed data up to the time of the power failure is used. At the next printout time, data after the power recovery is used to create and print the statistical calculation data.
	Periodic printout	Periodic printout is not performed immediately after power is restored. It is printed on the first printout time after recovery. The data used is measured/computed data from before and up to the power failure, and from the time of recovery up to the printout time. The "report start date/time" in this case is the periodic printout date/time closest to and prior to the power failure. The "report end date/time" is the current periodic printout date/time.
Before the printout time	TLOG computation	The data is printed at the printout time after the power recovers. The measured/computed data excluding the
	Periodic printout	power failure period is used.

### Procedure of Handling "Over" Values during Periodic Printout

When an "over" value<sup>\*</sup> is input for sum or average computation, that value is not used in the computation.


- \* An "over" value on a measurement channel refers to +Over or –Over. See section 12.4. An "over" value on a computation channel refers to a value that is less than or equal to
  - $-100000000\ \mbox{or greater}$  than or equal to  $10000000\ \mbox{excluding}$  the decimal.

# Appendix 2 Periodic Printout Interval

The periodic printout function prints measured values and other data numerically at the left side of the chart paper while performing trend recording.

The periodic printout interval varies depending on the chart speed and setup conditions.





The figure above is used to explain the printout contents. The actual printout and font are different from those illustrated in the figure. The printout positions are also slightly different.

#### When the Interval Is Set to Auto

Printout is performed at the interval corresponding to the chart speed.

Pen M	/lodel	Dot Model	
Chart Speed	Periodic Printout Interval	Chart Speed	Periodic Printout Interval
Up to 9 mm/h	Not printed	Up to 9 mm/h	Not printed
10 to 18 mm/h	8 hours	10 to 19 mm/h	8 hours
20 to 36 mm/h	4 hours	20 to 39 mm/h	4 hours
40 to 72 mm/h	2 hours	40 to 79 mm/h	2 hours
75 to 135 mm/h	1 hour	80 to 100 mm/h	1 hour
150 to 180 mm/h	30 minutes	101 mm/h or higher	Not printed
200 to 320 mm/h	20 minutes		
360 to 1500 mm/h	10 minutes		
1600 mm/h or higher	Not printed		

#### When the Interval Is Set to Manual

If you select Manual, you can set the interval.

#### Chart Speeds That Allows Periodic Printout

Pen Model		Dot Model	
Chart Speed	Printout Availability	Chart Speed	Printout Availability
Up to 9 mm/h	No	Up to 9 mm/h	No
10 to 1500 mm/h	Yes	10 to 100 mm/h	Yes
1600 mm/h or higher	No	101 mm/h or higher	No

#### Interval Settings •

Select from 10, 12, 15, 20, 30 minutes, 1, 2, 3, 4, 6, 8, 12, and 24 hours.


#### Printout Items

Item	Number of Lines	Initial Setting	Notes (Ref. Section)
Date/Time	2	-	Always printed.
Measured value and alarm status	1 line/channel	Printed	Print or not print selectable for each channel (section 6.6).
Scale	2	Printed	Print or not print selectable (section 7.7).
Pen color (Pen model only)	1	Printed	Print or not print selectable (section 7.7).
Chart speed	1	-	Always printed.

#### **Relationship between the Printout Items and Interval**

The next periodic printout does not start until all items of the previous periodic printout are printed.

If all items cannot be printed in the specified interval, the printout interval increases by an integer multiple of the specified interval.



Example: Dot model, chart speed: 20 mm/h, interval: 30 minutes, all other settings at default.

- · This setting requires 11 lines to be printed which is equivalent to approximately 28 mm\* of chart paper.
- The length of chart paper that is fed within the interval is 10 mm.
- The length of chart paper needed in the printout varies depending on the chart speed and dot printing interval.

Not all items can be printed in the specified interval of 30 minutes. The actual interval is 1 hour and 30 minutes.

If you want to print at a shorter interval, change the settings as follows:

- Reduce the number of printed items.
- Increase the chart speed within the printable range.

#### Note

Measurement, display, periodic printout, and trend recording (dot model) are not performed by setting unused channels to Skip (see section 5.1).

# Symbols

Symbols	
+Over	
–Over	

## Numeric

1-5V	
1-5V input	
1-5V low-cut function	7-24

### Α

absolute time mode	
absolute value	
absolute values, setting using	6-14
accuracy of clock	
activating the key lock	
adjusting the dot printing position	11-8
adjusting the hysteresis	11-8
adjusting the pen position	11-6
alarm	
alarm ACK	1-12, 3-18
alarm acknowledge operation	1-12, 3-18
alarm delay function	7-24
alarm hysteresis	1-8, 1-28, 7-3
alarm indication	
alarm information	
alarm output relay	
alarm output relays	
alarm output terminals	
alarm printout	
alarms on the delta computation channel	5-10
alarm type	5-10, 9-12, 12-3
alarm value	5-11, 9-12
AND/OR	•
AND operation (alarm output relay)	1-11
assigned function (remote control)	
assigning channels to recording pens	

## В

bar graph	
base point of the bar graph	
basic setting mode	
batch action, setting of	
batch comments	6-16
batch name	
batch number	1-22, 6-15
batch printout, turning ON/OFF of	6-16
bias	1-4, 6-12
bias function	
brightness (display)	6-11
brightness (internal light)	6-11
buffer memory	
buffer overflow mark	1-18, 1-19
burnout detection	

## С

calibration	11-4
calibration correction	1-4
calibration correction, performing of	6-13
calibration correction function	
calibration instrument	11-4
cassette holder	3-10

changing the settings	
channel auto switching	
channel printout	
channel range	,
channel switching interval	
character type	
chart cassette	
chart end output	1-29
chart holder	
chart paper	3-5, 12-4
chart paper guide	
chart speed	1-14, 5-13
cleaning	
clearing alarm information	3-15
comment line	
common logarithm	1-26
communication input data	
compensation voltage	7-7
computation-dedicated channels	1-26
computation errors	
computing equation	
computing equations	
constants	9-4, 9-10
construction	
conventions used in this manual	xi
copying & pasting a character string	4-4, 9-3
correction values	
current input	
cursor	
customized menu	1-32

### D

data display setup screen	
data types (computation)	1-26, 9-4
date/time	
date format	
DC voltage	
de-energized	
default values (basic setting mode)	4-11
default values (setting mode)	
delay high limit alarm	
delay low limit alarm	
deleting a character	4-4, 9-3
deleting an entire character string	4-4, 9-3
delta computation	
diagnosis output	
difference high limit alarm	
difference low limit alarm	1-7
dimensional drawings	12-23
display	
display/recording language	
display and key panel	
displayed contents	12-7
display examples	
display in which different screens can be assigned.	
display type	
display update rate	
dot printing interval	1-14, 6-1
DST	
duration (alarm delay)	

# E

E	
edge	
effects of operating conditions	12-22
EMC standards	iii
end printout	1-22, 6-15
end printout 2	6-15
energized	1-11,7-3
English, setting the language	
entering basic setting mode	
entering characters	
entering setting mode	
entering values	
error messages	
ESC key	
exponent	
external reference compensation	

# <u>F</u>

FAIL/chart end output relay	
FAIL output	
fastest recording interval	
feeding the chart paper	
felt pen	
filter	1-5, 6-2, 7-20
format of the date	
four arithmetic operation	
front cover tab of the chart cassette	3-11
FUNC key operation	

# H

half life of the brightness	11-10
handling precautions	
header printout	
heat sink	
high limit alarm	
high limit on rate-of-change alarm	
hold	
hold operation	
hysteresis	

# L

initializing the recorder settings	7-27
input computation	12-2
input range	
input type	12-1
inserting a character	
inserting characters	
installation location	
instantaneous mode	App-1
integration time of the A/D converter	
internal clock adjustment	
internal light LED assembly	
interval (periodic printout)	Арр-6
interval (rate-of-change alarm)	
isolation	

# K

	7-18
keys	3-2
keys to be key-locked	. 7-18

# L

language	
level	
linear scaling	
List	
loading the chart paper	
logical computation	
lot number	
lot number, setting of	6-15
low-cut	
low limit alarm	
low limit on rate-of-change alarm	

## Μ

main display	
manual printout	
measurable range	1-2
measuring input terminal	
memory backup	12-22
menu (basic setting mode)	
menu (data display setup)	8-2
menu (setting mode)	
menu, customization of	
message	6-8
message format	
message printout	1-19
message printout including measured value	1-23
message printout including measured value in	6-19
model	vi
mounting brackets	2-3
mounting hole	
moving average	

## Ν

names of parts	3-1
new chart speed printout	
non-hold	
non-hold operation	7-3
normal operating conditions	12-18
number of samples of moving average	6-3

# <u>0</u>

offset compensation mark	App-1
ON/OFF input	
opening the display	ix
operation menus using the FUNC key	
operation mode	
operations on the panel keys	
optional accessories	viii
optional functions	12-13
optional terminal	
order of precedence of computation	
over value	9-29
over values during periodic printout	App-5

## Ρ

packing materials	ix
panel	
panel cut dimensions	
parallel connection	
partial expanded recording	1-15, 6-5, 7-21, 9-16
password (key lock)	
password for releasing the key lock	7-18
pen caps	
pen holder	

pen offset compensating data, ejection of	
pen offset compensation	
periodic inspection	11-1
periodic printout	1-18, 9-17, App-1
periodic printout, disabling of	
periodic printout interval	
plotter pen	
POC	
portable type	
power (computation)	
power and other computations	
power failure	
power supply	
power switch	
precautions (input signal wiring)	
precautions (optional terminal wiring)	
precautions (power supply wiring)	
printing a message	
printing the computed value	
printing the recorder settings	
printout contents	
printouts	
printout using the TLOG timer	App-4
protective ground terminal	

# R

range type	
rear panel	
recorder	
recorder's version	
recording	
recording (computation channels)	
recording color 1-14, 7-8,	7-11, 9-23
recording span	
recording start printout	
recording zone	6-4, 9-15
reference junction compensation	1-4
reference pen	1-15
reference time	
reflash alarm	1-10, 7-3
registering display types to screens	8-3
relational computation	
relative time mode	
relay contact input	
relay contact output	
relay numbers	
releasing the alarm output	
releasing the key lock	
remaining chart length	11-1
remote control	. 1-30, 7-28
remote control input	
remote control input terminals	2-9
remote signal	
replacement period for expendable parts	11-10
replacing felt pens	
replacing the internal light LED	
replacing the plotter pen	3-8
report data	
report mode	
resetting the computed values	
resetting the report data	
resetting the TLOG computed value	
revise values, setting using	
revisions	
ribbon cassette	
ribbon feeding knob	
ribbon is loose	

### S

<u>S</u>	
safety precautions	iii
safety standards	iii
safety symbols	iii
scale printout	App-2
scaling	1-3
scan interval	
secondary chart speed	6-9
Setting complete screen	
setting mode	
settings necessary to use various functions	1-34
Setup	
setup guide	1-34
setup items (basic setting mode)	4-11
setup Items (setting mode)	
shunt resistor	1-2
skip	5-8
sprocket teeth	
square root	
square root computation	
square root low-cut function	
standard accessories	
standard performance	
standard temperature device	
starting the computation	
start printout	
start printout 2	
start recording	
status display	
status of the remote control input terminal	
stoppers	
stopping the computation	
stop recording	
suffix code	
SUM scale7-14,	
supported standards	
switching the display screen	3-12

## Т

<u> </u>	
tag	
ТС	
temperature unit	
thermocouple	
thermocouple input	
time constant	
time printout format	
timer	
time tick	1-16, App-1
time tick cancel mark	1-16, App-1
TLOG computation	
transistor input	
trend recording	
trend recording interval	
trigger	
troubleshooting	
type of measured values	
type of report data	
types of computations	
types of inputs	

U	
unit	
unit in computations	

# V

<u>v</u>	
versions and functions	ii
VFD	
Volt	

# W

<u> </u>	
wiring (measuring input )	
wiring (optional terminal)	
wiring (power supply)	2-11

## Z

<u>L</u>	
zone recording1-	14