

DIN-rail mounting temperature controller with current transformer input D1 line

Quick Guide • 17/11 • ISTR_Q_D1_1_03_--



**ASCON
TECNOLIGIC**

viale Indipendenza 56, 27029 - Vigevano (PV)
Tel.: +39 0381 698 71; Fax: +39 0381 698 730
internet site: www.ascontecnologic.com
E-mail: sales@ascontecnologic.com

Configuration and setting Software

The instrument must be configured using **Controller Explorer** (a proprietary free software). The most recent release of Controller Explorer is downloadable from our web site:

www.ascontecnologic.com

Once connected to this site, click on the banner: **Download**, then click on the row: **Controller Explorer**.

Download the most recent version of the software and, when present, any upgrade to the program.

Once installed the Software and the upgrades, run the program, the default communications parameters are:

Transmission speed: 9600 bps;

Protocol: ModBus;

Serial address: 247.

⚠ Warning!

When more controllers/instruments are to be installed, keep in mind that the default serial address **always** is 247.

For this reason, always connect/power on only **1 not configured instrument** a time, in order to **avoid the presence**, on the same network, of **2 instruments with the same address**. During the configuration, assign to each instrument a different serial address.

The "gammadue® and deltadue® controller series Serial communications and configuration software" manual can be downloaded from the web site:

www.ascontecnologic.com

As for the other manuals, also this one is present in the lower part of the product page.

Declaration of conformity and manual retrieval

D1 is a rear panel mounting, Class II instrument, it has been designed with compliance to the European Directives. All information about the controller can be found in the Installation or in the User Manual: **ISTR_I_D1_E_03_--.pdf** and **ISTR_U_D1_E_04_--.pdf**. The Manuals and the Declaration of Conformity of the instrument can be downloaded (free of charge) from the web-site:

www.ascontecnologic.com

Once connected to the web-site, search:

D1; then click on **D1** on the search result list.

In the lower part of the product page (in any language) is present the download area with the links to the documents available for the requested instrument (in the available languages).

⚠ Warning!

- Whenever a failure or a malfunction of the device may cause dangerous situations for persons, things or animals, please remember that the plant must be equipped with additional devices which will guarantee safety.


- We warrant that the products will be free from defects in material and workmanship for 18 months from the date of delivery. Products and components that are subject to wear due to conditions of use, service life and misuse are not covered by this warranty.

Disposal


The appliance (or the product) must be disposed of separately in compliance with the local standards in force on waste disposal.

Mounting several instruments

1 Mounted the instruments on the rail, put them side by side so that the male side connector fits into the corresponding female connector;




2 Then, insert the female 5-pole connector with the termination resistor of the serial communications into the corresponding male connector;



3 Wire the 5-pole male power supply and serial communications connector and insert it in the corresponding female connector;


4 When assembled insert the connector protection on both sides.

Dimensions



Terminal connectors

4 terminal connectors




Termination plug


C Power supply/comm.s connector

D

Power supply voltage: 24Vac (-25...+12%) or 24Vdc (-15...+25%)




Connections




Terminals

Features	A - B - C - D	Bus/Power Supply
Stripped wire	L = 7 mm - 0.28 in.	L = 7 mm - 0.28 in.
Flat blade screwdriver	0.6 x 3.5 mm	0.4 x 2.5 mm
Tightening torque	0.5...0.6 Nm	0.4...0.5 Nm

DIN rail mounting




1 Clip the upper part of the instrument on the rail;




2 Rotate the instrument downwards until the click;

Removing the instrument from the DIN rail

Switch the instrument off



1 Lower the spring slide by inserting a flat-blade screwdriver as indicated;




2 Turn and lift the instrument upwards.

Serial communications connection examples


Configuration



Acquisition and centralized supervision



Local control



Model code

The product code indicates the specific hardware configuration of the instrument, that can be modified by specialized engineers only.

Line Basic Accessories Configuration
Model: **D 1 5 B 5 D - E 9 0 0 / I L M N - O P Q R**

Line	D 1	L
Output OP1 - OP2	B	
Relay - Not fitted	0	
Relay - Relay	1	
SSR - Not fitted	3	
SSR - SSR	5	
Options	D	
None	0	
Current transformer (CT)	3	
Special function	E	
Not fitted	0	
Start-up + Timer	2	

Configuration code

A 4 + 4 digits index code follows the model (letters from I... R).

This code can be used to buy a pre-configured controller.

Input type and range	I	L
TR Pt100 IEC751	-99.9...300.0°C	-99.9...572.0°F
TR Pt100 IEC751	-200...600°C	-328...1112°F
TC L Fe-Const DIN43710	0...600°C	32...1112°F
TCU Fe-Cu45% Ni IEC584	0...600°C	32...1112°F
TC T Cu-CuNi	-200...400°C	-328...752°F
TC K Chromel-Alumel IEC584	0...1200°C	32...2192°F
TC S Pt10%Rh-Pt IEC584	0...1600°C	32...2912°F
TC R Pt13%Rh-Pt IEC584	0...1600°C	32...2912°F
TC B Pt30%Rh Pt6%Rh IEC584	0...1800°C	32...3272°F
TC N Nichrosil-NiSil IEC584	0...1200°C	32...2192°F
TC E Ni10%Cr-CuNi IEC584	0...600°C	32...1112°F
TC NI-NiMo18%	0...1100°C	32...2012°F
TC W3%Re-W25%Re	0...2000°C	32...3632°F
TC W5%Re-W26%Re	0...2000°C	32...3632°F
Dc input 0...50mV linear	Engineering units	1 4
Dc input 10...50mV linear	Engineering units	1 5
Custom input range [1]		1 6

Control mode

M
ON-OFF reverse action
ON-OFF direct action
PID single reverse action
PID single direct action
Linear cool output
ON-OFF cool output
Water cool output
Oil cool output
Single Action
Double action
N
Relays (OP1)
Heat OP1, Cool OP2
Heat OP1, Cool OP4
Heat OP4, Cool OP2

Output configuration

AL.	O	P	Q
0	0	0	0
1	1	1	1
2	2	2	2
3	3	3	3
4	4	4	4
5	5	5	5
6	6	6	6
7	7	7	7

Tipo e modo di intervento allarmi

AL.	1	2	3
Disabled or used by Timer (only for Al3)	0	0	0
Sensor break/Loop Break Alarm (LBA)	1	1	1
Absolute	active high	2	2
	active low	3	3
Deviation	active high	4	4
	active low	5	5
Band	active out	6	6
	active in	7	

Regolatore di temperatura per guida DIN con ingresso da trasformatore amperometrico linea D1



Quick Guide • 17/11 • ISTR_Q_D1_1_03_--



**ASCON
TECNOLIGIC**

viale Indipendenza 56, 27029 - Vigevano (PV)
Tel.: +39 0381 698 71, Fax: +39 0381 698 730
internet site: www.ascontecnologic.com
E-mail: sales@ascontecnologic.com

Software di configurazione e impostazione

Lo strumento deve essere configurato mediante il software **Controller Explorer** (programma proprietario gratuito).

La versione più recente del programma Controller Explorer può essere scaricata dal sito internet:

www.ascontecnologic.com

Collegato il sito internet indicato selezionare: **Download** poi cliccare sulla riga: **Controller Explorer**.

Effettuare il download della versione più recente del programma più gli eventuali aggiornamenti.

Una volta installato il software e gli aggiornamenti, lanciare il programma, i parametri di comunicazione di default sono:

Velocità di trasmissione: **9600 bps**;

Protocollo: **ModBus**;

Indirizzo seriale: **247**.

Attenzione!

Quando si devono installare più strumenti, porre attenzione al fatto che l'indirizzo seriale di default è **sempre = 247**.

Per questa ragione, alimentare o collegare sempre **1 strumento per volta** in modo da **non avere attivi** sulla stessa rete **2 strumenti con lo stesso indirizzo seriale**.

Assegnare indirizzi diversi ad ogni strumento.

Il manuale "Configurazione e comunicazione seriale gammadue® e deltadue®" può essere scaricato dal sito:

www.ascontecnologic.com

Come per gli altri manuali, anche quello indicato è presente nella parte bassa della pagina specifica del prodotto.

Codice modello

La sigla del modello identifica le caratteristiche hardware del regolatore modificabili solo da personale qualificato.

Linea	Base	Accessori	Configurazione
Modello:	D 1	5 B 5 D - E 9 0 0 / I L M N - O P Q R	1ª parte 2ª parte

Linea	D 1
Uscite OP1 - OP2	B
Relè - Non presente	0
Relè - Relè	1
SSR - Non presente	3
SSR - SSR	5
Opzioni	D
Nessuna	0
Trasformatore amperometrico	3
Funzioni speciali	E
Non previste	0
Start-up + Timer	2

Codice di configurazione

Un codice di 4 + 4 digit segue il codice modello (lettere I...R). Il codice di configurazione serve per ordinare lo strumento preconfigurato.

Tipo di ingresso e campo scala	I	L
TR Pt100 IEC751	-99.9...300.0°C	-99.9...572.0°F
TR Pt100 IEC751	-200...600°C	-328...1112°F
TC L Fe-Const DIN43710	0...600°C	32...1112°F
TCU Fe-Cu45% Ni IEC584	0...600°C	32...1112°F
TC T Cu-CuNi	-200...400°C	-328...752°F
TC K Chromel-Alumel IEC584	0...1200°C	32...2192°F
TC S Pt10%Rh-Pt IEC584	0...1600°C	32...2912°F
TC R Pt13%Rh-Pt IEC584	0...1600°C	32...2912°F
TC B Pt30%Rh Pt6%Rh IEC584	0...1800°C	32...3272°F
TC N Nichrosil-Nisil IEC584	0...1200°C	32...2192°F
TC E Ni90%Cr-CuNi IEC584	0...600°C	32...1112°F
TC NI-NiMo18%	0...1100°C	32...2012°F
TC W3%Re-W25%Re	0...2000°C	32...3632°F
TC W5%Re-W26%Re	0...2000°C	32...3632°F
Ingresso lineare 0...50mV	In unità ingegneristiche	1 4
Ingresso lineare 10...50mV	In unità ingegneristiche	1 5
Ingresso e scala "custom" [1]		1 6

Dichiarazione di conformità e manuale istruzioni

Il D1 è uno strumento per montaggio retroquadro di Classe II progettato per essere conforme alle Direttive europee.

Tutti i dettagli circa l'installazione e l'utilizzo dello strumento sono inseriti nel manuale di installazione e nel manuale d'uso:

ISTR_I_D1_I_03_--.pdf e **ISTR_U_D1_I_04_--.pdf**.

I Manuali e la Dichiarazione di Conformità dello strumento possono essere scaricati gratuitamente dal sito web:

www.ascontecnologic.com

Una volta collegato il sito internet indicato, cercare:

[D1]

poi selezionare D1 nell'elenco dei risultati.

Nella parte bassa della pagina dei prodotti (di qualsiasi lingua) è presente l'area download con i collegamenti ai documenti relativi al prodotto (nelle lingue disponibili).

Attenzione!

- Qualora un guasto o un malfunzionamento dell'apparecchio possa creare situazioni pericolose e/o dannose per persone, cose o animali si ricorda che l'impianto deve essere predisposto con dispositivi elettromeccanici aggiuntivi atti a garantire la sicurezza.

- I prodotti sono coperti da una garanzia di 18 mesi dalla data di spedizione. Dalla garanzia sono esclusi i prodotti e i componenti soggetti ad usura per condizioni di utilizzo, vita utile e uso improprio.

Smaltimento


L'apparecchiatura (o il prodotto) deve essere oggetto di raccolta separata in conformità alle vigenti normative locali in materia di smaltimento.

Installazioni multiple

1 Dopo aver montato gli strumenti sulla guida, affiancarli in modo che il connettore trasversale si inserisca nel connettore corrispondente;


2 Dopo aver affiancato tutti gli strumenti inserire la spina femmina a 5 poli con resistenza di terminazione della linea seriale nel corrispondente maschio;

3 Cablare il connettore di alimentazione sulla spina maschio a 5 poli ed inserirla nella corrispondente femmina;




4 A montaggio ultimato inserire le protezioni connettori su ambo i lati.

Dimensioni




Morsettierie



Tensione di alimentazione:
24Vac (-25...+12%) o
24Vdc (-15...+25%)


Collegamenti




Morsetti

Caratteristica	A - B - C - D	Bus/Alimentazione
Filo spelato	L = 7 mm - 0.28 in.	L = 7 mm - 0.28 in.
Cacciavite a taglio	0.6 x 3.5 mm	0.4 x 2.5 mm
Coppia di serraggio	0.5... 0.6 Nm	0.4... 0.5 Nm

Montaggio su guida DIN




1 Aggiornare la parte superiore dello strumento sulla guida;



2 Ruotare lo strumento verso l'alto.

Rimozione dalla guida DIN

Togliere tensione allo strumento



1 Abbassare la slitta a molla inserendo un cacciavite a lama piatta come indicato;



2 Ruotare lo strumento verso l'alto.


Esempi di collegamento seriale

Configurazione




CD-ROM con tool di configurazione

Acquisizione e comando centralizzato



Controllo locale



Pannello operatore

Elenco dei parametri

Nella tabella che segue sono elencati i parametri del regolatore con il relativo indirizzo seriale ModBus.

Per ulteriori informazioni si consulti il manuale: "Configurazione e comunicazione seriale gammadue® e deltadue®".

Analogici

Indirizzo ModBus	Nome parametro	Valore		
		Default	Modbus	Utente
0	Misura PV			
1	Setpoint di lavoro SP			
2	Uscita principale OP			
3	Setpoint di target SPT			
4	Setpoint locale SPL			
5	Banda proporzionale (PID) o isteresi (ON - OFF)	5.0/0.5	50/5	
6	Controllo Overshoot	1.00	100	
7	Tempo integrale	5.0	50	
8	Tempo derivativo			